

Stan dotychczasowy - Identyfikator budynku	Stan nowy - Identyfikator budynku
100401_1.0001.3.1_BUD	100401_1.0001.1_BUD
100401_1.0001.3.2_BUD	100401_1.0001.2_BUD
100401_1.0001.3.3_BUD	100401_1.0001.3_BUD
100401_1.0001.3.4_BUD	100401_1.0001.4_BUD
100401_1.0001.3.5_BUD	100401_1.0001.5_BUD
100401_1.0001.5.1_BUD	100401_1.0001.6_BUD
100401_1.0001.5.2_BUD	100401_1.0001.7_BUD
100401_1.0001.5.3_BUD	100401_1.0001.8_BUD
100401_1.0001.5.4_BUD	100401_1.0001.9_BUD
100401_1.0001.6/3.1_BUD	100401_1.0001.10_BUD
100401_1.0001.6/4.1_BUD	100401_1.0001.11_BUD
100401_1.0001.6/4.2_BUD	100401_1.0001.12_BUD
100401_1.0001.6/5.1_BUD	100401_1.0001.13_BUD
100401_1.0001.8/3.1_BUD	100401_1.0001.14_BUD
100401_1.0001.9.1_BUD	100401_1.0001.15_BUD
100401_1.0001.10/2.4_BUD	100401_1.0001.16_BUD
100401_1.0001.10/2.5_BUD	100401_1.0001.17_BUD
100401_1.0001.13/2.1_BUD	100401_1.0001.18_BUD
100401_1.0001.13/2.2_BUD	100401_1.0001.19_BUD
100401_1.0001.13/2.3_BUD	100401_1.0001.20_BUD
100401_1.0001.13/2.4_BUD	100401_1.0001.21_BUD
100401_1.0001.13/2.5_BUD	100401_1.0001.22_BUD
100401_1.0001.13/2.6_BUD	100401_1.0001.23_BUD
100401_1.0001.13/3.1_BUD	100401_1.0001.24_BUD
100401_1.0001.16/2.1_BUD	100401_1.0001.25_BUD
100401_1.0001.16/3.1_BUD	100401_1.0001.26_BUD
100401_1.0001.19/5.1_BUD	100401_1.0001.27_BUD
100401_1.0001.20/4.1_BUD	100401_1.0001.28_BUD
100401_1.0001.21/5.1_BUD	100401_1.0001.29_BUD
100401_1.0001.21/14.1_BUD	100401_1.0001.30_BUD
100401_1.0001.21/17.1_BUD	100401_1.0001.31_BUD
100401_1.0001.21/22.1_BUD	100401_1.0001.32_BUD
100401_1.0001.22/1.5_BUD	100401_1.0001.33_BUD
100401_1.0001.23/5.1_BUD	100401_1.0001.34_BUD
100401_1.0001.23/5.2_BUD	100401_1.0001.35_BUD
100401_1.0001.23/5.3_BUD	100401_1.0001.36_BUD
100401_1.0001.23/5.4_BUD	100401_1.0001.37_BUD
100401_1.0001.23/6.1_BUD	100401_1.0001.38_BUD
100401_1.0001.23/6.2_BUD	100401_1.0001.39_BUD
100401_1.0001.23/6.3_BUD	100401_1.0001.40_BUD
100401_1.0001.23/8.1_BUD	100401_1.0001.41_BUD
100401_1.0001.23/22.1_BUD	100401_1.0001.42_BUD
100401_1.0001.23/27.1_BUD	100401_1.0001.43_BUD
100401_1.0001.23/27.2_BUD	100401_1.0001.44_BUD
100401_1.0001.24.4_BUD	100401_1.0001.45_BUD
100401_1.0001.31/3.3_BUD	100401_1.0001.46_BUD
100401_1.0001.31/4.1_BUD	100401_1.0001.47_BUD
100401_1.0001.31/8.1_BUD	100401_1.0001.48_BUD
100401_1.0001.31/12.1_BUD	100401_1.0001.49_BUD
100401_1.0001.31/18.1_BUD	100401_1.0001.50_BUD
100401_1.0001.32/4.1_BUD	100401_1.0001.51_BUD
100401_1.0001.32/4.2_BUD	100401_1.0001.52_BUD
100401_1.0001.32/5.1_BUD	100401_1.0001.53_BUD

100401_1.0001.34/8.1_BUD	100401_1.0001.54_BUD
100401_1.0001.34/8.2_BUD	100401_1.0001.55_BUD
100401_1.0001.34/13.1_BUD	100401_1.0001.56_BUD
100401_1.0001.35/3.1_BUD	100401_1.0001.57_BUD
100401_1.0001.35/4.1_BUD	100401_1.0001.58_BUD
100401_1.0001.35/4.2_BUD	100401_1.0001.59_BUD
100401_1.0001.36/3.3_BUD	100401_1.0001.60_BUD
100401_1.0001.36/11.3_BUD	100401_1.0001.61_BUD
100401_1.0001.36/11.4_BUD	100401_1.0001.62_BUD
100401_1.0001.42.1_BUD	100401_1.0001.63_BUD
100401_1.0001.44.1_BUD	100401_1.0001.64_BUD
100401_1.0001.44.2_BUD	100401_1.0001.65_BUD
100401_1.0001.46.1_BUD	100401_1.0001.66_BUD
100401_1.0001.46.2_BUD	100401_1.0001.67_BUD
100401_1.0001.46.3_BUD	100401_1.0001.68_BUD
100401_1.0001.46.4_BUD	100401_1.0001.69_BUD
100401_1.0001.46.5_BUD	100401_1.0001.70_BUD
100401_1.0001.46.6_BUD	100401_1.0001.71_BUD
100401_1.0001.46.7_BUD	100401_1.0001.72_BUD
100401_1.0001.48.1_BUD	100401_1.0001.73_BUD
100401_1.0001.48.2_BUD	100401_1.0001.74_BUD
100401_1.0001.48.3_BUD	100401_1.0001.75_BUD
100401_1.0001.48.4_BUD	100401_1.0001.76_BUD
100401_1.0001.48.5_BUD	100401_1.0001.77_BUD
100401_1.0001.48.6_BUD	100401_1.0001.78_BUD
100401_1.0001.48.7_BUD	100401_1.0001.79_BUD
100401_1.0001.51.1_BUD	100401_1.0001.80_BUD
100401_1.0001.51.2_BUD	100401_1.0001.81_BUD
100401_1.0001.51.3_BUD	100401_1.0001.82_BUD
100401_1.0001.53.1_BUD	100401_1.0001.83_BUD
100401_1.0001.55/3.1_BUD	100401_1.0001.84_BUD
100401_1.0001.55/3.4_BUD	100401_1.0001.85_BUD
100401_1.0001.55/3.5_BUD	100401_1.0001.86_BUD
100401_1.0001.55/3.6_BUD	100401_1.0001.87_BUD
100401_1.0001.55/4.1_BUD	100401_1.0001.88_BUD
100401_1.0001.55/5.1_BUD	100401_1.0001.89_BUD
100401_1.0001.55/6.1_BUD	100401_1.0001.90_BUD
100401_1.0001.55/6.2_BUD	100401_1.0001.91_BUD
100401_1.0001.57/1.1_BUD	100401_1.0001.92_BUD
100401_1.0001.57/1.2_BUD	100401_1.0001.93_BUD
100401_1.0001.59/1.1_BUD	100401_1.0001.94_BUD
100401_1.0001.59/1.2_BUD	100401_1.0001.95_BUD
100401_1.0001.59/1.3_BUD	100401_1.0001.96_BUD
100401_1.0001.59/5.1_BUD	100401_1.0001.97_BUD
100401_1.0001.59/5.2_BUD	100401_1.0001.98_BUD
100401_1.0001.63/2.1_BUD	100401_1.0001.99_BUD
100401_1.0001.63/2.2_BUD	100401_1.0001.100_BUD
100401_1.0001.63/2.3_BUD	100401_1.0001.101_BUD
100401_1.0001.63/2.4_BUD	100401_1.0001.102_BUD
100401_1.0001.63/2.5_BUD	100401_1.0001.103_BUD
100401_1.0001.65/3.1_BUD	100401_1.0001.104_BUD
100401_1.0001.65/4.1_BUD	100401_1.0001.105_BUD
100401_1.0001.65/4.2_BUD	100401_1.0001.106_BUD
100401_1.0001.65/4.3_BUD	100401_1.0001.107_BUD

100401_1.0001.65/4.4_BUD	100401_1.0001.108_BUD
100401_1.0001.65/4.5_BUD	100401_1.0001.109_BUD
100401_1.0001.65/4.6_BUD	100401_1.0001.110_BUD
100401_1.0001.65/4.7_BUD	100401_1.0001.111_BUD
100401_1.0001.65/4.8_BUD	100401_1.0001.112_BUD
100401_1.0001.65/4.9_BUD	100401_1.0001.113_BUD
100401_1.0001.65/6.1_BUD	100401_1.0001.114_BUD
100401_1.0001.65/6.2_BUD	100401_1.0001.115_BUD
100401_1.0001.89/2.1_BUD	100401_1.0001.116_BUD
100401_1.0001.89/2.2_BUD	100401_1.0001.117_BUD
100401_1.0001.89/2.3_BUD	100401_1.0001.118_BUD
100401_1.0001.89/5.1_BUD	100401_1.0001.119_BUD
100401_1.0001.89/5.2_BUD	100401_1.0001.120_BUD
100401_1.0001.89/5.3_BUD	100401_1.0001.121_BUD
100401_1.0001.89/5.4_BUD	100401_1.0001.122_BUD
100401_1.0001.90.1_BUD	100401_1.0001.123_BUD
100401_1.0001.91.1_BUD	100401_1.0001.124_BUD
100401_1.0001.91.2_BUD	100401_1.0001.125_BUD
100401_1.0001.91.3_BUD	100401_1.0001.126_BUD
100401_1.0001.91.4_BUD	100401_1.0001.127_BUD
100401_1.0001.91.5_BUD	100401_1.0001.128_BUD
100401_1.0001.91.6_BUD	100401_1.0001.129_BUD
100401_1.0001.92.1_BUD	100401_1.0001.130_BUD
100401_1.0001.92.2_BUD	100401_1.0001.131_BUD
100401_1.0001.92.3_BUD	100401_1.0001.132_BUD
100401_1.0001.92.4_BUD	100401_1.0001.133_BUD
100401_1.0001.95.1_BUD	100401_1.0001.134_BUD
100401_1.0001.95.2_BUD	100401_1.0001.135_BUD
100401_1.0001.95.3_BUD	100401_1.0001.136_BUD
100401_1.0001.96.1_BUD	100401_1.0001.137_BUD
100401_1.0001.96.2_BUD	100401_1.0001.138_BUD
100401_1.0001.99/2.1_BUD	100401_1.0001.139_BUD
100401_1.0001.100.1_BUD	100401_1.0001.140_BUD
100401_1.0001.100.2_BUD	100401_1.0001.141_BUD
100401_1.0001.103.1_BUD	100401_1.0001.142_BUD
100401_1.0001.103.2_BUD	100401_1.0001.143_BUD
100401_1.0001.103.3_BUD	100401_1.0001.144_BUD
100401_1.0001.104.1_BUD	100401_1.0001.145_BUD
100401_1.0001.105.1_BUD	100401_1.0001.146_BUD
100401_1.0001.105/1.2_BUD	100401_1.0001.147_BUD
100401_1.0001.105/4.1_BUD	100401_1.0001.148_BUD
100401_1.0001.105/5.1_BUD	100401_1.0001.149_BUD
100401_1.0001.107/5.1_BUD	100401_1.0001.150_BUD
100401_1.0001.107/5.2_BUD	100401_1.0001.151_BUD
100401_1.0001.107/6.1_BUD	100401_1.0001.152_BUD
100401_1.0001.108/1.1_BUD	100401_1.0001.153_BUD
100401_1.0001.108/3.1_BUD	100401_1.0001.154_BUD
100401_1.0001.108/4.1_BUD	100401_1.0001.155_BUD
100401_1.0001.109/2.1_BUD	100401_1.0001.156_BUD
100401_1.0001.109/2.2_BUD	100401_1.0001.157_BUD
100401_1.0001.109/7.1_BUD	100401_1.0001.158_BUD
100401_1.0001.111/2.2_BUD	100401_1.0001.159_BUD
100401_1.0001.114.1_BUD	100401_1.0001.160_BUD
100401_1.0001.114.2_BUD	100401_1.0001.161_BUD

100401_1.0001.114.3_BUD	100401_1.0001.162_BUD
100401_1.0001.116.1_BUD	100401_1.0001.163_BUD
100401_1.0001.116.3_BUD	100401_1.0001.164_BUD
100401_1.0001.116/4.1_BUD	100401_1.0001.165_BUD
100401_1.0001.116/4.2_BUD	100401_1.0001.166_BUD
100401_1.0001.116/9.1_BUD	100401_1.0001.167_BUD
100401_1.0001.117/4.1_BUD	100401_1.0001.168_BUD
100401_1.0001.117/5.1_BUD	100401_1.0001.169_BUD
100401_1.0001.117/8.14_BUD	100401_1.0001.170_BUD
100401_1.0001.117/10.1_BUD	100401_1.0001.171_BUD
100401_1.0001.118/4.1_BUD	100401_1.0001.172_BUD
100401_1.0001.118/4.2_BUD	100401_1.0001.173_BUD
100401_1.0001.118/4.3_BUD	100401_1.0001.174_BUD
100401_1.0001.118/4.4_BUD	100401_1.0001.175_BUD
100401_1.0001.118/19.1_BUD	100401_1.0001.176_BUD
100401_1.0001.119/5.1_BUD	100401_1.0001.177_BUD
100401_1.0001.119/11.1_BUD	100401_1.0001.178_BUD
100401_1.0001.119/13.1_BUD	100401_1.0001.179_BUD
100401_1.0001.119/14.1_BUD	100401_1.0001.180_BUD
100401_1.0001.119/15.1_BUD	100401_1.0001.181_BUD
100401_1.0001.119/19.1_BUD	100401_1.0001.182_BUD
100401_1.0001.119/21.1_BUD	100401_1.0001.183_BUD
100401_1.0001.119/22.1_BUD	100401_1.0001.184_BUD
100401_1.0001.119/23.1_BUD	100401_1.0001.185_BUD
100401_1.0001.119/24.1_BUD	100401_1.0001.186_BUD
100401_1.0001.120/2.1_BUD	100401_1.0001.187_BUD
100401_1.0001.120/6.1_BUD	100401_1.0001.188_BUD
100401_1.0001.120/7.1_BUD	100401_1.0001.189_BUD
100401_1.0001.120/8.1_BUD	100401_1.0001.190_BUD
100401_1.0001.120/9.1_BUD	100401_1.0001.191_BUD
100401_1.0001.120/10.1_BUD	100401_1.0001.192_BUD
100401_1.0001.120/13.1_BUD	100401_1.0001.193_BUD
100401_1.0001.120/14.1_BUD	100401_1.0001.194_BUD
100401_1.0001.120/15.1_BUD	100401_1.0001.195_BUD
100401_1.0001.120/16.1_BUD	100401_1.0001.196_BUD
100401_1.0001.126/8.1_BUD	100401_1.0001.197_BUD
100401_1.0001.126/13.1_BUD	100401_1.0001.198_BUD
100401_1.0001.126/13.2_BUD	100401_1.0001.199_BUD
100401_1.0001.126/17.1_BUD	100401_1.0001.200_BUD
100401_1.0001.126/18.1_BUD	100401_1.0001.201_BUD
100401_1.0001.126/19.1_BUD	100401_1.0001.202_BUD
100401_1.0001.126/20.1_BUD	100401_1.0001.203_BUD
100401_1.0001.126/23.1_BUD	100401_1.0001.204_BUD
100401_1.0001.126/24.1_BUD	100401_1.0001.205_BUD
100401_1.0001.126/25.1_BUD	100401_1.0001.206_BUD
100401_1.0001.131/8.1_BUD	100401_1.0001.207_BUD
100401_1.0001.131/8.2_BUD	100401_1.0001.208_BUD
100401_1.0001.131/9.1_BUD	100401_1.0001.209_BUD
100401_1.0001.132/1.1_BUD	100401_1.0001.210_BUD
100401_1.0001.132/3.5_BUD	100401_1.0001.211_BUD
100401_1.0001.132/3.6_BUD	100401_1.0001.212_BUD
100401_1.0001.132/3.7_BUD	100401_1.0001.213_BUD
100401_1.0001.132/3.8_BUD	100401_1.0001.214_BUD
100401_1.0001.132/4.1_BUD	100401_1.0001.215_BUD

100401_1.0001.132/4.2_BUD	100401_1.0001.216_BUD
100401_1.0001.141/1.1_BUD	100401_1.0001.217_BUD
100401_1.0001.141/1.2_BUD	100401_1.0001.218_BUD
100401_1.0001.142/1.1_BUD	100401_1.0001.219_BUD
100401_1.0001.142/1.2_BUD	100401_1.0001.220_BUD
100401_1.0001.142/4.1_BUD	100401_1.0001.221_BUD
100401_1.0001.144.1_BUD	100401_1.0001.222_BUD
100401_1.0001.144.2_BUD	100401_1.0001.223_BUD
100401_1.0001.144.3_BUD	100401_1.0001.224_BUD
100401_1.0001.146.1_BUD	100401_1.0001.225_BUD
100401_1.0001.146.2_BUD	100401_1.0001.226_BUD
100401_1.0001.146/4.1_BUD	100401_1.0001.227_BUD
100401_1.0001.146/5.1_BUD	100401_1.0001.228_BUD
100401_1.0001.149/5.1_BUD	100401_1.0001.229_BUD
100401_1.0001.149/7.1_BUD	100401_1.0001.230_BUD
100401_1.0001.151.1_BUD	100401_1.0001.231_BUD
100401_1.0001.151/2.1_BUD	100401_1.0001.232_BUD
100401_1.0001.151/2.2_BUD	100401_1.0001.233_BUD
100401_1.0001.151/3.1_BUD	100401_1.0001.234_BUD
100401_1.0001.151/4.1_BUD	100401_1.0001.235_BUD
100401_1.0001.152/1.1_BUD	100401_1.0001.236_BUD
100401_1.0001.153.1_BUD	100401_1.0001.237_BUD
100401_1.0001.153/2.1_BUD	100401_1.0001.238_BUD
100401_1.0001.154/1.1_BUD	100401_1.0001.239_BUD
100401_1.0001.155/1.1_BUD	100401_1.0001.240_BUD
100401_1.0001.155/1.3_BUD	100401_1.0001.241_BUD
100401_1.0001.155/1.4_BUD	100401_1.0001.242_BUD
100401_1.0001.155/11.1_BUD	100401_1.0001.243_BUD
100401_1.0001.157/1.1_BUD	100401_1.0001.244_BUD
100401_1.0001.157/1.2_BUD	100401_1.0001.245_BUD
100401_1.0001.157/1.3_BUD	100401_1.0001.246_BUD
100401_1.0001.157/1.4_BUD	100401_1.0001.247_BUD
100401_1.0001.160/1.1_BUD	100401_1.0001.248_BUD
100401_1.0001.163.1_BUD	100401_1.0001.249_BUD
100401_1.0001.164.1_BUD	100401_1.0001.250_BUD
100401_1.0001.164.2_BUD	100401_1.0001.251_BUD
100401_1.0001.164.3_BUD	100401_1.0001.252_BUD
100401_1.0001.164.4_BUD	100401_1.0001.253_BUD
100401_1.0001.168.1_BUD	100401_1.0001.254_BUD
100401_1.0001.168.2_BUD	100401_1.0001.255_BUD
100401_1.0001.168.3_BUD	100401_1.0001.256_BUD
100401_1.0001.169/2.2_BUD	100401_1.0001.257_BUD
100401_1.0001.170.1_BUD	100401_1.0001.258_BUD
100401_1.0001.177.1_BUD	100401_1.0001.259_BUD
100401_1.0001.187.1_BUD	100401_1.0001.260_BUD
100401_1.0001.189/2.1_BUD	100401_1.0001.261_BUD
100401_1.0001.189/2.2_BUD	100401_1.0001.262_BUD
100401_1.0001.189/2.3_BUD	100401_1.0001.263_BUD
100401_1.0001.210.1_BUD	100401_1.0001.264_BUD
100401_1.0001.210.2_BUD	100401_1.0001.265_BUD
100401_1.0001.211.1_BUD	100401_1.0001.266_BUD
100401_1.0001.211.2_BUD	100401_1.0001.267_BUD
100401_1.0001.212.1_BUD	100401_1.0001.268_BUD
100401_1.0001.212.2_BUD	100401_1.0001.269_BUD

100401_1.0001.213.1_BUD	100401_1.0001.270_BUD
100401_1.0001.213.2_BUD	100401_1.0001.271_BUD
100401_1.0001.214.1_BUD	100401_1.0001.272_BUD
100401_1.0001.214.2_BUD	100401_1.0001.273_BUD
100401_1.0001.215.1_BUD	100401_1.0001.274_BUD
100401_1.0001.215.2_BUD	100401_1.0001.275_BUD
100401_1.0001.216.1_BUD	100401_1.0001.276_BUD
100401_1.0001.216.2_BUD	100401_1.0001.277_BUD
100401_1.0001.218.1_BUD	100401_1.0001.278_BUD
100401_1.0001.218.2_BUD	100401_1.0001.279_BUD
100401_1.0001.219.1_BUD	100401_1.0001.280_BUD
100401_1.0001.219.2_BUD	100401_1.0001.281_BUD
100401_1.0001.220.1_BUD	100401_1.0001.282_BUD
100401_1.0001.220.2_BUD	100401_1.0001.283_BUD
100401_1.0001.221.1_BUD	100401_1.0001.284_BUD
100401_1.0001.221.2_BUD	100401_1.0001.285_BUD
100401_1.0001.222.1_BUD	100401_1.0001.286_BUD
100401_1.0001.222.2_BUD	100401_1.0001.287_BUD
100401_1.0001.223/1.1_BUD	100401_1.0001.288_BUD
100401_1.0001.223/1.2_BUD	100401_1.0001.289_BUD
100401_1.0001.223/2.1_BUD	100401_1.0001.290_BUD
100401_1.0001.223/2.2_BUD	100401_1.0001.291_BUD
100401_1.0001.224.1_BUD	100401_1.0001.292_BUD
100401_1.0001.224.2_BUD	100401_1.0001.293_BUD
100401_1.0001.225.1_BUD	100401_1.0001.294_BUD
100401_1.0001.225.2_BUD	100401_1.0001.295_BUD
100401_1.0001.225.3_BUD	100401_1.0001.296_BUD
100401_1.0001.226.1_BUD	100401_1.0001.297_BUD
100401_1.0001.226.2_BUD	100401_1.0001.298_BUD
100401_1.0001.226.3_BUD	100401_1.0001.299_BUD
100401_1.0001.227.1_BUD	100401_1.0001.300_BUD
100401_1.0001.227.2_BUD	100401_1.0001.301_BUD
100401_1.0001.227.3_BUD	100401_1.0001.302_BUD
100401_1.0001.228.1_BUD	100401_1.0001.303_BUD
100401_1.0001.228.2_BUD	100401_1.0001.304_BUD
100401_1.0001.229.1_BUD	100401_1.0001.305_BUD
100401_1.0001.229.2_BUD	100401_1.0001.306_BUD
100401_1.0001.230.1_BUD	100401_1.0001.307_BUD
100401_1.0001.230.2_BUD	100401_1.0001.308_BUD
100401_1.0001.231.1_BUD	100401_1.0001.309_BUD
100401_1.0001.231.2_BUD	100401_1.0001.310_BUD
100401_1.0001.231.3_BUD	100401_1.0001.311_BUD
100401_1.0001.232.1_BUD	100401_1.0001.312_BUD
100401_1.0001.233.1_BUD	100401_1.0001.313_BUD
100401_1.0001.233.2_BUD	100401_1.0001.314_BUD
100401_1.0001.234.1_BUD	100401_1.0001.315_BUD
100401_1.0001.236.1_BUD	100401_1.0001.316_BUD
100401_1.0001.236.2_BUD	100401_1.0001.317_BUD
100401_1.0001.237.1_BUD	100401_1.0001.318_BUD
100401_1.0001.237.2_BUD	100401_1.0001.319_BUD
100401_1.0001.238.1_BUD	100401_1.0001.320_BUD
100401_1.0001.238.2_BUD	100401_1.0001.321_BUD
100401_1.0001.238.3_BUD	100401_1.0001.322_BUD
100401_1.0001.239.1_BUD	100401_1.0001.323_BUD

100401_1.0001.239.2_BUD	100401_1.0001.324_BUD
100401_1.0001.240.1_BUD	100401_1.0001.325_BUD
100401_1.0001.240.2_BUD	100401_1.0001.326_BUD
100401_1.0001.240.3_BUD	100401_1.0001.327_BUD
100401_1.0001.241.1_BUD	100401_1.0001.328_BUD
100401_1.0001.241.2_BUD	100401_1.0001.329_BUD
100401_1.0001.242.1_BUD	100401_1.0001.330_BUD
100401_1.0001.242.2_BUD	100401_1.0001.331_BUD
100401_1.0001.243.1_BUD	100401_1.0001.332_BUD
100401_1.0001.243.2_BUD	100401_1.0001.333_BUD
100401_1.0001.243.3_BUD	100401_1.0001.334_BUD
100401_1.0001.244.1_BUD	100401_1.0001.335_BUD
100401_1.0001.244.2_BUD	100401_1.0001.336_BUD
100401_1.0001.245.1_BUD	100401_1.0001.337_BUD
100401_1.0001.245.2_BUD	100401_1.0001.338_BUD
100401_1.0001.245.3_BUD	100401_1.0001.339_BUD
100401_1.0001.247.1_BUD	100401_1.0001.340_BUD
100401_1.0001.247.2_BUD	100401_1.0001.341_BUD
100401_1.0001.248.1_BUD	100401_1.0001.342_BUD
100401_1.0001.248.2_BUD	100401_1.0001.343_BUD
100401_1.0001.249.1_BUD	100401_1.0001.344_BUD
100401_1.0001.249.2_BUD	100401_1.0001.345_BUD
100401_1.0001.250.1_BUD	100401_1.0001.346_BUD
100401_1.0001.250.2_BUD	100401_1.0001.347_BUD
100401_1.0001.250.3_BUD	100401_1.0001.348_BUD
100401_1.0001.251.1_BUD	100401_1.0001.349_BUD
100401_1.0001.251.2_BUD	100401_1.0001.350_BUD
100401_1.0001.252.1_BUD	100401_1.0001.351_BUD
100401_1.0001.252.2_BUD	100401_1.0001.352_BUD
100401_1.0001.253.1_BUD	100401_1.0001.353_BUD
100401_1.0001.253.2_BUD	100401_1.0001.354_BUD
100401_1.0001.254.1_BUD	100401_1.0001.355_BUD
100401_1.0001.255.1_BUD	100401_1.0001.356_BUD
100401_1.0001.256.1_BUD	100401_1.0001.357_BUD
100401_1.0001.256.2_BUD	100401_1.0001.358_BUD
100401_1.0001.257.1_BUD	100401_1.0001.359_BUD
100401_1.0001.257.2_BUD	100401_1.0001.360_BUD
100401_1.0001.258.1_BUD	100401_1.0001.361_BUD
100401_1.0001.258.2_BUD	100401_1.0001.362_BUD
100401_1.0001.260.1_BUD	100401_1.0001.363_BUD
100401_1.0001.261.1_BUD	100401_1.0001.364_BUD
100401_1.0001.261.2_BUD	100401_1.0001.365_BUD
100401_1.0001.261.3_BUD	100401_1.0001.366_BUD
100401_1.0001.262.1_BUD	100401_1.0001.367_BUD
100401_1.0001.262.2_BUD	100401_1.0001.368_BUD
100401_1.0001.263.1_BUD	100401_1.0001.369_BUD
100401_1.0001.263.2_BUD	100401_1.0001.370_BUD
100401_1.0001.263.3_BUD	100401_1.0001.371_BUD
100401_1.0001.264.1_BUD	100401_1.0001.372_BUD
100401_1.0001.264.2_BUD	100401_1.0001.373_BUD
100401_1.0001.264.3_BUD	100401_1.0001.374_BUD
100401_1.0001.265.1_BUD	100401_1.0001.375_BUD
100401_1.0001.265.2_BUD	100401_1.0001.376_BUD
100401_1.0001.266.1_BUD	100401_1.0001.377_BUD

100401_1.0001.266.2_BUD	100401_1.0001.378_BUD
100401_1.0001.267.1_BUD	100401_1.0001.379_BUD
100401_1.0001.267.2_BUD	100401_1.0001.380_BUD
100401_1.0001.267.3_BUD	100401_1.0001.381_BUD
100401_1.0001.268.1_BUD	100401_1.0001.382_BUD
100401_1.0001.268.2_BUD	100401_1.0001.383_BUD
100401_1.0001.269.1_BUD	100401_1.0001.384_BUD
100401_1.0001.269.2_BUD	100401_1.0001.385_BUD
100401_1.0001.270.1_BUD	100401_1.0001.386_BUD
100401_1.0001.270.2_BUD	100401_1.0001.387_BUD
100401_1.0001.271.1_BUD	100401_1.0001.388_BUD
100401_1.0001.271.2_BUD	100401_1.0001.389_BUD
100401_1.0001.273.1_BUD	100401_1.0001.390_BUD
100401_1.0001.273.2_BUD	100401_1.0001.391_BUD
100401_1.0001.274.1_BUD	100401_1.0001.392_BUD
100401_1.0001.274.2_BUD	100401_1.0001.393_BUD
100401_1.0001.275.1_BUD	100401_1.0001.394_BUD
100401_1.0001.276.1_BUD	100401_1.0001.395_BUD
100401_1.0001.276.2_BUD	100401_1.0001.396_BUD
100401_1.0001.277.1_BUD	100401_1.0001.397_BUD
100401_1.0001.277.2_BUD	100401_1.0001.398_BUD
100401_1.0001.278.1_BUD	100401_1.0001.399_BUD
100401_1.0001.278.2_BUD	100401_1.0001.400_BUD
100401_1.0001.279.1_BUD	100401_1.0001.401_BUD
100401_1.0001.279.2_BUD	100401_1.0001.402_BUD
100401_1.0001.280.1_BUD	100401_1.0001.403_BUD
100401_1.0001.281.1_BUD	100401_1.0001.404_BUD
100401_1.0001.281.2_BUD	100401_1.0001.405_BUD
100401_1.0001.282.1_BUD	100401_1.0001.406_BUD
100401_1.0001.282.2_BUD	100401_1.0001.407_BUD
100401_1.0001.284.1_BUD	100401_1.0001.408_BUD
100401_1.0001.287/2.1_BUD	100401_1.0001.409_BUD
100401_1.0001.287/2.2_BUD	100401_1.0001.410_BUD
100401_1.0001.287/2.3_BUD	100401_1.0001.411_BUD
100401_1.0001.287/2.4_BUD	100401_1.0001.412_BUD
100401_1.0001.287/2.5_BUD	100401_1.0001.413_BUD
100401_1.0001.287/3.1_BUD	100401_1.0001.414_BUD
100401_1.0001.287/3.2_BUD	100401_1.0001.415_BUD
100401_1.0001.287/3.3_BUD	100401_1.0001.416_BUD
100401_1.0001.287/3.4_BUD	100401_1.0001.417_BUD
100401_1.0001.287/3.5_BUD	100401_1.0001.418_BUD
100401_1.0001.287/3.6_BUD	100401_1.0001.419_BUD
100401_1.0001.288/4.1_BUD	100401_1.0001.420_BUD
100401_1.0001.288/5.1_BUD	100401_1.0001.421_BUD
100401_1.0001.288/5.2_BUD	100401_1.0001.422_BUD
100401_1.0001.288/5.3_BUD	100401_1.0001.423_BUD
100401_1.0001.288/5.4_BUD	100401_1.0001.424_BUD
100401_1.0001.288/5.5_BUD	100401_1.0001.425_BUD
100401_1.0001.288/5.6_BUD	100401_1.0001.426_BUD
100401_1.0001.288/5.7_BUD	100401_1.0001.427_BUD
100401_1.0001.288/5.8_BUD	100401_1.0001.428_BUD
100401_1.0001.288/6.1_BUD	100401_1.0001.429_BUD
100401_1.0001.288/6.2_BUD	100401_1.0001.430_BUD
100401_1.0001.289/3.1_BUD	100401_1.0001.431_BUD

100401_1.0001.289/3.2_BUD	100401_1.0001.432_BUD
100401_1.0001.289/3.3_BUD	100401_1.0001.433_BUD
100401_1.0001.290/4.1_BUD	100401_1.0001.434_BUD
100401_1.0001.290/4.2_BUD	100401_1.0001.435_BUD
100401_1.0001.290/4.3_BUD	100401_1.0001.436_BUD
100401_1.0001.290/4.4_BUD	100401_1.0001.437_BUD
100401_1.0001.290/4.5_BUD	100401_1.0001.438_BUD
100401_1.0001.292/4.1_BUD	100401_1.0001.439_BUD
100401_1.0001.292/4.2_BUD	100401_1.0001.440_BUD
100401_1.0001.292/4.3_BUD	100401_1.0001.441_BUD
100401_1.0001.292/4.4_BUD	100401_1.0001.442_BUD
100401_1.0001.293/5.1_BUD	100401_1.0001.443_BUD
100401_1.0001.293/7.1_BUD	100401_1.0001.444_BUD
100401_1.0001.293/8.1_BUD	100401_1.0001.445_BUD
100401_1.0001.293/8.2_BUD	100401_1.0001.446_BUD
100401_1.0001.293/9.1_BUD	100401_1.0001.447_BUD
100401_1.0001.293/10.1_BUD	100401_1.0001.448_BUD
100401_1.0001.293/11.1_BUD	100401_1.0001.449_BUD
100401_1.0001.293/13.1_BUD	100401_1.0001.450_BUD
100401_1.0001.293/15.1_BUD	100401_1.0001.451_BUD
100401_1.0001.293/15.2_BUD	100401_1.0001.452_BUD
100401_1.0001.293/16.1_BUD	100401_1.0001.453_BUD
100401_1.0001.293/16.2_BUD	100401_1.0001.454_BUD
100401_1.0001.293/19.1_BUD	100401_1.0001.455_BUD
100401_1.0001.293/20.1_BUD	100401_1.0001.456_BUD
100401_1.0001.293/22.1_BUD	100401_1.0001.457_BUD
100401_1.0001.293/23.1_BUD	100401_1.0001.458_BUD
100401_1.0001.293/24.1_BUD	100401_1.0001.459_BUD
100401_1.0001.293/25.1_BUD	100401_1.0001.460_BUD
100401_1.0001.293/26.1_BUD	100401_1.0001.461_BUD
100401_1.0001.293/27.1_BUD	100401_1.0001.462_BUD
100401_1.0001.293/27.2_BUD	100401_1.0001.463_BUD
100401_1.0001.293/28.1_BUD	100401_1.0001.464_BUD
100401_1.0001.293/31.1_BUD	100401_1.0001.465_BUD
100401_1.0001.293/32.1_BUD	100401_1.0001.466_BUD
100401_1.0001.293/33.1_BUD	100401_1.0001.467_BUD
100401_1.0001.294.1_BUD	100401_1.0001.468_BUD
100401_1.0001.294.2_BUD	100401_1.0001.469_BUD
100401_1.0001.294.3_BUD	100401_1.0001.470_BUD
100401_1.0001.294/1.1_BUD	100401_1.0001.471_BUD
100401_1.0001.295/28.1_BUD	100401_1.0001.472_BUD
100401_1.0001.295/29.1_BUD	100401_1.0001.473_BUD
100401_1.0001.295/29.2_BUD	100401_1.0001.474_BUD
100401_1.0001.295/29.3_BUD	100401_1.0001.475_BUD
100401_1.0001.295/30.1_BUD	100401_1.0001.476_BUD
100401_1.0001.295/37.1_BUD	100401_1.0001.477_BUD
100401_1.0001.295/37.4_BUD	100401_1.0001.478_BUD
100401_1.0001.295/37.5_BUD	100401_1.0001.479_BUD
100401_1.0001.295/39.1_BUD	100401_1.0001.480_BUD
100401_1.0001.295/40.1_BUD	100401_1.0001.481_BUD
100401_1.0001.295/41.1_BUD	100401_1.0001.482_BUD
100401_1.0001.295/42.1_BUD	100401_1.0001.483_BUD
100401_1.0001.295/43.1_BUD	100401_1.0001.484_BUD
100401_1.0001.295/45.1_BUD	100401_1.0001.485_BUD

100401_1.0001.296/26.1_BUD	100401_1.0001.486_BUD
100401_1.0001.296/28.1_BUD	100401_1.0001.487_BUD
100401_1.0001.296/30.1_BUD	100401_1.0001.488_BUD
100401_1.0001.296/32.1_BUD	100401_1.0001.489_BUD
100401_1.0001.296/33.1_BUD	100401_1.0001.490_BUD
100401_1.0001.296/34.1_BUD	100401_1.0001.491_BUD
100401_1.0001.296/34.2_BUD	100401_1.0001.492_BUD
100401_1.0001.296/41.3_BUD	100401_1.0001.493_BUD
100401_1.0001.296/41.4_BUD	100401_1.0001.494_BUD
100401_1.0001.296/43.1_BUD	100401_1.0001.495_BUD
100401_1.0001.296/44.1_BUD	100401_1.0001.496_BUD
100401_1.0001.296/44.2_BUD	100401_1.0001.497_BUD
100401_1.0001.296/45.1_BUD	100401_1.0001.498_BUD
100401_1.0001.297/1.1_BUD	100401_1.0001.499_BUD
100401_1.0001.297/1.2_BUD	100401_1.0001.500_BUD
100401_1.0001.297/1.3_BUD	100401_1.0001.501_BUD
100401_1.0001.297/1.4_BUD	100401_1.0001.502_BUD
100401_1.0001.311/1.1_BUD	100401_1.0001.503_BUD
100401_1.0001.311/1.2_BUD	100401_1.0001.504_BUD
100401_1.0001.311/1.3_BUD	100401_1.0001.505_BUD
100401_1.0001.311/1.4_BUD	100401_1.0001.506_BUD
100401_1.0001.311/1.6_BUD	100401_1.0001.507_BUD
100401_1.0001.311/1.7_BUD	100401_1.0001.508_BUD
100401_1.0001.311/1.8_BUD	100401_1.0001.509_BUD
100401_1.0001.311/1.9_BUD	100401_1.0001.510_BUD
100401_1.0001.311/5.2_BUD	100401_1.0001.511_BUD
100401_1.0001.311/9.1_BUD	100401_1.0001.512_BUD
100401_1.0001.311/17.2_BUD	100401_1.0001.513_BUD
100401_1.0001.311/17.3_BUD	100401_1.0001.514_BUD
100401_1.0001.326/1.1_BUD	100401_1.0001.515_BUD
100401_1.0001.326/1.2_BUD	100401_1.0001.516_BUD
100401_1.0001.326/1.3_BUD	100401_1.0001.517_BUD
100401_1.0001.326/1.4_BUD	100401_1.0001.518_BUD
100401_1.0001.334.1_BUD	100401_1.0001.519_BUD
100401_1.0001.334.2_BUD	100401_1.0001.520_BUD
100401_1.0001.334.3_BUD	100401_1.0001.521_BUD
100401_1.0001.334.4_BUD	100401_1.0001.522_BUD
100401_1.0001.334.5_BUD	100401_1.0001.523_BUD
100401_1.0001.337/11.2_BUD	100401_1.0001.524_BUD
100401_1.0001.337/12.2_BUD	100401_1.0001.525_BUD
100401_1.0001.337/13.2_BUD	100401_1.0001.526_BUD
100401_1.0001.337/14.2_BUD	100401_1.0001.527_BUD
100401_1.0001.337/15.2_BUD	100401_1.0001.528_BUD
100401_1.0001.337/16.2_BUD	100401_1.0001.529_BUD
100401_1.0001.337/17.2_BUD	100401_1.0001.530_BUD
100401_1.0001.337/18.2_BUD	100401_1.0001.531_BUD
100401_1.0001.337/19.2_BUD	100401_1.0001.532_BUD
100401_1.0001.337/20.2_BUD	100401_1.0001.533_BUD
100401_1.0001.337/21.2_BUD	100401_1.0001.534_BUD
100401_1.0001.337/22.2_BUD	100401_1.0001.535_BUD
100401_1.0001.337/23.2_BUD	100401_1.0001.536_BUD
100401_1.0001.337/24.2_BUD	100401_1.0001.537_BUD
100401_1.0001.337/25.2_BUD	100401_1.0001.538_BUD
100401_1.0001.337/26.2_BUD	100401_1.0001.539_BUD

100401_1.0001.337/29.1_BUD	100401_1.0001.540_BUD
100401_1.0001.337/30.1_BUD	100401_1.0001.541_BUD
100401_1.0001.337/31.1_BUD	100401_1.0001.542_BUD
100401_1.0001.337/32.1_BUD	100401_1.0001.543_BUD
100401_1.0001.337/33.1_BUD	100401_1.0001.544_BUD
100401_1.0001.337/34.1_BUD	100401_1.0001.545_BUD
100401_1.0001.337/35.1_BUD	100401_1.0001.546_BUD
100401_1.0001.337/36.1_BUD	100401_1.0001.547_BUD
100401_1.0001.337/37.1_BUD	100401_1.0001.548_BUD
100401_1.0001.337/38.1_BUD	100401_1.0001.549_BUD
100401_1.0001.337/39.1_BUD	100401_1.0001.550_BUD
100401_1.0001.337/40.1_BUD	100401_1.0001.551_BUD
100401_1.0001.337/41.2_BUD	100401_1.0001.552_BUD
100401_1.0001.337/42.1_BUD	100401_1.0001.553_BUD
100401_1.0001.337/72.1_BUD	100401_1.0001.554_BUD
100401_1.0001.337/73.1_BUD	100401_1.0001.555_BUD
100401_1.0001.337/74.1_BUD	100401_1.0001.556_BUD
100401_1.0001.337/75.1_BUD	100401_1.0001.557_BUD
100401_1.0001.337/76.1_BUD	100401_1.0001.558_BUD
100401_1.0001.337/77.1_BUD	100401_1.0001.559_BUD
100401_1.0001.337/78.1_BUD	100401_1.0001.560_BUD
100401_1.0001.337/79.1_BUD	100401_1.0001.561_BUD
100401_1.0001.337/80.1_BUD	100401_1.0001.562_BUD
100401_1.0001.337/81.1_BUD	100401_1.0001.563_BUD
100401_1.0001.337/82.1_BUD	100401_1.0001.564_BUD
100401_1.0001.337/83.1_BUD	100401_1.0001.565_BUD
100401_1.0001.337/84.1_BUD	100401_1.0001.566_BUD
100401_1.0001.337/85.1_BUD	100401_1.0001.567_BUD
100401_1.0001.337/86.1_BUD	100401_1.0001.568_BUD
100401_1.0001.337/87.1_BUD	100401_1.0001.569_BUD
100401_1.0001.337/88.1_BUD	100401_1.0001.570_BUD
100401_1.0001.337/89.1_BUD	100401_1.0001.571_BUD
100401_1.0001.337/90.1_BUD	100401_1.0001.572_BUD
100401_1.0001.337/91.1_BUD	100401_1.0001.573_BUD
100401_1.0001.337/92.1_BUD	100401_1.0001.574_BUD
100401_1.0001.337/93.1_BUD	100401_1.0001.575_BUD
100401_1.0001.337/94.1_BUD	100401_1.0001.576_BUD
100401_1.0001.337/95.1_BUD	100401_1.0001.577_BUD
100401_1.0001.337/99.1_BUD	100401_1.0001.578_BUD
100401_1.0001.337/102.1_BUD	100401_1.0001.579_BUD
100401_1.0001.337/103.1_BUD	100401_1.0001.580_BUD
100401_1.0001.337/104.1_BUD	100401_1.0001.581_BUD
100401_1.0001.337/105.1_BUD	100401_1.0001.582_BUD
100401_1.0001.337/106.1_BUD	100401_1.0001.583_BUD
100401_1.0001.337/107.1_BUD	100401_1.0001.584_BUD
100401_1.0001.337/108.1_BUD	100401_1.0001.585_BUD
100401_1.0001.339/8.1_BUD	100401_1.0001.586_BUD
100401_1.0001.340/5.1_BUD	100401_1.0001.587_BUD
100401_1.0001.340/5.2_BUD	100401_1.0001.588_BUD
100401_1.0001.340/6.1_BUD	100401_1.0001.589_BUD
100401_1.0001.340/7.1_BUD	100401_1.0001.590_BUD
100401_1.0001.340/8.1_BUD	100401_1.0001.591_BUD
100401_1.0001.340/8.2_BUD	100401_1.0001.592_BUD
100401_1.0001.340/8.3_BUD	100401_1.0001.593_BUD

100401_1.0001.342.1_BUD	100401_1.0001.594_BUD
100401_1.0001.342.2_BUD	100401_1.0001.595_BUD
100401_1.0001.342.3_BUD	100401_1.0001.596_BUD
100401_1.0001.343.1_BUD	100401_1.0001.597_BUD
100401_1.0001.343.2_BUD	100401_1.0001.598_BUD
100401_1.0001.344.1_BUD	100401_1.0001.599_BUD
100401_1.0001.344.2_BUD	100401_1.0001.600_BUD
100401_1.0001.345.1_BUD	100401_1.0001.601_BUD
100401_1.0001.345.2_BUD	100401_1.0001.602_BUD
100401_1.0001.349.1_BUD	100401_1.0001.603_BUD
100401_1.0001.349.2_BUD	100401_1.0001.604_BUD
100401_1.0001.349.3_BUD	100401_1.0001.605_BUD
100401_1.0001.349.4_BUD	100401_1.0001.606_BUD
100401_1.0001.349.5_BUD	100401_1.0001.607_BUD
100401_1.0001.350.1_BUD	100401_1.0001.608_BUD
100401_1.0001.350.2_BUD	100401_1.0001.609_BUD
100401_1.0001.350.3_BUD	100401_1.0001.610_BUD
100401_1.0001.350.4_BUD	100401_1.0001.611_BUD
100401_1.0001.351/1.1_BUD	100401_1.0001.612_BUD
100401_1.0001.351/1.2_BUD	100401_1.0001.613_BUD
100401_1.0001.352/1.1_BUD	100401_1.0001.614_BUD
100401_1.0001.352/1.2_BUD	100401_1.0001.615_BUD
100401_1.0001.352/1.3_BUD	100401_1.0001.616_BUD
100401_1.0001.353/1.1_BUD	100401_1.0001.617_BUD
100401_1.0001.353/1.2_BUD	100401_1.0001.618_BUD
100401_1.0001.353/1.3_BUD	100401_1.0001.619_BUD
100401_1.0001.354/1.1_BUD	100401_1.0001.620_BUD
100401_1.0001.354/1.2_BUD	100401_1.0001.621_BUD
100401_1.0001.355/1.1_BUD	100401_1.0001.622_BUD
100401_1.0001.355/1.2_BUD	100401_1.0001.623_BUD
100401_1.0001.355/1.3_BUD	100401_1.0001.624_BUD
100401_1.0001.356/3.1_BUD	100401_1.0001.625_BUD
100401_1.0001.356/3.2_BUD	100401_1.0001.626_BUD
100401_1.0001.356/7.1_BUD	100401_1.0001.627_BUD
100401_1.0001.358.1_BUD	100401_1.0001.628_BUD
100401_1.0001.358.2_BUD	100401_1.0001.629_BUD
100401_1.0001.358.4_BUD	100401_1.0001.630_BUD
100401_1.0001.359/1.1_BUD	100401_1.0001.631_BUD
100401_1.0001.359/1.2_BUD	100401_1.0001.632_BUD
100401_1.0001.359/1.3_BUD	100401_1.0001.633_BUD
100401_1.0001.359/1.4_BUD	100401_1.0001.634_BUD
100401_1.0001.360.1_BUD	100401_1.0001.635_BUD
100401_1.0001.360.2_BUD	100401_1.0001.636_BUD
100401_1.0001.360.3_BUD	100401_1.0001.637_BUD
100401_1.0001.361.1_BUD	100401_1.0001.638_BUD
100401_1.0001.361.3_BUD	100401_1.0001.639_BUD
100401_1.0001.362.1_BUD	100401_1.0001.640_BUD
100401_1.0001.363.1_BUD	100401_1.0001.641_BUD
100401_1.0001.363.2_BUD	100401_1.0001.642_BUD
100401_1.0001.364.2_BUD	100401_1.0001.643_BUD
100401_1.0001.364/2.1_BUD	100401_1.0001.644_BUD
100401_1.0001.364/3.1_BUD	100401_1.0001.645_BUD
100401_1.0001.364/4.1_BUD	100401_1.0001.646_BUD
100401_1.0001.365/12.1_BUD	100401_1.0001.647_BUD

100401_1.0001.366/2.1_BUD	100401_1.0001.648_BUD
100401_1.0001.366/4.1_BUD	100401_1.0001.649_BUD
100401_1.0001.367.1_BUD	100401_1.0001.650_BUD
100401_1.0001.367.3_BUD	100401_1.0001.651_BUD
100401_1.0001.367.4_BUD	100401_1.0001.652_BUD
100401_1.0001.367.5_BUD	100401_1.0001.653_BUD
100401_1.0001.368.1_BUD	100401_1.0001.654_BUD
100401_1.0001.368.2_BUD	100401_1.0001.655_BUD
100401_1.0001.369/1.1_BUD	100401_1.0001.656_BUD
100401_1.0001.369/1.2_BUD	100401_1.0001.657_BUD
100401_1.0001.369/1.3_BUD	100401_1.0001.658_BUD
100401_1.0001.369/2.1_BUD	100401_1.0001.659_BUD
100401_1.0001.371/1.1_BUD	100401_1.0001.660_BUD
100401_1.0001.371/2.1_BUD	100401_1.0001.661_BUD
100401_1.0001.371/2.2_BUD	100401_1.0001.662_BUD
100401_1.0001.371/2.3_BUD	100401_1.0001.663_BUD
100401_1.0001.372.1_BUD	100401_1.0001.664_BUD
100401_1.0001.373.1_BUD	100401_1.0001.665_BUD
100401_1.0001.373.2_BUD	100401_1.0001.666_BUD
100401_1.0001.374.1_BUD	100401_1.0001.667_BUD
100401_1.0001.374.2_BUD	100401_1.0001.668_BUD
100401_1.0001.376.1_BUD	100401_1.0001.669_BUD
100401_1.0001.376.2_BUD	100401_1.0001.670_BUD
100401_1.0001.377.1_BUD	100401_1.0001.671_BUD
100401_1.0001.377.2_BUD	100401_1.0001.672_BUD
100401_1.0001.378.1_BUD	100401_1.0001.673_BUD
100401_1.0001.378.2_BUD	100401_1.0001.674_BUD
100401_1.0001.378.3_BUD	100401_1.0001.675_BUD
100401_1.0001.378.4_BUD	100401_1.0001.676_BUD
100401_1.0001.379.1_BUD	100401_1.0001.677_BUD
100401_1.0001.381.1_BUD	100401_1.0001.678_BUD
100401_1.0001.381.2_BUD	100401_1.0001.679_BUD
100401_1.0001.381.3_BUD	100401_1.0001.680_BUD
100401_1.0001.381.4_BUD	100401_1.0001.681_BUD
100401_1.0001.383/1.1_BUD	100401_1.0001.682_BUD
100401_1.0001.383/2.1_BUD	100401_1.0001.683_BUD
100401_1.0001.383/2.2_BUD	100401_1.0001.684_BUD
100401_1.0001.383/2.3_BUD	100401_1.0001.685_BUD
100401_1.0001.384.1_BUD	100401_1.0001.686_BUD
100401_1.0001.384.2_BUD	100401_1.0001.687_BUD
100401_1.0001.385.1_BUD	100401_1.0001.688_BUD
100401_1.0001.385.2_BUD	100401_1.0001.689_BUD
100401_1.0001.386/2.1_BUD	100401_1.0001.690_BUD
100401_1.0001.386/2.2_BUD	100401_1.0001.691_BUD
100401_1.0001.386/3.1_BUD	100401_1.0001.692_BUD
100401_1.0001.388/2.1_BUD	100401_1.0001.693_BUD
100401_1.0001.388/3.1_BUD	100401_1.0001.694_BUD
100401_1.0001.388/4.1_BUD	100401_1.0001.695_BUD
100401_1.0001.388/4.2_BUD	100401_1.0001.696_BUD
100401_1.0001.388/4.3_BUD	100401_1.0001.697_BUD
100401_1.0001.389/4.1_BUD	100401_1.0001.698_BUD
100401_1.0001.389/4.2_BUD	100401_1.0001.699_BUD
100401_1.0001.389/4.3_BUD	100401_1.0001.700_BUD
100401_1.0001.399/7.1_BUD	100401_1.0001.701_BUD

100401_1.0001.399/7.2_BUD	100401_1.0001.702_BUD
100401_1.0001.399/18.1_BUD	100401_1.0001.703_BUD
100401_1.0001.399/18.2_BUD	100401_1.0001.704_BUD
100401_1.0001.399/20.1_BUD	100401_1.0001.705_BUD
100401_1.0001.399/20.2_BUD	100401_1.0001.706_BUD
100401_1.0001.399/20.3_BUD	100401_1.0001.707_BUD
100401_1.0001.399/20.4_BUD	100401_1.0001.708_BUD
100401_1.0001.399/20.5_BUD	100401_1.0001.709_BUD
100401_1.0001.399/26.1_BUD	100401_1.0001.710_BUD
100401_1.0001.399/26.2_BUD	100401_1.0001.711_BUD
100401_1.0001.399/26.3_BUD	100401_1.0001.712_BUD
100401_1.0001.399/26.4_BUD	100401_1.0001.713_BUD
100401_1.0001.399/27.1_BUD	100401_1.0001.714_BUD
100401_1.0001.399/28.1_BUD	100401_1.0001.715_BUD
100401_1.0001.399/32.1_BUD	100401_1.0001.716_BUD
100401_1.0001.399/34.1_BUD	100401_1.0001.717_BUD
100401_1.0001.399/34.2_BUD	100401_1.0001.718_BUD
100401_1.0001.399/35.1_BUD	100401_1.0001.719_BUD
100401_1.0001.399/36.1_BUD	100401_1.0001.720_BUD
100401_1.0001.399/39.1_BUD	100401_1.0001.721_BUD
100401_1.0001.399/40.1_BUD	100401_1.0001.722_BUD
100401_1.0001.399/41.1_BUD	100401_1.0001.723_BUD
100401_1.0001.399/41.2_BUD	100401_1.0001.724_BUD
100401_1.0001.399/43.1_BUD	100401_1.0001.725_BUD
100401_1.0001.399/43.2_BUD	100401_1.0001.726_BUD
100401_1.0001.399/47.1_BUD	100401_1.0001.727_BUD
100401_1.0001.399/47.3_BUD	100401_1.0001.728_BUD
100401_1.0001.399/47.5_BUD	100401_1.0001.729_BUD
100401_1.0001.399/48.4_BUD	100401_1.0001.730_BUD
100401_1.0001.399/48.5_BUD	100401_1.0001.731_BUD
100401_1.0001.399/48.10_BUD	100401_1.0001.732_BUD
100401_1.0001.399/48.11_BUD	100401_1.0001.733_BUD
100401_1.0001.399/50.1_BUD	100401_1.0001.734_BUD
100401_1.0001.399/56.1_BUD	100401_1.0001.735_BUD
100401_1.0001.399/56.2_BUD	100401_1.0001.736_BUD
100401_1.0001.399/57.1_BUD	100401_1.0001.737_BUD
100401_1.0001.399/57.2_BUD	100401_1.0001.738_BUD
100401_1.0001.399/57.3_BUD	100401_1.0001.739_BUD
100401_1.0001.399/57.4_BUD	100401_1.0001.740_BUD
100401_1.0001.399/57.5_BUD	100401_1.0001.741_BUD
100401_1.0001.399/57.6_BUD	100401_1.0001.742_BUD
100401_1.0001.399/57.7_BUD	100401_1.0001.743_BUD
100401_1.0001.399/65.1_BUD	100401_1.0001.744_BUD
100401_1.0001.399/67.1_BUD	100401_1.0001.745_BUD
100401_1.0001.401.1_BUD	100401_1.0001.746_BUD
100401_1.0001.401.2_BUD	100401_1.0001.747_BUD
100401_1.0001.401.3_BUD	100401_1.0001.748_BUD
100401_1.0001.401.4_BUD	100401_1.0001.749_BUD
100401_1.0001.401.6_BUD	100401_1.0001.750_BUD
100401_1.0001.401.7_BUD	100401_1.0001.751_BUD
100401_1.0001.401.8_BUD	100401_1.0001.752_BUD
100401_1.0001.401.9_BUD	100401_1.0001.753_BUD
100401_1.0001.401.10_BUD	100401_1.0001.754_BUD
100401_1.0001.405.1_BUD	100401_1.0001.755_BUD

100401_1.0001.405.2_BUD	100401_1.0001.756_BUD
100401_1.0001.405.3_BUD	100401_1.0001.757_BUD
100401_1.0001.410.1_BUD	100401_1.0001.758_BUD
100401_1.0001.411.1_BUD	100401_1.0001.759_BUD
100401_1.0001.411.2_BUD	100401_1.0001.760_BUD
100401_1.0001.411.3_BUD	100401_1.0001.761_BUD
100401_1.0001.411.4_BUD	100401_1.0001.762_BUD
100401_1.0001.412.1_BUD	100401_1.0001.763_BUD
100401_1.0001.412.2_BUD	100401_1.0001.764_BUD
100401_1.0001.413.1_BUD	100401_1.0001.765_BUD
100401_1.0001.414.1_BUD	100401_1.0001.766_BUD
100401_1.0001.414.2_BUD	100401_1.0001.767_BUD
100401_1.0001.416.1_BUD	100401_1.0001.768_BUD
100401_1.0001.416.2_BUD	100401_1.0001.769_BUD
100401_1.0001.416.3_BUD	100401_1.0001.770_BUD
100401_1.0001.417.1_BUD	100401_1.0001.771_BUD
100401_1.0001.417.2_BUD	100401_1.0001.772_BUD
100401_1.0001.418.1_BUD	100401_1.0001.773_BUD
100401_1.0001.418.2_BUD	100401_1.0001.774_BUD
100401_1.0001.419.1_BUD	100401_1.0001.775_BUD
100401_1.0001.420.1_BUD	100401_1.0001.776_BUD
100401_1.0001.420.2_BUD	100401_1.0001.777_BUD
100401_1.0001.420.3_BUD	100401_1.0001.778_BUD
100401_1.0001.421.1_BUD	100401_1.0001.779_BUD
100401_1.0001.421.3_BUD	100401_1.0001.780_BUD
100401_1.0001.422/5.1_BUD	100401_1.0001.781_BUD
100401_1.0001.422/5.2_BUD	100401_1.0001.782_BUD
100401_1.0001.422/5.3_BUD	100401_1.0001.783_BUD
100401_1.0001.422/5.4_BUD	100401_1.0001.784_BUD
100401_1.0001.422/5.5_BUD	100401_1.0001.785_BUD
100401_1.0001.423/10.1_BUD	100401_1.0001.786_BUD
100401_1.0001.423/10.2_BUD	100401_1.0001.787_BUD
100401_1.0001.423/19.1_BUD	100401_1.0001.788_BUD
100401_1.0001.423/20.1_BUD	100401_1.0001.789_BUD
100401_1.0001.423/21.1_BUD	100401_1.0001.790_BUD
100401_1.0001.423/22.1_BUD	100401_1.0001.791_BUD
100401_1.0001.423/23.1_BUD	100401_1.0001.792_BUD
100401_1.0001.423/25.1_BUD	100401_1.0001.793_BUD
100401_1.0001.423/25.2_BUD	100401_1.0001.794_BUD
100401_1.0001.423/25.3_BUD	100401_1.0001.795_BUD
100401_1.0001.423/25.4_BUD	100401_1.0001.796_BUD
100401_1.0001.423/25.5_BUD	100401_1.0001.797_BUD
100401_1.0001.423/25.6_BUD	100401_1.0001.798_BUD
100401_1.0001.423/27.1_BUD	100401_1.0001.799_BUD
100401_1.0001.423/28.1_BUD	100401_1.0001.800_BUD
100401_1.0001.423/30.1_BUD	100401_1.0001.801_BUD
100401_1.0001.423/31.1_BUD	100401_1.0001.802_BUD
100401_1.0001.423/32.1_BUD	100401_1.0001.803_BUD
100401_1.0001.423/34.1_BUD	100401_1.0001.804_BUD
100401_1.0001.423/52.1_BUD	100401_1.0001.805_BUD
100401_1.0001.423/53.1_BUD	100401_1.0001.806_BUD
100401_1.0001.423/54.1_BUD	100401_1.0001.807_BUD
100401_1.0001.423/55.1_BUD	100401_1.0001.808_BUD
100401_1.0001.423/56.1_BUD	100401_1.0001.809_BUD

100401_1.0001.423/59.1_BUD	100401_1.0001.810_BUD
100401_1.0001.423/63.1_BUD	100401_1.0001.811_BUD
100401_1.0001.426/2.1_BUD	100401_1.0001.812_BUD
100401_1.0001.427/1.1_BUD	100401_1.0001.813_BUD
100401_1.0001.427/2.1_BUD	100401_1.0001.814_BUD
100401_1.0001.428.1_BUD	100401_1.0001.815_BUD
100401_1.0001.428.5_BUD	100401_1.0001.816_BUD
100401_1.0001.428.7_BUD	100401_1.0001.817_BUD
100401_1.0001.429.1_BUD	100401_1.0001.818_BUD
100401_1.0001.429.2_BUD	100401_1.0001.819_BUD
100401_1.0001.429.3_BUD	100401_1.0001.820_BUD
100401_1.0001.429.4_BUD	100401_1.0001.821_BUD
100401_1.0001.430/1.1_BUD	100401_1.0001.822_BUD
100401_1.0001.430/1.2_BUD	100401_1.0001.823_BUD
100401_1.0001.430/2.1_BUD	100401_1.0001.824_BUD
100401_1.0001.431.1_BUD	100401_1.0001.825_BUD
100401_1.0001.431.2_BUD	100401_1.0001.826_BUD
100401_1.0001.431.3_BUD	100401_1.0001.827_BUD
100401_1.0001.431.4_BUD	100401_1.0001.828_BUD
100401_1.0001.432.1_BUD	100401_1.0001.829_BUD
100401_1.0001.432.2_BUD	100401_1.0001.830_BUD
100401_1.0001.432.3_BUD	100401_1.0001.831_BUD
100401_1.0001.432.4_BUD	100401_1.0001.832_BUD
100401_1.0001.433.1_BUD	100401_1.0001.833_BUD
100401_1.0001.434.5_BUD	100401_1.0001.834_BUD
100401_1.0001.435/2.1_BUD	100401_1.0001.835_BUD
100401_1.0001.435/2.2_BUD	100401_1.0001.836_BUD
100401_1.0001.435/2.3_BUD	100401_1.0001.837_BUD
100401_1.0001.435/2.4_BUD	100401_1.0001.838_BUD
100401_1.0001.435/2.5_BUD	100401_1.0001.839_BUD
100401_1.0001.435/2.6_BUD	100401_1.0001.840_BUD
100401_1.0001.435/3.1_BUD	100401_1.0001.841_BUD
100401_1.0001.435/3.2_BUD	100401_1.0001.842_BUD
100401_1.0001.435/3.3_BUD	100401_1.0001.843_BUD
100401_1.0001.435/3.4_BUD	100401_1.0001.844_BUD
100401_1.0001.435/3.5_BUD	100401_1.0001.845_BUD
100401_1.0001.438/9.1_BUD	100401_1.0001.846_BUD
100401_1.0001.439/3.1_BUD	100401_1.0001.847_BUD
100401_1.0001.439/5.1_BUD	100401_1.0001.848_BUD
100401_1.0001.439/6.1_BUD	100401_1.0001.849_BUD
100401_1.0001.439/7.1_BUD	100401_1.0001.850_BUD
100401_1.0001.439/10.1_BUD	100401_1.0001.851_BUD
100401_1.0001.439/14.1_BUD	100401_1.0001.852_BUD
100401_1.0001.440.1_BUD	100401_1.0001.853_BUD
100401_1.0001.440.2_BUD	100401_1.0001.854_BUD
100401_1.0001.440.3_BUD	100401_1.0001.855_BUD
100401_1.0001.440.4_BUD	100401_1.0001.856_BUD
100401_1.0001.441.1_BUD	100401_1.0001.857_BUD
100401_1.0001.441.2_BUD	100401_1.0001.858_BUD
100401_1.0001.442.1_BUD	100401_1.0001.859_BUD
100401_1.0001.442.2_BUD	100401_1.0001.860_BUD
100401_1.0001.442.3_BUD	100401_1.0001.861_BUD
100401_1.0001.443.1_BUD	100401_1.0001.862_BUD
100401_1.0001.443.2_BUD	100401_1.0001.863_BUD

100401_1.0001.444.1_BUD	100401_1.0001.864_BUD
100401_1.0001.444.2_BUD	100401_1.0001.865_BUD
100401_1.0001.444.3_BUD	100401_1.0001.866_BUD
100401_1.0001.444.4_BUD	100401_1.0001.867_BUD
100401_1.0001.446/3.1_BUD	100401_1.0001.868_BUD
100401_1.0001.446/3.2_BUD	100401_1.0001.869_BUD
100401_1.0001.446/3.3_BUD	100401_1.0001.870_BUD
100401_1.0001.446/4.1_BUD	100401_1.0001.871_BUD
100401_1.0001.446/4.2_BUD	100401_1.0001.872_BUD
100401_1.0001.447/1.1_BUD	100401_1.0001.873_BUD
100401_1.0001.447/1.2_BUD	100401_1.0001.874_BUD
100401_1.0001.447/1.3_BUD	100401_1.0001.875_BUD
100401_1.0001.447/4.1_BUD	100401_1.0001.876_BUD
100401_1.0001.447/4.7_BUD	100401_1.0001.877_BUD
100401_1.0001.447/4.8_BUD	100401_1.0001.878_BUD
100401_1.0001.447/6.3_BUD	100401_1.0001.879_BUD
100401_1.0001.447/6.5_BUD	100401_1.0001.880_BUD
100401_1.0001.447/6.6_BUD	100401_1.0001.881_BUD
100401_1.0001.449.1_BUD	100401_1.0001.882_BUD
100401_1.0001.449.4_BUD	100401_1.0001.883_BUD
100401_1.0001.449.6_BUD	100401_1.0001.884_BUD
100401_1.0001.449.7_BUD	100401_1.0001.885_BUD
100401_1.0001.449.8_BUD	100401_1.0001.886_BUD
100401_1.0001.449.9_BUD	100401_1.0001.887_BUD
100401_1.0001.451/1.1_BUD	100401_1.0001.888_BUD
100401_1.0001.451/1.2_BUD	100401_1.0001.889_BUD
100401_1.0001.451/4.1_BUD	100401_1.0001.890_BUD
100401_1.0001.451/5.1_BUD	100401_1.0001.891_BUD
100401_1.0001.451/5.2_BUD	100401_1.0001.892_BUD
100401_1.0001.452/1.1_BUD	100401_1.0001.893_BUD
100401_1.0001.452/1.2_BUD	100401_1.0001.894_BUD
100401_1.0001.452/1.3_BUD	100401_1.0001.895_BUD
100401_1.0001.452/2.1_BUD	100401_1.0001.896_BUD
100401_1.0001.452/2.2_BUD	100401_1.0001.897_BUD
100401_1.0001.452/2.3_BUD	100401_1.0001.898_BUD
100401_1.0001.452/2.4_BUD	100401_1.0001.899_BUD
100401_1.0001.453.1_BUD	100401_1.0001.900_BUD
100401_1.0001.453.2_BUD	100401_1.0001.901_BUD
100401_1.0001.453.4_BUD	100401_1.0001.902_BUD
100401_1.0001.454.1_BUD	100401_1.0001.903_BUD
100401_1.0001.454.2_BUD	100401_1.0001.904_BUD
100401_1.0001.454.3_BUD	100401_1.0001.905_BUD
100401_1.0001.454/2.1_BUD	100401_1.0001.906_BUD
100401_1.0001.455.1_BUD	100401_1.0001.907_BUD
100401_1.0001.455.3_BUD	100401_1.0001.908_BUD
100401_1.0001.455.4_BUD	100401_1.0001.909_BUD
100401_1.0001.455.5_BUD	100401_1.0001.910_BUD
100401_1.0001.455.6_BUD	100401_1.0001.911_BUD
100401_1.0001.455.7_BUD	100401_1.0001.912_BUD
100401_1.0001.455.8_BUD	100401_1.0001.913_BUD
100401_1.0001.456/1.1_BUD	100401_1.0001.914_BUD
100401_1.0001.456/2.1_BUD	100401_1.0001.915_BUD
100401_1.0001.456/4.1_BUD	100401_1.0001.916_BUD
100401_1.0001.456/4.2_BUD	100401_1.0001.917_BUD

100401_1.0001.456/6.1_BUD	100401_1.0001.918_BUD
100401_1.0001.456/7.1_BUD	100401_1.0001.919_BUD
100401_1.0001.456/10.1_BUD	100401_1.0001.920_BUD
100401_1.0001.457.1_BUD	100401_1.0001.921_BUD
100401_1.0001.457.2_BUD	100401_1.0001.922_BUD
100401_1.0001.458/1.1_BUD	100401_1.0001.923_BUD
100401_1.0001.458/1.2_BUD	100401_1.0001.924_BUD
100401_1.0001.459/1.1_BUD	100401_1.0001.925_BUD
100401_1.0001.459/2.1_BUD	100401_1.0001.926_BUD
100401_1.0001.459/2.2_BUD	100401_1.0001.927_BUD
100401_1.0001.459/2.3_BUD	100401_1.0001.928_BUD
100401_1.0001.460/2.1_BUD	100401_1.0001.929_BUD
100401_1.0001.460/4.1_BUD	100401_1.0001.930_BUD
100401_1.0001.460/4.3_BUD	100401_1.0001.931_BUD
100401_1.0001.460/4.4_BUD	100401_1.0001.932_BUD
100401_1.0001.460/4.5_BUD	100401_1.0001.933_BUD
100401_1.0001.460/4.6_BUD	100401_1.0001.934_BUD
100401_1.0001.460/4.8_BUD	100401_1.0001.935_BUD
100401_1.0001.461.1_BUD	100401_1.0001.936_BUD
100401_1.0001.461.2_BUD	100401_1.0001.937_BUD
100401_1.0001.463.1_BUD	100401_1.0001.938_BUD
100401_1.0001.463.2_BUD	100401_1.0001.939_BUD
100401_1.0001.463.3_BUD	100401_1.0001.940_BUD
100401_1.0001.463.4_BUD	100401_1.0001.941_BUD
100401_1.0001.464/1.1_BUD	100401_1.0001.942_BUD
100401_1.0001.464/2.1_BUD	100401_1.0001.943_BUD
100401_1.0001.466/1.1_BUD	100401_1.0001.944_BUD
100401_1.0001.466/1.2_BUD	100401_1.0001.945_BUD
100401_1.0001.466/1.3_BUD	100401_1.0001.946_BUD
100401_1.0001.466/3.1_BUD	100401_1.0001.947_BUD
100401_1.0001.466/3.2_BUD	100401_1.0001.948_BUD
100401_1.0001.469.7_BUD	100401_1.0001.949_BUD
100401_1.0001.470/3.1_BUD	100401_1.0001.950_BUD
100401_1.0001.470/5.1_BUD	100401_1.0001.951_BUD
100401_1.0001.470/5.2_BUD	100401_1.0001.952_BUD
100401_1.0001.470/5.3_BUD	100401_1.0001.953_BUD
100401_1.0001.472.3_BUD	100401_1.0001.954_BUD
100401_1.0001.472.4_BUD	100401_1.0001.955_BUD
100401_1.0001.473/1.1_BUD	100401_1.0001.956_BUD
100401_1.0001.473/1.2_BUD	100401_1.0001.957_BUD
100401_1.0001.473/1.3_BUD	100401_1.0001.958_BUD
100401_1.0001.474/1.1_BUD	100401_1.0001.959_BUD
100401_1.0001.474/1.2_BUD	100401_1.0001.960_BUD
100401_1.0001.474/1.3_BUD	100401_1.0001.961_BUD
100401_1.0001.474/1.4_BUD	100401_1.0001.962_BUD
100401_1.0001.474/1.5_BUD	100401_1.0001.963_BUD
100401_1.0001.474/2.1_BUD	100401_1.0001.964_BUD
100401_1.0001.474/2.2_BUD	100401_1.0001.965_BUD
100401_1.0001.474/2.3_BUD	100401_1.0001.966_BUD
100401_1.0001.475.1_BUD	100401_1.0001.967_BUD
100401_1.0001.475.2_BUD	100401_1.0001.968_BUD
100401_1.0001.476/1.1_BUD	100401_1.0001.969_BUD
100401_1.0001.476/2.1_BUD	100401_1.0001.970_BUD
100401_1.0001.476/4.1_BUD	100401_1.0001.971_BUD

100401_1.0001.477.1_BUD	100401_1.0001.972_BUD
100401_1.0001.477.2_BUD	100401_1.0001.973_BUD
100401_1.0001.477.4_BUD	100401_1.0001.974_BUD
100401_1.0001.477.5_BUD	100401_1.0001.975_BUD
100401_1.0001.477.6_BUD	100401_1.0001.976_BUD
100401_1.0001.478.1_BUD	100401_1.0001.977_BUD
100401_1.0001.478.2_BUD	100401_1.0001.978_BUD
100401_1.0001.478.3_BUD	100401_1.0001.979_BUD
100401_1.0001.479.1_BUD	100401_1.0001.980_BUD
100401_1.0001.479.2_BUD	100401_1.0001.981_BUD
100401_1.0001.479.3_BUD	100401_1.0001.982_BUD
100401_1.0001.480/1.1_BUD	100401_1.0001.983_BUD
100401_1.0001.480/3.1_BUD	100401_1.0001.984_BUD
100401_1.0001.480/15.1_BUD	100401_1.0001.985_BUD
100401_1.0001.480/18.1_BUD	100401_1.0001.986_BUD
100401_1.0001.480/21.1_BUD	100401_1.0001.987_BUD
100401_1.0001.481/2.1_BUD	100401_1.0001.988_BUD
100401_1.0001.481/4.1_BUD	100401_1.0001.989_BUD
100401_1.0001.481/5.1_BUD	100401_1.0001.990_BUD
100401_1.0001.481/15.1_BUD	100401_1.0001.991_BUD
100401_1.0001.483/1.1_BUD	100401_1.0001.992_BUD
100401_1.0001.483/1.2_BUD	100401_1.0001.993_BUD
100401_1.0001.483/3.1_BUD	100401_1.0001.994_BUD
100401_1.0001.483/3.2_BUD	100401_1.0001.995_BUD
100401_1.0001.483/3.3_BUD	100401_1.0001.996_BUD
100401_1.0001.483/4.1_BUD	100401_1.0001.997_BUD
100401_1.0001.483/4.2_BUD	100401_1.0001.998_BUD
100401_1.0001.484/1.1_BUD	100401_1.0001.999_BUD
100401_1.0001.484/1.2_BUD	100401_1.0001.1000_BUD
100401_1.0001.484/1.3_BUD	100401_1.0001.1001_BUD
100401_1.0001.484/2.1_BUD	100401_1.0001.1002_BUD
100401_1.0001.486/2.1_BUD	100401_1.0001.1003_BUD
100401_1.0001.486/2.2_BUD	100401_1.0001.1004_BUD
100401_1.0001.486/2.3_BUD	100401_1.0001.1005_BUD
100401_1.0001.488.2_BUD	100401_1.0001.1006_BUD
100401_1.0001.488.3_BUD	100401_1.0001.1007_BUD
100401_1.0001.488.4_BUD	100401_1.0001.1008_BUD
100401_1.0001.488.5_BUD	100401_1.0001.1009_BUD
100401_1.0001.488.6_BUD	100401_1.0001.1010_BUD
100401_1.0001.489.1_BUD	100401_1.0001.1011_BUD
100401_1.0001.489.2_BUD	100401_1.0001.1012_BUD
100401_1.0001.489.3_BUD	100401_1.0001.1013_BUD
100401_1.0001.489.4_BUD	100401_1.0001.1014_BUD
100401_1.0001.489.5_BUD	100401_1.0001.1015_BUD
100401_1.0001.489.6_BUD	100401_1.0001.1016_BUD
100401_1.0001.490/2.1_BUD	100401_1.0001.1017_BUD
100401_1.0001.490/3.1_BUD	100401_1.0001.1018_BUD
100401_1.0001.490/3.2_BUD	100401_1.0001.1019_BUD
100401_1.0001.491/2.1_BUD	100401_1.0001.1020_BUD
100401_1.0001.491/2.2_BUD	100401_1.0001.1021_BUD
100401_1.0001.494.1_BUD	100401_1.0001.1022_BUD
100401_1.0001.495.1_BUD	100401_1.0001.1023_BUD
100401_1.0001.495.2_BUD	100401_1.0001.1024_BUD
100401_1.0001.497.1_BUD	100401_1.0001.1025_BUD

100401_1.0001.497.2_BUD	100401_1.0001.1026_BUD
100401_1.0001.498/1.1_BUD	100401_1.0001.1027_BUD
100401_1.0001.499.1_BUD	100401_1.0001.1028_BUD
100401_1.0001.499.2_BUD	100401_1.0001.1029_BUD
100401_1.0001.499.3_BUD	100401_1.0001.1030_BUD
100401_1.0001.499.4_BUD	100401_1.0001.1031_BUD
100401_1.0001.500/1.1_BUD	100401_1.0001.1032_BUD
100401_1.0001.500/3.1_BUD	100401_1.0001.1033_BUD
100401_1.0001.500/4.1_BUD	100401_1.0001.1034_BUD
100401_1.0001.501/2.1_BUD	100401_1.0001.1035_BUD
100401_1.0001.501/2.2_BUD	100401_1.0001.1036_BUD
100401_1.0001.502/1.1_BUD	100401_1.0001.1037_BUD
100401_1.0001.502/1.2_BUD	100401_1.0001.1038_BUD
100401_1.0001.502/2.1_BUD	100401_1.0001.1039_BUD
100401_1.0001.502/2.2_BUD	100401_1.0001.1040_BUD
100401_1.0001.502/2.3_BUD	100401_1.0001.1041_BUD
100401_1.0001.503/2.1_BUD	100401_1.0001.1042_BUD
100401_1.0001.505/1.1_BUD	100401_1.0001.1043_BUD
100401_1.0001.505/6.1_BUD	100401_1.0001.1044_BUD
100401_1.0001.505/7.1_BUD	100401_1.0001.1045_BUD
100401_1.0001.505/7.2_BUD	100401_1.0001.1046_BUD
100401_1.0001.505/7.3_BUD	100401_1.0001.1047_BUD
100401_1.0001.505/7.4_BUD	100401_1.0001.1048_BUD
100401_1.0001.505/8.1_BUD	100401_1.0001.1049_BUD
100401_1.0001.506.1_BUD	100401_1.0001.1050_BUD
100401_1.0001.507/1.1_BUD	100401_1.0001.1051_BUD
100401_1.0001.507/2.1_BUD	100401_1.0001.1052_BUD
100401_1.0001.508.2_BUD	100401_1.0001.1053_BUD
100401_1.0001.508.3_BUD	100401_1.0001.1054_BUD
100401_1.0001.508.4_BUD	100401_1.0001.1055_BUD
100401_1.0001.511/2.1_BUD	100401_1.0001.1056_BUD
100401_1.0001.511/2.2_BUD	100401_1.0001.1057_BUD
100401_1.0001.511/2.3_BUD	100401_1.0001.1058_BUD
100401_1.0001.511/2.4_BUD	100401_1.0001.1059_BUD
100401_1.0001.513/2.1_BUD	100401_1.0001.1060_BUD
100401_1.0001.513/6.1_BUD	100401_1.0001.1061_BUD
100401_1.0001.515.1_BUD	100401_1.0001.1062_BUD
100401_1.0001.515.2_BUD	100401_1.0001.1063_BUD
100401_1.0001.517/2.1_BUD	100401_1.0001.1064_BUD
100401_1.0001.520/1.1_BUD	100401_1.0001.1065_BUD
100401_1.0001.520/1.2_BUD	100401_1.0001.1066_BUD
100401_1.0001.520/3.1_BUD	100401_1.0001.1067_BUD
100401_1.0001.521.1_BUD	100401_1.0001.1068_BUD
100401_1.0001.521.2_BUD	100401_1.0001.1069_BUD
100401_1.0001.522/1.1_BUD	100401_1.0001.1070_BUD
100401_1.0001.522/3.1_BUD	100401_1.0001.1071_BUD
100401_1.0001.522/7.1_BUD	100401_1.0001.1072_BUD
100401_1.0001.522/9.1_BUD	100401_1.0001.1073_BUD
100401_1.0001.522/11.1_BUD	100401_1.0001.1074_BUD
100401_1.0001.522/14.1_BUD	100401_1.0001.1075_BUD
100401_1.0001.522/15.1_BUD	100401_1.0001.1076_BUD
100401_1.0001.522/16.1_BUD	100401_1.0001.1077_BUD
100401_1.0001.523/1.1_BUD	100401_1.0001.1078_BUD
100401_1.0001.523/1.2_BUD	100401_1.0001.1079_BUD

100401_1.0001.523/1.3_BUD	100401_1.0001.1080_BUD
100401_1.0001.523/1.5_BUD	100401_1.0001.1081_BUD
100401_1.0001.524.1_BUD	100401_1.0001.1082_BUD
100401_1.0001.524.2_BUD	100401_1.0001.1083_BUD
100401_1.0001.525.1_BUD	100401_1.0001.1084_BUD
100401_1.0001.526.6_BUD	100401_1.0001.1085_BUD
100401_1.0001.527.1_BUD	100401_1.0001.1086_BUD
100401_1.0001.527.3_BUD	100401_1.0001.1087_BUD
100401_1.0001.528.1_BUD	100401_1.0001.1088_BUD
100401_1.0001.528.2_BUD	100401_1.0001.1089_BUD
100401_1.0001.528.3_BUD	100401_1.0001.1090_BUD
100401_1.0001.529.1_BUD	100401_1.0001.1091_BUD
100401_1.0001.530.1_BUD	100401_1.0001.1092_BUD
100401_1.0001.531.1_BUD	100401_1.0001.1093_BUD
100401_1.0001.531.2_BUD	100401_1.0001.1094_BUD
100401_1.0001.532.1_BUD	100401_1.0001.1095_BUD
100401_1.0001.532.2_BUD	100401_1.0001.1096_BUD
100401_1.0001.533/1.1_BUD	100401_1.0001.1097_BUD
100401_1.0001.533/2.1_BUD	100401_1.0001.1098_BUD
100401_1.0001.533/2.2_BUD	100401_1.0001.1099_BUD
100401_1.0001.534.1_BUD	100401_1.0001.1100_BUD
100401_1.0001.535.1_BUD	100401_1.0001.1101_BUD
100401_1.0001.535.2_BUD	100401_1.0001.1102_BUD
100401_1.0001.536.1_BUD	100401_1.0001.1103_BUD
100401_1.0001.536.2_BUD	100401_1.0001.1104_BUD
100401_1.0001.536.3_BUD	100401_1.0001.1105_BUD
100401_1.0001.537.1_BUD	100401_1.0001.1106_BUD
100401_1.0001.539/3.1_BUD	100401_1.0001.1107_BUD
100401_1.0001.539/4.1_BUD	100401_1.0001.1108_BUD
100401_1.0001.539/5.1_BUD	100401_1.0001.1109_BUD
100401_1.0001.540/6.1_BUD	100401_1.0001.1110_BUD
100401_1.0001.540/7.1_BUD	100401_1.0001.1111_BUD
100401_1.0001.541.1_BUD	100401_1.0001.1112_BUD
100401_1.0001.541.2_BUD	100401_1.0001.1113_BUD
100401_1.0001.541.3_BUD	100401_1.0001.1114_BUD
100401_1.0001.541.4_BUD	100401_1.0001.1115_BUD
100401_1.0001.541.5_BUD	100401_1.0001.1116_BUD
100401_1.0001.541.6_BUD	100401_1.0001.1117_BUD
100401_1.0001.541.7_BUD	100401_1.0001.1118_BUD
100401_1.0001.542/1.1_BUD	100401_1.0001.1119_BUD
100401_1.0001.542/1.2_BUD	100401_1.0001.1120_BUD
100401_1.0001.542/1.3_BUD	100401_1.0001.1121_BUD
100401_1.0001.542/1.4_BUD	100401_1.0001.1122_BUD
100401_1.0001.542/2.1_BUD	100401_1.0001.1123_BUD
100401_1.0001.542/2.2_BUD	100401_1.0001.1124_BUD
100401_1.0001.542/2.3_BUD	100401_1.0001.1125_BUD
100401_1.0001.543/1.1_BUD	100401_1.0001.1126_BUD
100401_1.0001.543/1.2_BUD	100401_1.0001.1127_BUD
100401_1.0001.543/1.3_BUD	100401_1.0001.1128_BUD
100401_1.0001.545.1_BUD	100401_1.0001.1129_BUD
100401_1.0001.545.2_BUD	100401_1.0001.1130_BUD
100401_1.0001.545.3_BUD	100401_1.0001.1131_BUD
100401_1.0001.545.4_BUD	100401_1.0001.1132_BUD
100401_1.0001.545.5_BUD	100401_1.0001.1133_BUD

100401_1.0001.545.6_BUD	100401_1.0001.1134_BUD
100401_1.0001.545.7_BUD	100401_1.0001.1135_BUD
100401_1.0001.546/2.1_BUD	100401_1.0001.1136_BUD
100401_1.0001.546/4.1_BUD	100401_1.0001.1137_BUD
100401_1.0001.546/12.1_BUD	100401_1.0001.1138_BUD
100401_1.0001.546/13.1_BUD	100401_1.0001.1139_BUD
100401_1.0001.546/13.2_BUD	100401_1.0001.1140_BUD
100401_1.0001.546/14.1_BUD	100401_1.0001.1141_BUD
100401_1.0001.546/14.2_BUD	100401_1.0001.1142_BUD
100401_1.0001.546/14.3_BUD	100401_1.0001.1143_BUD
100401_1.0001.546/14.4_BUD	100401_1.0001.1144_BUD
100401_1.0001.546/15.1_BUD	100401_1.0001.1145_BUD
100401_1.0001.546/16.1_BUD	100401_1.0001.1146_BUD
100401_1.0001.546/17.1_BUD	100401_1.0001.1147_BUD
100401_1.0001.546/21.1_BUD	100401_1.0001.1148_BUD
100401_1.0001.547.1_BUD	100401_1.0001.1149_BUD
100401_1.0001.548/1.1_BUD	100401_1.0001.1150_BUD
100401_1.0001.548/3.1_BUD	100401_1.0001.1151_BUD
100401_1.0001.548/4.1_BUD	100401_1.0001.1152_BUD
100401_1.0001.550/2.1_BUD	100401_1.0001.1153_BUD
100401_1.0001.550/2.2_BUD	100401_1.0001.1154_BUD
100401_1.0001.550/6.1_BUD	100401_1.0001.1155_BUD
100401_1.0001.550/7.1_BUD	100401_1.0001.1156_BUD
100401_1.0001.550/9.1_BUD	100401_1.0001.1157_BUD
100401_1.0001.551.1_BUD	100401_1.0001.1158_BUD
100401_1.0001.551.2_BUD	100401_1.0001.1159_BUD
100401_1.0001.553/2.1_BUD	100401_1.0001.1160_BUD
100401_1.0001.553/7.1_BUD	100401_1.0001.1161_BUD
100401_1.0001.556/5.1_BUD	100401_1.0001.1162_BUD
100401_1.0001.556/7.1_BUD	100401_1.0001.1163_BUD
100401_1.0001.556/7.2_BUD	100401_1.0001.1164_BUD
100401_1.0001.559/1.1_BUD	100401_1.0001.1165_BUD
100401_1.0001.559/5.1_BUD	100401_1.0001.1166_BUD
100401_1.0001.559/5.2_BUD	100401_1.0001.1167_BUD
100401_1.0001.559/6.1_BUD	100401_1.0001.1168_BUD
100401_1.0001.559/10.1_BUD	100401_1.0001.1169_BUD
100401_1.0001.559/10.2_BUD	100401_1.0001.1170_BUD
100401_1.0001.559/12.1_BUD	100401_1.0001.1171_BUD
100401_1.0001.559/13.1_BUD	100401_1.0001.1172_BUD
100401_1.0001.559/14.1_BUD	100401_1.0001.1173_BUD
100401_1.0001.559/14.2_BUD	100401_1.0001.1174_BUD
100401_1.0001.560/5.1_BUD	100401_1.0001.1175_BUD
100401_1.0001.560/6.1_BUD	100401_1.0001.1176_BUD
100401_1.0001.560/7.1_BUD	100401_1.0001.1177_BUD
100401_1.0001.560/8.1_BUD	100401_1.0001.1178_BUD
100401_1.0001.560/9.1_BUD	100401_1.0001.1179_BUD
100401_1.0001.560/10.1_BUD	100401_1.0001.1180_BUD
100401_1.0001.560/11.1_BUD	100401_1.0001.1181_BUD
100401_1.0001.560/12.1_BUD	100401_1.0001.1182_BUD
100401_1.0001.560/13.1_BUD	100401_1.0001.1183_BUD
100401_1.0001.560/14.1_BUD	100401_1.0001.1184_BUD
100401_1.0001.560/15.1_BUD	100401_1.0001.1185_BUD
100401_1.0001.560/16.1_BUD	100401_1.0001.1186_BUD
100401_1.0001.560/17.1_BUD	100401_1.0001.1187_BUD

100401_1.0001.560/18.1_BUD	100401_1.0001.1188_BUD
100401_1.0001.560/19.1_BUD	100401_1.0001.1189_BUD
100401_1.0001.560/20.1_BUD	100401_1.0001.1190_BUD
100401_1.0001.560/21.1_BUD	100401_1.0001.1191_BUD
100401_1.0001.560/22.1_BUD	100401_1.0001.1192_BUD
100401_1.0001.560/23.1_BUD	100401_1.0001.1193_BUD
100401_1.0001.560/24.1_BUD	100401_1.0001.1194_BUD
100401_1.0001.560/25.1_BUD	100401_1.0001.1195_BUD
100401_1.0001.560/27.1_BUD	100401_1.0001.1196_BUD
100401_1.0001.560/27.2_BUD	100401_1.0001.1197_BUD
100401_1.0001.560/27.3_BUD	100401_1.0001.1198_BUD
100401_1.0001.560/27.4_BUD	100401_1.0001.1199_BUD
100401_1.0001.560/27.5_BUD	100401_1.0001.1200_BUD
100401_1.0001.560/27.6_BUD	100401_1.0001.1201_BUD
100401_1.0001.560/27.7_BUD	100401_1.0001.1202_BUD
100401_1.0001.560/27.8_BUD	100401_1.0001.1203_BUD
100401_1.0001.560/27.9_BUD	100401_1.0001.1204_BUD
100401_1.0001.560/27.10_BUD	100401_1.0001.1205_BUD
100401_1.0001.560/27.11_BUD	100401_1.0001.1206_BUD
100401_1.0001.560/27.12_BUD	100401_1.0001.1207_BUD
100401_1.0001.560/27.13_BUD	100401_1.0001.1208_BUD
100401_1.0001.560/28.1_BUD	100401_1.0001.1209_BUD
100401_1.0001.560/28.2_BUD	100401_1.0001.1210_BUD
100401_1.0001.560/32.1_BUD	100401_1.0001.1211_BUD
100401_1.0001.560/35.1_BUD	100401_1.0001.1212_BUD
100401_1.0001.560/35.2_BUD	100401_1.0001.1213_BUD
100401_1.0001.561/1.1_BUD	100401_1.0001.1214_BUD
100401_1.0001.561/1.2_BUD	100401_1.0001.1215_BUD
100401_1.0001.561/1.3_BUD	100401_1.0001.1216_BUD
100401_1.0001.561/1.4_BUD	100401_1.0001.1217_BUD
100401_1.0001.561/1.5_BUD	100401_1.0001.1218_BUD
100401_1.0001.561/1.6_BUD	100401_1.0001.1219_BUD
100401_1.0001.563/2.1_BUD	100401_1.0001.1220_BUD
100401_1.0001.563/3.1_BUD	100401_1.0001.1221_BUD
100401_1.0001.563/4.1_BUD	100401_1.0001.1222_BUD
100401_1.0001.563/5.1_BUD	100401_1.0001.1223_BUD
100401_1.0001.563/5.2_BUD	100401_1.0001.1224_BUD
100401_1.0001.565/1.1_BUD	100401_1.0001.1225_BUD
100401_1.0001.565/1.2_BUD	100401_1.0001.1226_BUD
100401_1.0001.567/2.1_BUD	100401_1.0001.1227_BUD
100401_1.0001.567/2.2_BUD	100401_1.0001.1228_BUD
100401_1.0001.567/2.3_BUD	100401_1.0001.1229_BUD
100401_1.0001.567/2.4_BUD	100401_1.0001.1230_BUD
100401_1.0001.567/2.5_BUD	100401_1.0001.1231_BUD
100401_1.0001.567/2.6_BUD	100401_1.0001.1232_BUD
100401_1.0001.567/3.1_BUD	100401_1.0001.1233_BUD
100401_1.0001.572.1_BUD	100401_1.0001.1234_BUD
100401_1.0001.572.2_BUD	100401_1.0001.1235_BUD
100401_1.0001.572.3_BUD	100401_1.0001.1236_BUD
100401_1.0001.572.4_BUD	100401_1.0001.1237_BUD
100401_1.0001.572.5_BUD	100401_1.0001.1238_BUD
100401_1.0001.572.6_BUD	100401_1.0001.1239_BUD
100401_1.0001.572.7_BUD	100401_1.0001.1240_BUD
100401_1.0001.576/7.1_BUD	100401_1.0001.1241_BUD

100401_1.0001.578/1.1_BUD	100401_1.0001.1242_BUD
100401_1.0001.578/2.1_BUD	100401_1.0001.1243_BUD
100401_1.0001.578/4.1_BUD	100401_1.0001.1244_BUD
100401_1.0001.578/6.1_BUD	100401_1.0001.1245_BUD
100401_1.0001.578/9.1_BUD	100401_1.0001.1246_BUD
100401_1.0001.578/10.1_BUD	100401_1.0001.1247_BUD
100401_1.0001.578/11.1_BUD	100401_1.0001.1248_BUD
100401_1.0001.578/13.1_BUD	100401_1.0001.1249_BUD
100401_1.0001.578/15.1_BUD	100401_1.0001.1250_BUD
100401_1.0001.578/17.1_BUD	100401_1.0001.1251_BUD
100401_1.0001.578/18.1_BUD	100401_1.0001.1252_BUD
100401_1.0001.578/20.1_BUD	100401_1.0001.1253_BUD
100401_1.0001.578/21.1_BUD	100401_1.0001.1254_BUD
100401_1.0001.578/23.1_BUD	100401_1.0001.1255_BUD
100401_1.0001.578/25.1_BUD	100401_1.0001.1256_BUD
100401_1.0001.578/27.1_BUD	100401_1.0001.1257_BUD
100401_1.0001.578/28.1_BUD	100401_1.0001.1258_BUD
100401_1.0001.578/29.1_BUD	100401_1.0001.1259_BUD
100401_1.0001.578/32.1_BUD	100401_1.0001.1260_BUD
100401_1.0001.578/33.1_BUD	100401_1.0001.1261_BUD
100401_1.0001.579.1_BUD	100401_1.0001.1262_BUD
100401_1.0001.579.2_BUD	100401_1.0001.1263_BUD
100401_1.0001.579.3_BUD	100401_1.0001.1264_BUD
100401_1.0001.579.4_BUD	100401_1.0001.1265_BUD
100401_1.0001.579.5_BUD	100401_1.0001.1266_BUD
100401_1.0001.580/2.1_BUD	100401_1.0001.1267_BUD
100401_1.0001.580/3.1_BUD	100401_1.0001.1268_BUD
100401_1.0001.580/4.1_BUD	100401_1.0001.1269_BUD
100401_1.0001.580/5.1_BUD	100401_1.0001.1270_BUD
100401_1.0001.580/6.1_BUD	100401_1.0001.1271_BUD
100401_1.0001.580/7.1_BUD	100401_1.0001.1272_BUD
100401_1.0001.580/8.1_BUD	100401_1.0001.1273_BUD
100401_1.0001.580/9.1_BUD	100401_1.0001.1274_BUD
100401_1.0001.580/10.1_BUD	100401_1.0001.1275_BUD
100401_1.0001.580/11.1_BUD	100401_1.0001.1276_BUD
100401_1.0001.580/14.1_BUD	100401_1.0001.1277_BUD
100401_1.0001.580/14.2_BUD	100401_1.0001.1278_BUD
100401_1.0001.580/14.3_BUD	100401_1.0001.1279_BUD
100401_1.0001.580/14.5_BUD	100401_1.0001.1280_BUD
100401_1.0001.580/15.3_BUD	100401_1.0001.1281_BUD
100401_1.0001.580/15.4_BUD	100401_1.0001.1282_BUD
100401_1.0001.581.3_BUD	100401_1.0001.1283_BUD
100401_1.0001.583/2.1_BUD	100401_1.0001.1284_BUD
100401_1.0001.583/2.2_BUD	100401_1.0001.1285_BUD
100401_1.0001.583/2.3_BUD	100401_1.0001.1286_BUD
100401_1.0001.583/5.1_BUD	100401_1.0001.1287_BUD
100401_1.0001.583/6.1_BUD	100401_1.0001.1288_BUD
100401_1.0001.583/7.1_BUD	100401_1.0001.1289_BUD
100401_1.0001.583/8.1_BUD	100401_1.0001.1290_BUD
100401_1.0001.583/9.1_BUD	100401_1.0001.1291_BUD
100401_1.0001.588.1_BUD	100401_1.0001.1292_BUD
100401_1.0001.588.2_BUD	100401_1.0001.1293_BUD
100401_1.0001.594.1_BUD	100401_1.0001.1294_BUD
100401_1.0001.594.2_BUD	100401_1.0001.1295_BUD

100401_1.0001.594.3_BUD	100401_1.0001.1296_BUD
100401_1.0001.594.4_BUD	100401_1.0001.1297_BUD
100401_1.0001.604.1_BUD	100401_1.0001.1298_BUD
100401_1.0001.625/1.1_BUD	100401_1.0001.1299_BUD
100401_1.0001.625/18.1_BUD	100401_1.0001.1300_BUD
100401_1.0001.625/18.2_BUD	100401_1.0001.1301_BUD
100401_1.0001.625/19.1_BUD	100401_1.0001.1302_BUD
100401_1.0001.625/20.1_BUD	100401_1.0001.1303_BUD
100401_1.0001.625/21.1_BUD	100401_1.0001.1304_BUD
100401_1.0001.625/22.1_BUD	100401_1.0001.1305_BUD
100401_1.0001.625/30.1_BUD	100401_1.0001.1306_BUD
100401_1.0001.625/33.1_BUD	100401_1.0001.1307_BUD
100401_1.0001.625/33.2_BUD	100401_1.0001.1308_BUD
100401_1.0001.625/35.1_BUD	100401_1.0001.1309_BUD
100401_1.0001.625/36.1_BUD	100401_1.0001.1310_BUD
100401_1.0001.625/37.1_BUD	100401_1.0001.1311_BUD
100401_1.0001.625/38.1_BUD	100401_1.0001.1312_BUD
100401_1.0001.625/39.1_BUD	100401_1.0001.1313_BUD
100401_1.0001.625/40.1_BUD	100401_1.0001.1314_BUD
100401_1.0001.625/41.1_BUD	100401_1.0001.1315_BUD
100401_1.0001.625/43.1_BUD	100401_1.0001.1316_BUD
100401_1.0001.625/46.1_BUD	100401_1.0001.1317_BUD
100401_1.0001.625/47.1_BUD	100401_1.0001.1318_BUD
100401_1.0001.626/2.1_BUD	100401_1.0001.1319_BUD
100401_1.0001.626/7.1_BUD	100401_1.0001.1320_BUD
100401_1.0001.626/12.1_BUD	100401_1.0001.1321_BUD
100401_1.0001.627/2.1_BUD	100401_1.0001.1322_BUD
100401_1.0001.628.1_BUD	100401_1.0001.1323_BUD
100401_1.0001.628.2_BUD	100401_1.0001.1324_BUD
100401_1.0001.628.3_BUD	100401_1.0001.1325_BUD
100401_1.0001.630/1.1_BUD	100401_1.0001.1326_BUD
100401_1.0001.630/2.1_BUD	100401_1.0001.1327_BUD
100401_1.0001.630/3.1_BUD	100401_1.0001.1328_BUD
100401_1.0001.630/4.1_BUD	100401_1.0001.1329_BUD
100401_1.0001.630/5.1_BUD	100401_1.0001.1330_BUD
100401_1.0001.630/6.1_BUD	100401_1.0001.1331_BUD
100401_1.0001.630/7.1_BUD	100401_1.0001.1332_BUD
100401_1.0001.630/8.1_BUD	100401_1.0001.1333_BUD
100401_1.0001.630/9.1_BUD	100401_1.0001.1334_BUD
100401_1.0001.630/10.1_BUD	100401_1.0001.1335_BUD
100401_1.0001.630/11.1_BUD	100401_1.0001.1336_BUD
100401_1.0001.630/12.1_BUD	100401_1.0001.1337_BUD
100401_1.0001.630/13.1_BUD	100401_1.0001.1338_BUD
100401_1.0001.630/14.1_BUD	100401_1.0001.1339_BUD
100401_1.0001.630/15.1_BUD	100401_1.0001.1340_BUD
100401_1.0001.630/16.1_BUD	100401_1.0001.1341_BUD
100401_1.0001.630/17.1_BUD	100401_1.0001.1342_BUD
100401_1.0001.630/18.1_BUD	100401_1.0001.1343_BUD
100401_1.0001.630/19.1_BUD	100401_1.0001.1344_BUD
100401_1.0001.630/20.1_BUD	100401_1.0001.1345_BUD
100401_1.0001.630/21.1_BUD	100401_1.0001.1346_BUD
100401_1.0001.630/22.1_BUD	100401_1.0001.1347_BUD
100401_1.0001.630/23.1_BUD	100401_1.0001.1348_BUD
100401_1.0001.630/24.1_BUD	100401_1.0001.1349_BUD

100401_1.0001.630/25.1_BUD	100401_1.0001.1350_BUD
100401_1.0001.630/26.1_BUD	100401_1.0001.1351_BUD
100401_1.0001.630/27.1_BUD	100401_1.0001.1352_BUD
100401_1.0001.630/28.1_BUD	100401_1.0001.1353_BUD
100401_1.0001.630/29.1_BUD	100401_1.0001.1354_BUD
100401_1.0001.630/30.1_BUD	100401_1.0001.1355_BUD
100401_1.0001.630/31.1_BUD	100401_1.0001.1356_BUD
100401_1.0001.630/32.1_BUD	100401_1.0001.1357_BUD
100401_1.0001.630/33.1_BUD	100401_1.0001.1358_BUD
100401_1.0001.630/34.1_BUD	100401_1.0001.1359_BUD
100401_1.0001.630/35.1_BUD	100401_1.0001.1360_BUD
100401_1.0001.630/36.1_BUD	100401_1.0001.1361_BUD
100401_1.0001.630/37.1_BUD	100401_1.0001.1362_BUD
100401_1.0001.630/40.1_BUD	100401_1.0001.1363_BUD
100401_1.0001.630/41.1_BUD	100401_1.0001.1364_BUD
100401_1.0001.630/42.1_BUD	100401_1.0001.1365_BUD
100401_1.0001.630/44.1_BUD	100401_1.0001.1366_BUD
100401_1.0001.630/45.1_BUD	100401_1.0001.1367_BUD
100401_1.0001.630/46.1_BUD	100401_1.0001.1368_BUD
100401_1.0001.630/47.1_BUD	100401_1.0001.1369_BUD
100401_1.0001.630/48.1_BUD	100401_1.0001.1370_BUD
100401_1.0001.630/49.1_BUD	100401_1.0001.1371_BUD
100401_1.0001.630/50.1_BUD	100401_1.0001.1372_BUD
100401_1.0001.630/51.1_BUD	100401_1.0001.1373_BUD
100401_1.0001.630/52.1_BUD	100401_1.0001.1374_BUD
100401_1.0001.630/53.1_BUD	100401_1.0001.1375_BUD
100401_1.0001.630/54.1_BUD	100401_1.0001.1376_BUD
100401_1.0001.630/55.1_BUD	100401_1.0001.1377_BUD
100401_1.0001.630/56.1_BUD	100401_1.0001.1378_BUD
100401_1.0001.630/57.1_BUD	100401_1.0001.1379_BUD
100401_1.0001.630/58.1_BUD	100401_1.0001.1380_BUD
100401_1.0001.630/59.1_BUD	100401_1.0001.1381_BUD
100401_1.0001.630/60.1_BUD	100401_1.0001.1382_BUD
100401_1.0001.630/61.1_BUD	100401_1.0001.1383_BUD
100401_1.0001.630/62.1_BUD	100401_1.0001.1384_BUD
100401_1.0001.630/63.1_BUD	100401_1.0001.1385_BUD
100401_1.0001.630/64.1_BUD	100401_1.0001.1386_BUD
100401_1.0001.630/65.1_BUD	100401_1.0001.1387_BUD
100401_1.0001.630/66.1_BUD	100401_1.0001.1388_BUD
100401_1.0001.630/67.1_BUD	100401_1.0001.1389_BUD
100401_1.0001.630/71.1_BUD	100401_1.0001.1390_BUD
100401_1.0001.630/72.1_BUD	100401_1.0001.1391_BUD
100401_1.0001.630/73.1_BUD	100401_1.0001.1392_BUD
100401_1.0001.630/74.1_BUD	100401_1.0001.1393_BUD
100401_1.0001.630/75.1_BUD	100401_1.0001.1394_BUD
100401_1.0001.630/77.1_BUD	100401_1.0001.1395_BUD
100401_1.0001.630/78.1_BUD	100401_1.0001.1396_BUD
100401_1.0001.630/79.1_BUD	100401_1.0001.1397_BUD
100401_1.0001.630/80.1_BUD	100401_1.0001.1398_BUD
100401_1.0001.630/81.1_BUD	100401_1.0001.1399_BUD
100401_1.0001.630/83.1_BUD	100401_1.0001.1400_BUD
100401_1.0001.630/84.1_BUD	100401_1.0001.1401_BUD
100401_1.0001.630/85.1_BUD	100401_1.0001.1402_BUD
100401_1.0001.631/4.1_BUD	100401_1.0001.1403_BUD

100401_1.0001.631/4.2_BUD	100401_1.0001.1404_BUD
100401_1.0001.631/5.1_BUD	100401_1.0001.1405_BUD
100401_1.0001.640/1.1_BUD	100401_1.0001.1406_BUD
100401_1.0001.640/2.1_BUD	100401_1.0001.1407_BUD
100401_1.0001.640/2.2_BUD	100401_1.0001.1408_BUD
100401_1.0001.640/2.3_BUD	100401_1.0001.1409_BUD
100401_1.0001.640/2.6_BUD	100401_1.0001.1410_BUD
100401_1.0001.640/2.8_BUD	100401_1.0001.1411_BUD
100401_1.0001.640/2.9_BUD	100401_1.0001.1412_BUD
100401_1.0001.640/2.10_BUD	100401_1.0001.1413_BUD
100401_1.0001.642/4.1_BUD	100401_1.0001.1414_BUD
100401_1.0001.642/4.2_BUD	100401_1.0001.1415_BUD
100401_1.0001.642/4.3_BUD	100401_1.0001.1416_BUD
100401_1.0001.643/2.1_BUD	100401_1.0001.1417_BUD
100401_1.0001.643/2.2_BUD	100401_1.0001.1418_BUD
100401_1.0001.643/2.3_BUD	100401_1.0001.1419_BUD
100401_1.0001.643/2.4_BUD	100401_1.0001.1420_BUD
100401_1.0001.643/2.5_BUD	100401_1.0001.1421_BUD
100401_1.0001.643/2.6_BUD	100401_1.0001.1422_BUD
100401_1.0001.644/2.1_BUD	100401_1.0001.1423_BUD
100401_1.0001.644/2.2_BUD	100401_1.0001.1424_BUD
100401_1.0001.644/2.3_BUD	100401_1.0001.1425_BUD
100401_1.0001.644/2.4_BUD	100401_1.0001.1426_BUD
100401_1.0001.649/5.1_BUD	100401_1.0001.1427_BUD
100401_1.0001.649/5.2_BUD	100401_1.0001.1428_BUD
100401_1.0001.653/1.1_BUD	100401_1.0001.1429_BUD
100401_1.0001.661.1_BUD	100401_1.0001.1430_BUD
100401_1.0001.661.2_BUD	100401_1.0001.1431_BUD
100401_1.0001.662.1_BUD	100401_1.0001.1432_BUD
100401_1.0001.662.2_BUD	100401_1.0001.1433_BUD
100401_1.0001.662.3_BUD	100401_1.0001.1434_BUD
100401_1.0001.662.5_BUD	100401_1.0001.1435_BUD
100401_1.0001.663/1.1_BUD	100401_1.0001.1436_BUD
100401_1.0001.665.1_BUD	100401_1.0001.1437_BUD
100401_1.0001.665.2_BUD	100401_1.0001.1438_BUD
100401_1.0001.666.1_BUD	100401_1.0001.1439_BUD
100401_1.0001.666.2_BUD	100401_1.0001.1440_BUD
100401_1.0001.666.3_BUD	100401_1.0001.1441_BUD
100401_1.0001.666.4_BUD	100401_1.0001.1442_BUD
100401_1.0001.667/1.1_BUD	100401_1.0001.1443_BUD
100401_1.0001.667/1.2_BUD	100401_1.0001.1444_BUD
100401_1.0001.667/1.3_BUD	100401_1.0001.1445_BUD
100401_1.0001.667/2.1_BUD	100401_1.0001.1446_BUD
100401_1.0001.667/2.2_BUD	100401_1.0001.1447_BUD
100401_1.0001.669/2.1_BUD	100401_1.0001.1448_BUD
100401_1.0001.669/2.2_BUD	100401_1.0001.1449_BUD
100401_1.0001.669/2.3_BUD	100401_1.0001.1450_BUD
100401_1.0001.669/2.4_BUD	100401_1.0001.1451_BUD
100401_1.0001.669/9.1_BUD	100401_1.0001.1452_BUD
100401_1.0001.673/4.1_BUD	100401_1.0001.1453_BUD
100401_1.0001.673/4.2_BUD	100401_1.0001.1454_BUD
100401_1.0001.673/6.1_BUD	100401_1.0001.1455_BUD
100401_1.0001.673/6.2_BUD	100401_1.0001.1456_BUD
100401_1.0001.674/2.1_BUD	100401_1.0001.1457_BUD

100401_1.0001.674/4.1_BUD	100401_1.0001.1458_BUD
100401_1.0001.674/5.1_BUD	100401_1.0001.1459_BUD
100401_1.0001.674/6.1_BUD	100401_1.0001.1460_BUD
100401_1.0001.674/10.1_BUD	100401_1.0001.1461_BUD
100401_1.0001.674/11.1_BUD	100401_1.0001.1462_BUD
100401_1.0001.674/12.1_BUD	100401_1.0001.1463_BUD
100401_1.0001.674/18.1_BUD	100401_1.0001.1464_BUD
100401_1.0001.674/20.1_BUD	100401_1.0001.1465_BUD
100401_1.0001.677/3.2_BUD	100401_1.0001.1466_BUD
100401_1.0001.677/4.1_BUD	100401_1.0001.1467_BUD
100401_1.0001.677/4.2_BUD	100401_1.0001.1468_BUD
100401_1.0001.678.1_BUD	100401_1.0001.1469_BUD
100401_1.0001.678.2_BUD	100401_1.0001.1470_BUD
100401_1.0001.678.3_BUD	100401_1.0001.1471_BUD
100401_1.0001.678.4_BUD	100401_1.0001.1472_BUD
100401_1.0001.679.1_BUD	100401_1.0001.1473_BUD
100401_1.0001.679.2_BUD	100401_1.0001.1474_BUD
100401_1.0001.679.3_BUD	100401_1.0001.1475_BUD
100401_1.0001.679.4_BUD	100401_1.0001.1476_BUD
100401_1.0001.679.5_BUD	100401_1.0001.1477_BUD
100401_1.0001.679.6_BUD	100401_1.0001.1478_BUD
100401_1.0001.680.2_BUD	100401_1.0001.1479_BUD
100401_1.0001.680.3_BUD	100401_1.0001.1480_BUD
100401_1.0001.680.4_BUD	100401_1.0001.1481_BUD
100401_1.0001.680.5_BUD	100401_1.0001.1482_BUD
100401_1.0001.681.1_BUD	100401_1.0001.1483_BUD
100401_1.0001.684.1_BUD	100401_1.0001.1484_BUD
100401_1.0001.685.1_BUD	100401_1.0001.1485_BUD
100401_1.0001.688.1_BUD	100401_1.0001.1486_BUD
100401_1.0001.689.1_BUD	100401_1.0001.1487_BUD
100401_1.0001.691/1.1_BUD	100401_1.0001.1488_BUD
100401_1.0001.691/2.2_BUD	100401_1.0001.1489_BUD
100401_1.0001.693.1_BUD	100401_1.0001.1490_BUD
100401_1.0001.694/1.1_BUD	100401_1.0001.1491_BUD
100401_1.0001.694/1.4_BUD	100401_1.0001.1492_BUD
100401_1.0001.694/2.1_BUD	100401_1.0001.1493_BUD
100401_1.0001.694/2.2_BUD	100401_1.0001.1494_BUD
100401_1.0001.694/2.3_BUD	100401_1.0001.1495_BUD
100401_1.0001.695.1_BUD	100401_1.0001.1496_BUD
100401_1.0001.695.2_BUD	100401_1.0001.1497_BUD
100401_1.0001.696/2.1_BUD	100401_1.0001.1498_BUD
100401_1.0001.696/3.1_BUD	100401_1.0001.1499_BUD
100401_1.0001.696/13.1_BUD	100401_1.0001.1500_BUD
100401_1.0001.696/14.1_BUD	100401_1.0001.1501_BUD
100401_1.0001.696/18.1_BUD	100401_1.0001.1502_BUD
100401_1.0001.696/20.1_BUD	100401_1.0001.1503_BUD
100401_1.0001.696/21.1_BUD	100401_1.0001.1504_BUD
100401_1.0001.696/22.1_BUD	100401_1.0001.1505_BUD
100401_1.0001.696/22.2_BUD	100401_1.0001.1506_BUD
100401_1.0001.696/22.3_BUD	100401_1.0001.1507_BUD
100401_1.0001.696/22.4_BUD	100401_1.0001.1508_BUD
100401_1.0001.699/3.1_BUD	100401_1.0001.1509_BUD
100401_1.0001.699/4.1_BUD	100401_1.0001.1510_BUD
100401_1.0001.699/4.2_BUD	100401_1.0001.1511_BUD

100401_1.0001.702/7.1_BUD	100401_1.0001.1512_BUD
100401_1.0001.702/15.1_BUD	100401_1.0001.1513_BUD
100401_1.0001.702/19.1_BUD	100401_1.0001.1514_BUD
100401_1.0001.702/29.1_BUD	100401_1.0001.1515_BUD
100401_1.0001.702/29.2_BUD	100401_1.0001.1516_BUD
100401_1.0001.702/29.3_BUD	100401_1.0001.1517_BUD
100401_1.0001.702/30.1_BUD	100401_1.0001.1518_BUD
100401_1.0001.702/38.1_BUD	100401_1.0001.1519_BUD
100401_1.0001.702/39.1_BUD	100401_1.0001.1520_BUD
100401_1.0001.702/40.1_BUD	100401_1.0001.1521_BUD
100401_1.0001.702/44.1_BUD	100401_1.0001.1522_BUD
100401_1.0001.702/44.2_BUD	100401_1.0001.1523_BUD
100401_1.0001.702/50.1_BUD	100401_1.0001.1524_BUD
100401_1.0001.703.1_BUD	100401_1.0001.1525_BUD
100401_1.0001.703.2_BUD	100401_1.0001.1526_BUD
100401_1.0001.703.3_BUD	100401_1.0001.1527_BUD
100401_1.0001.703.4_BUD	100401_1.0001.1528_BUD
100401_1.0001.704.1_BUD	100401_1.0001.1529_BUD
100401_1.0001.706/8.1_BUD	100401_1.0001.1530_BUD
100401_1.0001.706/9.1_BUD	100401_1.0001.1531_BUD
100401_1.0001.706/10.1_BUD	100401_1.0001.1532_BUD
100401_1.0001.706/12.1_BUD	100401_1.0001.1533_BUD
100401_1.0001.706/13.1_BUD	100401_1.0001.1534_BUD
100401_1.0001.706/13.2_BUD	100401_1.0001.1535_BUD
100401_1.0001.706/14.1_BUD	100401_1.0001.1536_BUD
100401_1.0001.706/14.2_BUD	100401_1.0001.1537_BUD
100401_1.0001.710/1.1_BUD	100401_1.0001.1538_BUD
100401_1.0001.711.1_BUD	100401_1.0001.1539_BUD
100401_1.0001.711.2_BUD	100401_1.0001.1540_BUD
100401_1.0001.713/1.1_BUD	100401_1.0001.1541_BUD
100401_1.0001.713/2.1_BUD	100401_1.0001.1542_BUD
100401_1.0001.713/2.2_BUD	100401_1.0001.1543_BUD
100401_1.0001.713/2.3_BUD	100401_1.0001.1544_BUD
100401_1.0001.714.1_BUD	100401_1.0001.1545_BUD
100401_1.0001.714.2_BUD	100401_1.0001.1546_BUD
100401_1.0001.715/1.1_BUD	100401_1.0001.1547_BUD
100401_1.0001.715/1.2_BUD	100401_1.0001.1548_BUD
100401_1.0001.715/1.3_BUD	100401_1.0001.1549_BUD
100401_1.0001.715/1.4_BUD	100401_1.0001.1550_BUD
100401_1.0001.715/2.1_BUD	100401_1.0001.1551_BUD
100401_1.0001.715/2.2_BUD	100401_1.0001.1552_BUD
100401_1.0001.715/3.1_BUD	100401_1.0001.1553_BUD
100401_1.0001.715/3.2_BUD	100401_1.0001.1554_BUD
100401_1.0001.716.1_BUD	100401_1.0001.1555_BUD
100401_1.0001.716.2_BUD	100401_1.0001.1556_BUD
100401_1.0001.718.1_BUD	100401_1.0001.1557_BUD
100401_1.0001.718.5_BUD	100401_1.0001.1558_BUD
100401_1.0001.718.6_BUD	100401_1.0001.1559_BUD
100401_1.0001.719.1_BUD	100401_1.0001.1560_BUD
100401_1.0001.719.2_BUD	100401_1.0001.1561_BUD
100401_1.0001.720.1_BUD	100401_1.0001.1562_BUD
100401_1.0001.720.2_BUD	100401_1.0001.1563_BUD
100401_1.0001.720.3_BUD	100401_1.0001.1564_BUD
100401_1.0001.720.4_BUD	100401_1.0001.1565_BUD

100401_1.0001.721.1_BUD	100401_1.0001.1566_BUD
100401_1.0001.721.2_BUD	100401_1.0001.1567_BUD
100401_1.0001.722.3_BUD	100401_1.0001.1568_BUD
100401_1.0001.722/1.1_BUD	100401_1.0001.1569_BUD
100401_1.0001.722/1.2_BUD	100401_1.0001.1570_BUD
100401_1.0001.722/1.3_BUD	100401_1.0001.1571_BUD
100401_1.0001.722/2.1_BUD	100401_1.0001.1572_BUD
100401_1.0001.723.1_BUD	100401_1.0001.1573_BUD
100401_1.0001.723.2_BUD	100401_1.0001.1574_BUD
100401_1.0001.724.1_BUD	100401_1.0001.1575_BUD
100401_1.0001.724.2_BUD	100401_1.0001.1576_BUD
100401_1.0001.725/1.1_BUD	100401_1.0001.1577_BUD
100401_1.0001.727.1_BUD	100401_1.0001.1578_BUD
100401_1.0001.727.2_BUD	100401_1.0001.1579_BUD
100401_1.0001.728.1_BUD	100401_1.0001.1580_BUD
100401_1.0001.728.2_BUD	100401_1.0001.1581_BUD
100401_1.0001.729/2.2_BUD	100401_1.0001.1582_BUD
100401_1.0001.729/2.3_BUD	100401_1.0001.1583_BUD
100401_1.0001.729/4.1_BUD	100401_1.0001.1584_BUD
100401_1.0001.729/5.2_BUD	100401_1.0001.1585_BUD
100401_1.0001.729/7.1_BUD	100401_1.0001.1586_BUD
100401_1.0001.729/7.3_BUD	100401_1.0001.1587_BUD
100401_1.0001.729/8.1_BUD	100401_1.0001.1588_BUD
100401_1.0001.729/8.2_BUD	100401_1.0001.1589_BUD
100401_1.0001.730/2.1_BUD	100401_1.0001.1590_BUD
100401_1.0001.730/3.1_BUD	100401_1.0001.1591_BUD
100401_1.0001.730/4.1_BUD	100401_1.0001.1592_BUD
100401_1.0001.730/5.1_BUD	100401_1.0001.1593_BUD
100401_1.0001.730/6.1_BUD	100401_1.0001.1594_BUD
100401_1.0001.732/1.1_BUD	100401_1.0001.1595_BUD
100401_1.0001.733/1.1_BUD	100401_1.0001.1596_BUD
100401_1.0001.734/1.1_BUD	100401_1.0001.1597_BUD
100401_1.0001.734/2.1_BUD	100401_1.0001.1598_BUD
100401_1.0001.734/2.2_BUD	100401_1.0001.1599_BUD
100401_1.0001.734/2.3_BUD	100401_1.0001.1600_BUD
100401_1.0001.735.1_BUD	100401_1.0001.1601_BUD
100401_1.0001.735.2_BUD	100401_1.0001.1602_BUD
100401_1.0001.737.1_BUD	100401_1.0001.1603_BUD
100401_1.0001.738/3.1_BUD	100401_1.0001.1604_BUD
100401_1.0001.738/3.2_BUD	100401_1.0001.1605_BUD
100401_1.0001.740/1.1_BUD	100401_1.0001.1606_BUD
100401_1.0001.740/1.2_BUD	100401_1.0001.1607_BUD
100401_1.0001.740/1.3_BUD	100401_1.0001.1608_BUD
100401_1.0001.740/2.1_BUD	100401_1.0001.1609_BUD
100401_1.0001.740/2.2_BUD	100401_1.0001.1610_BUD
100401_1.0001.740/2.3_BUD	100401_1.0001.1611_BUD
100401_1.0001.740/2.4_BUD	100401_1.0001.1612_BUD
100401_1.0001.740/2.5_BUD	100401_1.0001.1613_BUD
100401_1.0001.740/2.6_BUD	100401_1.0001.1614_BUD
100401_1.0001.740/2.7_BUD	100401_1.0001.1615_BUD
100401_1.0001.740/2.8_BUD	100401_1.0001.1616_BUD
100401_1.0001.740/2.9_BUD	100401_1.0001.1617_BUD
100401_1.0001.740/4.1_BUD	100401_1.0001.1618_BUD
100401_1.0001.741.1_BUD	100401_1.0001.1619_BUD

100401_1.0001.741.6_BUD	100401_1.0001.1620_BUD
100401_1.0001.741.7_BUD	100401_1.0001.1621_BUD
100401_1.0001.741.8_BUD	100401_1.0001.1622_BUD
100401_1.0001.742/3.1_BUD	100401_1.0001.1623_BUD
100401_1.0001.742/3.2_BUD	100401_1.0001.1624_BUD
100401_1.0001.742/7.1_BUD	100401_1.0001.1625_BUD
100401_1.0001.743.1_BUD	100401_1.0001.1626_BUD
100401_1.0001.743.2_BUD	100401_1.0001.1627_BUD
100401_1.0001.744.1_BUD	100401_1.0001.1628_BUD
100401_1.0001.744.2_BUD	100401_1.0001.1629_BUD
100401_1.0001.744.3_BUD	100401_1.0001.1630_BUD
100401_1.0001.746.1_BUD	100401_1.0001.1631_BUD
100401_1.0001.746.2_BUD	100401_1.0001.1632_BUD
100401_1.0001.746.3_BUD	100401_1.0001.1633_BUD
100401_1.0001.747.1_BUD	100401_1.0001.1634_BUD
100401_1.0001.748/1.1_BUD	100401_1.0001.1635_BUD
100401_1.0001.748/1.2_BUD	100401_1.0001.1636_BUD
100401_1.0001.748/1.6_BUD	100401_1.0001.1637_BUD
100401_1.0001.748/1.8_BUD	100401_1.0001.1638_BUD
100401_1.0001.749/1.3_BUD	100401_1.0001.1639_BUD
100401_1.0001.749/2.1_BUD	100401_1.0001.1640_BUD
100401_1.0001.749/2.2_BUD	100401_1.0001.1641_BUD
100401_1.0001.749/2.3_BUD	100401_1.0001.1642_BUD
100401_1.0001.751.3_BUD	100401_1.0001.1643_BUD
100401_1.0001.752.1_BUD	100401_1.0001.1644_BUD
100401_1.0001.752.2_BUD	100401_1.0001.1645_BUD
100401_1.0001.753.1_BUD	100401_1.0001.1646_BUD
100401_1.0001.754.1_BUD	100401_1.0001.1647_BUD
100401_1.0001.754.2_BUD	100401_1.0001.1648_BUD
100401_1.0001.755.1_BUD	100401_1.0001.1649_BUD
100401_1.0001.755.2_BUD	100401_1.0001.1650_BUD
100401_1.0001.756/2.1_BUD	100401_1.0001.1651_BUD
100401_1.0001.756/2.2_BUD	100401_1.0001.1652_BUD
100401_1.0001.756/2.3_BUD	100401_1.0001.1653_BUD
100401_1.0001.757.1_BUD	100401_1.0001.1654_BUD
100401_1.0001.757.2_BUD	100401_1.0001.1655_BUD
100401_1.0001.757.3_BUD	100401_1.0001.1656_BUD
100401_1.0001.757.4_BUD	100401_1.0001.1657_BUD
100401_1.0001.758.1_BUD	100401_1.0001.1658_BUD
100401_1.0001.763.1_BUD	100401_1.0001.1659_BUD
100401_1.0001.763.2_BUD	100401_1.0001.1660_BUD
100401_1.0001.764.1_BUD	100401_1.0001.1661_BUD
100401_1.0001.764.2_BUD	100401_1.0001.1662_BUD
100401_1.0001.764.3_BUD	100401_1.0001.1663_BUD
100401_1.0001.764.4_BUD	100401_1.0001.1664_BUD
100401_1.0001.765/1.1_BUD	100401_1.0001.1665_BUD
100401_1.0001.765/2.1_BUD	100401_1.0001.1666_BUD
100401_1.0001.765/2.2_BUD	100401_1.0001.1667_BUD
100401_1.0001.766/1.1_BUD	100401_1.0001.1668_BUD
100401_1.0001.766/2.1_BUD	100401_1.0001.1669_BUD
100401_1.0001.767/2.1_BUD	100401_1.0001.1670_BUD
100401_1.0001.767/2.2_BUD	100401_1.0001.1671_BUD
100401_1.0001.767/2.3_BUD	100401_1.0001.1672_BUD
100401_1.0001.767/2.4_BUD	100401_1.0001.1673_BUD

100401_1.0001.767/2.5_BUD	100401_1.0001.1674_BUD
100401_1.0001.767/2.6_BUD	100401_1.0001.1675_BUD
100401_1.0001.767/4.1_BUD	100401_1.0001.1676_BUD
100401_1.0001.767/4.2_BUD	100401_1.0001.1677_BUD
100401_1.0001.767/4.3_BUD	100401_1.0001.1678_BUD
100401_1.0001.767/4.4_BUD	100401_1.0001.1679_BUD
100401_1.0001.767/4.5_BUD	100401_1.0001.1680_BUD
100401_1.0001.767/5.1_BUD	100401_1.0001.1681_BUD
100401_1.0001.768.1_BUD	100401_1.0001.1682_BUD
100401_1.0001.768.2_BUD	100401_1.0001.1683_BUD
100401_1.0001.768.3_BUD	100401_1.0001.1684_BUD
100401_1.0001.769.1_BUD	100401_1.0001.1685_BUD
100401_1.0001.769.2_BUD	100401_1.0001.1686_BUD
100401_1.0001.769.3_BUD	100401_1.0001.1687_BUD
100401_1.0001.769.4_BUD	100401_1.0001.1688_BUD
100401_1.0001.769.5_BUD	100401_1.0001.1689_BUD
100401_1.0001.770/1.1_BUD	100401_1.0001.1690_BUD
100401_1.0001.770/1.2_BUD	100401_1.0001.1691_BUD
100401_1.0001.770/1.3_BUD	100401_1.0001.1692_BUD
100401_1.0001.770/2.1_BUD	100401_1.0001.1693_BUD
100401_1.0001.770/2.2_BUD	100401_1.0001.1694_BUD
100401_1.0001.771/1.1_BUD	100401_1.0001.1695_BUD
100401_1.0001.772.1_BUD	100401_1.0001.1696_BUD
100401_1.0001.772.6_BUD	100401_1.0001.1697_BUD
100401_1.0001.772/4.1_BUD	100401_1.0001.1698_BUD
100401_1.0001.772/6.1_BUD	100401_1.0001.1699_BUD
100401_1.0001.773.1_BUD	100401_1.0001.1700_BUD
100401_1.0001.773.2_BUD	100401_1.0001.1701_BUD
100401_1.0001.774.1_BUD	100401_1.0001.1702_BUD
100401_1.0001.774.2_BUD	100401_1.0001.1703_BUD
100401_1.0001.774.3_BUD	100401_1.0001.1704_BUD
100401_1.0001.775.3_BUD	100401_1.0001.1705_BUD
100401_1.0001.775.4_BUD	100401_1.0001.1706_BUD
100401_1.0001.775.5_BUD	100401_1.0001.1707_BUD
100401_1.0001.776.1_BUD	100401_1.0001.1708_BUD
100401_1.0001.776.2_BUD	100401_1.0001.1709_BUD
100401_1.0001.776.3_BUD	100401_1.0001.1710_BUD
100401_1.0001.776.4_BUD	100401_1.0001.1711_BUD
100401_1.0001.778.1_BUD	100401_1.0001.1712_BUD
100401_1.0001.778.2_BUD	100401_1.0001.1713_BUD
100401_1.0001.778.3_BUD	100401_1.0001.1714_BUD
100401_1.0001.778.4_BUD	100401_1.0001.1715_BUD
100401_1.0001.779/2.3_BUD	100401_1.0001.1716_BUD
100401_1.0001.779/2.4_BUD	100401_1.0001.1717_BUD
100401_1.0001.779/2.5_BUD	100401_1.0001.1718_BUD
100401_1.0001.780/1.1_BUD	100401_1.0001.1719_BUD
100401_1.0001.780/3.1_BUD	100401_1.0001.1720_BUD
100401_1.0001.780/3.2_BUD	100401_1.0001.1721_BUD
100401_1.0001.780/4.1_BUD	100401_1.0001.1722_BUD
100401_1.0001.780/5.1_BUD	100401_1.0001.1723_BUD
100401_1.0001.780/5.2_BUD	100401_1.0001.1724_BUD
100401_1.0001.781/1.2_BUD	100401_1.0001.1725_BUD
100401_1.0001.781/2.1_BUD	100401_1.0001.1726_BUD
100401_1.0001.782.1_BUD	100401_1.0001.1727_BUD

100401_1.0001.782.2_BUD	100401_1.0001.1728_BUD
100401_1.0001.782.3_BUD	100401_1.0001.1729_BUD
100401_1.0001.783.1_BUD	100401_1.0001.1730_BUD
100401_1.0001.783.2_BUD	100401_1.0001.1731_BUD
100401_1.0001.783.3_BUD	100401_1.0001.1732_BUD
100401_1.0001.784/2.1_BUD	100401_1.0001.1733_BUD
100401_1.0001.784/2.2_BUD	100401_1.0001.1734_BUD
100401_1.0001.784/2.3_BUD	100401_1.0001.1735_BUD
100401_1.0001.792.1_BUD	100401_1.0001.1736_BUD
100401_1.0001.792.4_BUD	100401_1.0001.1737_BUD
100401_1.0001.792.6_BUD	100401_1.0001.1738_BUD
100401_1.0001.792.7_BUD	100401_1.0001.1739_BUD
100401_1.0001.792/3.1_BUD	100401_1.0001.1740_BUD
100401_1.0001.792/4.1_BUD	100401_1.0001.1741_BUD
100401_1.0001.792/7.1_BUD	100401_1.0001.1742_BUD
100401_1.0001.794/1.1_BUD	100401_1.0001.1743_BUD
100401_1.0001.794/1.3_BUD	100401_1.0001.1744_BUD
100401_1.0001.798/2.1_BUD	100401_1.0001.1745_BUD
100401_1.0001.798/2.2_BUD	100401_1.0001.1746_BUD
100401_1.0001.798/3.1_BUD	100401_1.0001.1747_BUD
100401_1.0001.798/3.2_BUD	100401_1.0001.1748_BUD
100401_1.0001.799/1.1_BUD	100401_1.0001.1749_BUD
100401_1.0001.799/3.1_BUD	100401_1.0001.1750_BUD
100401_1.0001.799/6.3_BUD	100401_1.0001.1751_BUD
100401_1.0001.800.1_BUD	100401_1.0001.1752_BUD
100401_1.0001.801.1_BUD	100401_1.0001.1753_BUD
100401_1.0001.801/2.1_BUD	100401_1.0001.1754_BUD
100401_1.0001.802.1_BUD	100401_1.0001.1755_BUD
100401_1.0001.802.2_BUD	100401_1.0001.1756_BUD
100401_1.0001.802.3_BUD	100401_1.0001.1757_BUD
100401_1.0001.803/1.1_BUD	100401_1.0001.1758_BUD
100401_1.0001.803/2.1_BUD	100401_1.0001.1759_BUD
100401_1.0001.804.1_BUD	100401_1.0001.1760_BUD
100401_1.0001.804.4_BUD	100401_1.0001.1761_BUD
100401_1.0001.805/2.1_BUD	100401_1.0001.1762_BUD
100401_1.0001.806.1_BUD	100401_1.0001.1763_BUD
100401_1.0001.806.2_BUD	100401_1.0001.1764_BUD
100401_1.0001.806.3_BUD	100401_1.0001.1765_BUD
100401_1.0001.808.1_BUD	100401_1.0001.1766_BUD
100401_1.0001.808.2_BUD	100401_1.0001.1767_BUD
100401_1.0001.809.1_BUD	100401_1.0001.1768_BUD
100401_1.0001.809.2_BUD	100401_1.0001.1769_BUD
100401_1.0001.809.3_BUD	100401_1.0001.1770_BUD
100401_1.0001.811.1_BUD	100401_1.0001.1771_BUD
100401_1.0001.813.2_BUD	100401_1.0001.1772_BUD
100401_1.0001.814.2_BUD	100401_1.0001.1773_BUD
100401_1.0001.815.1_BUD	100401_1.0001.1774_BUD
100401_1.0001.815.3_BUD	100401_1.0001.1775_BUD
100401_1.0001.815.4_BUD	100401_1.0001.1776_BUD
100401_1.0001.815/1.1_BUD	100401_1.0001.1777_BUD
100401_1.0001.816.1_BUD	100401_1.0001.1778_BUD
100401_1.0001.816.5_BUD	100401_1.0001.1779_BUD
100401_1.0001.819.1_BUD	100401_1.0001.1780_BUD
100401_1.0001.820.1_BUD	100401_1.0001.1781_BUD

100401_1.0001.820.2_BUD	100401_1.0001.1782_BUD
100401_1.0001.820.4_BUD	100401_1.0001.1783_BUD
100401_1.0001.821/1.1_BUD	100401_1.0001.1784_BUD
100401_1.0001.821/1.2_BUD	100401_1.0001.1785_BUD
100401_1.0001.821/1.3_BUD	100401_1.0001.1786_BUD
100401_1.0001.821/2.1_BUD	100401_1.0001.1787_BUD
100401_1.0001.821/2.2_BUD	100401_1.0001.1788_BUD
100401_1.0001.822.1_BUD	100401_1.0001.1789_BUD
100401_1.0001.824.1_BUD	100401_1.0001.1790_BUD
100401_1.0001.824.2_BUD	100401_1.0001.1791_BUD
100401_1.0001.824.3_BUD	100401_1.0001.1792_BUD
100401_1.0001.825.1_BUD	100401_1.0001.1793_BUD
100401_1.0001.827/1.1_BUD	100401_1.0001.1794_BUD
100401_1.0001.827/1.2_BUD	100401_1.0001.1795_BUD
100401_1.0001.833.1_BUD	100401_1.0001.1796_BUD
100401_1.0001.834/2.1_BUD	100401_1.0001.1797_BUD
100401_1.0001.834/3.1_BUD	100401_1.0001.1798_BUD
100401_1.0001.834/3.2_BUD	100401_1.0001.1799_BUD
100401_1.0001.834/4.3_BUD	100401_1.0001.1800_BUD
100401_1.0001.834/5.1_BUD	100401_1.0001.1801_BUD
100401_1.0001.834/5.2_BUD	100401_1.0001.1802_BUD
100401_1.0001.834/5.3_BUD	100401_1.0001.1803_BUD
100401_1.0001.834/7.1_BUD	100401_1.0001.1804_BUD
100401_1.0001.834/7.2_BUD	100401_1.0001.1805_BUD
100401_1.0001.834/7.3_BUD	100401_1.0001.1806_BUD
100401_1.0001.834/8.1_BUD	100401_1.0001.1807_BUD
100401_1.0001.834/8.2_BUD	100401_1.0001.1808_BUD
100401_1.0001.834/12.1_BUD	100401_1.0001.1809_BUD
100401_1.0001.834/25.1_BUD	100401_1.0001.1810_BUD
100401_1.0001.834/29.1_BUD	100401_1.0001.1811_BUD
100401_1.0001.834/29.2_BUD	100401_1.0001.1812_BUD
100401_1.0001.840/2.1_BUD	100401_1.0001.1813_BUD
100401_1.0001.840/2.2_BUD	100401_1.0001.1814_BUD
100401_1.0001.840/3.1_BUD	100401_1.0001.1815_BUD
100401_1.0001.840/4.1_BUD	100401_1.0001.1816_BUD
100401_1.0001.841.1_BUD	100401_1.0001.1817_BUD
100401_1.0001.841.2_BUD	100401_1.0001.1818_BUD
100401_1.0001.841.3_BUD	100401_1.0001.1819_BUD
100401_1.0001.842/1.1_BUD	100401_1.0001.1820_BUD
100401_1.0001.842/1.2_BUD	100401_1.0001.1821_BUD
100401_1.0001.842/1.3_BUD	100401_1.0001.1822_BUD
100401_1.0001.842/2.1_BUD	100401_1.0001.1823_BUD
100401_1.0001.845.1_BUD	100401_1.0001.1824_BUD
100401_1.0001.846.1_BUD	100401_1.0001.1825_BUD
100401_1.0001.846.2_BUD	100401_1.0001.1826_BUD
100401_1.0001.847.1_BUD	100401_1.0001.1827_BUD
100401_1.0001.847.2_BUD	100401_1.0001.1828_BUD
100401_1.0001.847.3_BUD	100401_1.0001.1829_BUD
100401_1.0001.848.1_BUD	100401_1.0001.1830_BUD
100401_1.0001.848.2_BUD	100401_1.0001.1831_BUD
100401_1.0001.849.1_BUD	100401_1.0001.1832_BUD
100401_1.0001.849.2_BUD	100401_1.0001.1833_BUD
100401_1.0001.849.3_BUD	100401_1.0001.1834_BUD
100401_1.0001.851.1_BUD	100401_1.0001.1835_BUD

100401_1.0001.851.2_BUD	100401_1.0001.1836_BUD
100401_1.0001.852/4.1_BUD	100401_1.0001.1837_BUD
100401_1.0001.852/7.1_BUD	100401_1.0001.1838_BUD
100401_1.0001.852/7.2_BUD	100401_1.0001.1839_BUD
100401_1.0001.852/8.1_BUD	100401_1.0001.1840_BUD
100401_1.0001.853.1_BUD	100401_1.0001.1841_BUD
100401_1.0001.853.2_BUD	100401_1.0001.1842_BUD
100401_1.0001.853.3_BUD	100401_1.0001.1843_BUD
100401_1.0001.854.1_BUD	100401_1.0001.1844_BUD
100401_1.0001.854.2_BUD	100401_1.0001.1845_BUD
100401_1.0001.855.1_BUD	100401_1.0001.1846_BUD
100401_1.0001.855.2_BUD	100401_1.0001.1847_BUD
100401_1.0001.856.1_BUD	100401_1.0001.1848_BUD
100401_1.0001.856.2_BUD	100401_1.0001.1849_BUD
100401_1.0001.856.3_BUD	100401_1.0001.1850_BUD
100401_1.0001.856.4_BUD	100401_1.0001.1851_BUD
100401_1.0001.857.1_BUD	100401_1.0001.1852_BUD
100401_1.0001.857.2_BUD	100401_1.0001.1853_BUD
100401_1.0001.857.3_BUD	100401_1.0001.1854_BUD
100401_1.0001.857.4_BUD	100401_1.0001.1855_BUD
100401_1.0001.857.5_BUD	100401_1.0001.1856_BUD
100401_1.0001.858.1_BUD	100401_1.0001.1857_BUD
100401_1.0001.858.4_BUD	100401_1.0001.1858_BUD
100401_1.0001.858.5_BUD	100401_1.0001.1859_BUD
100401_1.0001.859.1_BUD	100401_1.0001.1860_BUD
100401_1.0001.859.2_BUD	100401_1.0001.1861_BUD
100401_1.0001.859.3_BUD	100401_1.0001.1862_BUD
100401_1.0001.860/1.1_BUD	100401_1.0001.1863_BUD
100401_1.0001.860/2.1_BUD	100401_1.0001.1864_BUD
100401_1.0001.860/2.2_BUD	100401_1.0001.1865_BUD
100401_1.0001.860/2.3_BUD	100401_1.0001.1866_BUD
100401_1.0001.860/2.4_BUD	100401_1.0001.1867_BUD
100401_1.0001.861.1_BUD	100401_1.0001.1868_BUD
100401_1.0001.861.2_BUD	100401_1.0001.1869_BUD
100401_1.0001.862.1_BUD	100401_1.0001.1870_BUD
100401_1.0001.862.2_BUD	100401_1.0001.1871_BUD
100401_1.0001.862.3_BUD	100401_1.0001.1872_BUD
100401_1.0001.864.1_BUD	100401_1.0001.1873_BUD
100401_1.0001.864.2_BUD	100401_1.0001.1874_BUD
100401_1.0001.864.3_BUD	100401_1.0001.1875_BUD
100401_1.0001.864.4_BUD	100401_1.0001.1876_BUD
100401_1.0001.864.5_BUD	100401_1.0001.1877_BUD
100401_1.0001.865.1_BUD	100401_1.0001.1878_BUD
100401_1.0001.867.1_BUD	100401_1.0001.1879_BUD
100401_1.0001.867.2_BUD	100401_1.0001.1880_BUD
100401_1.0001.867.3_BUD	100401_1.0001.1881_BUD
100401_1.0001.868.1_BUD	100401_1.0001.1882_BUD
100401_1.0001.868.2_BUD	100401_1.0001.1883_BUD
100401_1.0001.868.3_BUD	100401_1.0001.1884_BUD
100401_1.0001.868.4_BUD	100401_1.0001.1885_BUD
100401_1.0001.869.1_BUD	100401_1.0001.1886_BUD
100401_1.0001.870.1_BUD	100401_1.0001.1887_BUD
100401_1.0001.870.2_BUD	100401_1.0001.1888_BUD
100401_1.0001.870/1.1_BUD	100401_1.0001.1889_BUD

100401_1.0001.871.1_BUD	100401_1.0001.1890_BUD
100401_1.0001.871.2_BUD	100401_1.0001.1891_BUD
100401_1.0001.872/1.1_BUD	100401_1.0001.1892_BUD
100401_1.0001.872/1.2_BUD	100401_1.0001.1893_BUD
100401_1.0001.872/2.1_BUD	100401_1.0001.1894_BUD
100401_1.0001.873.1_BUD	100401_1.0001.1895_BUD
100401_1.0001.873.2_BUD	100401_1.0001.1896_BUD
100401_1.0001.873.3_BUD	100401_1.0001.1897_BUD
100401_1.0001.875/1.1_BUD	100401_1.0001.1898_BUD
100401_1.0001.875/4.1_BUD	100401_1.0001.1899_BUD
100401_1.0001.875/4.2_BUD	100401_1.0001.1900_BUD
100401_1.0001.875/5.1_BUD	100401_1.0001.1901_BUD
100401_1.0001.875/5.2_BUD	100401_1.0001.1902_BUD
100401_1.0001.875/5.3_BUD	100401_1.0001.1903_BUD
100401_1.0001.875/5.4_BUD	100401_1.0001.1904_BUD
100401_1.0001.875/7.1_BUD	100401_1.0001.1905_BUD
100401_1.0001.875/8.1_BUD	100401_1.0001.1906_BUD
100401_1.0001.875/12.1_BUD	100401_1.0001.1907_BUD
100401_1.0001.875/13.1_BUD	100401_1.0001.1908_BUD
100401_1.0001.875/13.3_BUD	100401_1.0001.1909_BUD
100401_1.0001.875/13.4_BUD	100401_1.0001.1910_BUD
100401_1.0001.877.5_BUD	100401_1.0001.1911_BUD
100401_1.0001.877.6_BUD	100401_1.0001.1912_BUD
100401_1.0001.879/6.1_BUD	100401_1.0001.1913_BUD
100401_1.0001.879/7.2_BUD	100401_1.0001.1914_BUD
100401_1.0001.879/15.1_BUD	100401_1.0001.1915_BUD
100401_1.0001.879/16.1_BUD	100401_1.0001.1916_BUD
100401_1.0001.881.1_BUD	100401_1.0001.1917_BUD
100401_1.0001.881.2_BUD	100401_1.0001.1918_BUD
100401_1.0001.881.3_BUD	100401_1.0001.1919_BUD
100401_1.0001.881/1.1_BUD	100401_1.0001.1920_BUD
100401_1.0001.882.1_BUD	100401_1.0001.1921_BUD
100401_1.0001.883/1.1_BUD	100401_1.0001.1922_BUD
100401_1.0001.884/1.1_BUD	100401_1.0001.1923_BUD
100401_1.0001.884/1.2_BUD	100401_1.0001.1924_BUD
100401_1.0001.884/2.1_BUD	100401_1.0001.1925_BUD
100401_1.0001.885.1_BUD	100401_1.0001.1926_BUD
100401_1.0001.885.2_BUD	100401_1.0001.1927_BUD
100401_1.0001.885.3_BUD	100401_1.0001.1928_BUD
100401_1.0001.885.4_BUD	100401_1.0001.1929_BUD
100401_1.0001.885.5_BUD	100401_1.0001.1930_BUD
100401_1.0001.885.6_BUD	100401_1.0001.1931_BUD
100401_1.0001.886.1_BUD	100401_1.0001.1932_BUD
100401_1.0001.886.2_BUD	100401_1.0001.1933_BUD
100401_1.0001.886.3_BUD	100401_1.0001.1934_BUD
100401_1.0001.886.4_BUD	100401_1.0001.1935_BUD
100401_1.0001.886.5_BUD	100401_1.0001.1936_BUD
100401_1.0001.887.1_BUD	100401_1.0001.1937_BUD
100401_1.0001.887.2_BUD	100401_1.0001.1938_BUD
100401_1.0001.887.3_BUD	100401_1.0001.1939_BUD
100401_1.0001.888.1_BUD	100401_1.0001.1940_BUD
100401_1.0001.888.2_BUD	100401_1.0001.1941_BUD
100401_1.0001.891.1_BUD	100401_1.0001.1942_BUD
100401_1.0001.891.2_BUD	100401_1.0001.1943_BUD

100401_1.0001.892.1_BUD	100401_1.0001.1944_BUD
100401_1.0001.892.2_BUD	100401_1.0001.1945_BUD
100401_1.0001.893.1_BUD	100401_1.0001.1946_BUD
100401_1.0001.893.2_BUD	100401_1.0001.1947_BUD
100401_1.0001.893.3_BUD	100401_1.0001.1948_BUD
100401_1.0001.893.4_BUD	100401_1.0001.1949_BUD
100401_1.0001.893.5_BUD	100401_1.0001.1950_BUD
100401_1.0001.893.6_BUD	100401_1.0001.1951_BUD
100401_1.0001.893.7_BUD	100401_1.0001.1952_BUD
100401_1.0001.895.3_BUD	100401_1.0001.1953_BUD
100401_1.0001.895.4_BUD	100401_1.0001.1954_BUD
100401_1.0001.896.1_BUD	100401_1.0001.1955_BUD
100401_1.0001.896.2_BUD	100401_1.0001.1956_BUD
100401_1.0001.897.1_BUD	100401_1.0001.1957_BUD
100401_1.0001.897.2_BUD	100401_1.0001.1958_BUD
100401_1.0001.898.1_BUD	100401_1.0001.1959_BUD
100401_1.0001.898.2_BUD	100401_1.0001.1960_BUD
100401_1.0001.898.3_BUD	100401_1.0001.1961_BUD
100401_1.0001.898.4_BUD	100401_1.0001.1962_BUD
100401_1.0001.899.1_BUD	100401_1.0001.1963_BUD
100401_1.0001.899.2_BUD	100401_1.0001.1964_BUD
100401_1.0001.900.1_BUD	100401_1.0001.1965_BUD
100401_1.0001.900.2_BUD	100401_1.0001.1966_BUD
100401_1.0001.901.3_BUD	100401_1.0001.1967_BUD
100401_1.0001.901.4_BUD	100401_1.0001.1968_BUD
100401_1.0001.902.1_BUD	100401_1.0001.1969_BUD
100401_1.0001.902.2_BUD	100401_1.0001.1970_BUD
100401_1.0001.902.3_BUD	100401_1.0001.1971_BUD
100401_1.0001.902/2.1_BUD	100401_1.0001.1972_BUD
100401_1.0001.904/2.1_BUD	100401_1.0001.1973_BUD
100401_1.0001.904/2.2_BUD	100401_1.0001.1974_BUD
100401_1.0001.904/3.1_BUD	100401_1.0001.1975_BUD
100401_1.0001.904/3.2_BUD	100401_1.0001.1976_BUD
100401_1.0001.904/4.1_BUD	100401_1.0001.1977_BUD
100401_1.0001.904/4.2_BUD	100401_1.0001.1978_BUD
100401_1.0001.905/1.1_BUD	100401_1.0001.1979_BUD
100401_1.0001.905/1.2_BUD	100401_1.0001.1980_BUD
100401_1.0001.905/1.3_BUD	100401_1.0001.1981_BUD
100401_1.0001.905/1.4_BUD	100401_1.0001.1982_BUD
100401_1.0001.905/1.5_BUD	100401_1.0001.1983_BUD
100401_1.0001.905/2.1_BUD	100401_1.0001.1984_BUD
100401_1.0001.905/2.2_BUD	100401_1.0001.1985_BUD
100401_1.0001.906.1_BUD	100401_1.0001.1986_BUD
100401_1.0001.906.2_BUD	100401_1.0001.1987_BUD
100401_1.0001.907/1.1_BUD	100401_1.0001.1988_BUD
100401_1.0001.907/1.2_BUD	100401_1.0001.1989_BUD
100401_1.0001.907/2.1_BUD	100401_1.0001.1990_BUD
100401_1.0001.907/2.2_BUD	100401_1.0001.1991_BUD
100401_1.0001.907/4.1_BUD	100401_1.0001.1992_BUD
100401_1.0001.907/4.2_BUD	100401_1.0001.1993_BUD
100401_1.0001.908/1.1_BUD	100401_1.0001.1994_BUD
100401_1.0001.908/2.1_BUD	100401_1.0001.1995_BUD
100401_1.0001.909.2_BUD	100401_1.0001.1996_BUD
100401_1.0001.910/2.1_BUD	100401_1.0001.1997_BUD

100401_1.0001.910/2.2_BUD	100401_1.0001.1998_BUD
100401_1.0001.911.1_BUD	100401_1.0001.1999_BUD
100401_1.0001.911.2_BUD	100401_1.0001.2000_BUD
100401_1.0001.912.1_BUD	100401_1.0001.2001_BUD
100401_1.0001.912.2_BUD	100401_1.0001.2002_BUD
100401_1.0001.913.1_BUD	100401_1.0001.2003_BUD
100401_1.0001.913.2_BUD	100401_1.0001.2004_BUD
100401_1.0001.914.1_BUD	100401_1.0001.2005_BUD
100401_1.0001.914.2_BUD	100401_1.0001.2006_BUD
100401_1.0001.915.1_BUD	100401_1.0001.2007_BUD
100401_1.0001.915.2_BUD	100401_1.0001.2008_BUD
100401_1.0001.915.3_BUD	100401_1.0001.2009_BUD
100401_1.0001.917.1_BUD	100401_1.0001.2010_BUD
100401_1.0001.917.2_BUD	100401_1.0001.2011_BUD
100401_1.0001.922/2.1_BUD	100401_1.0001.2012_BUD
100401_1.0001.923/8.1_BUD	100401_1.0001.2013_BUD
100401_1.0001.923/10.1_BUD	100401_1.0001.2014_BUD
100401_1.0001.923/10.2_BUD	100401_1.0001.2015_BUD
100401_1.0001.923/12.1_BUD	100401_1.0001.2016_BUD
100401_1.0001.924/2.1_BUD	100401_1.0001.2017_BUD
100401_1.0001.925/1.1_BUD	100401_1.0001.2018_BUD
100401_1.0001.925/1.2_BUD	100401_1.0001.2019_BUD
100401_1.0001.926/1.1_BUD	100401_1.0001.2020_BUD
100401_1.0001.926/1.2_BUD	100401_1.0001.2021_BUD
100401_1.0001.928.1_BUD	100401_1.0001.2022_BUD
100401_1.0001.928.2_BUD	100401_1.0001.2023_BUD
100401_1.0001.928.3_BUD	100401_1.0001.2024_BUD
100401_1.0001.929.1_BUD	100401_1.0001.2025_BUD
100401_1.0001.929.2_BUD	100401_1.0001.2026_BUD
100401_1.0001.930/1.1_BUD	100401_1.0001.2027_BUD
100401_1.0001.930/1.2_BUD	100401_1.0001.2028_BUD
100401_1.0001.930/1.3_BUD	100401_1.0001.2029_BUD
100401_1.0001.931/2.1_BUD	100401_1.0001.2030_BUD
100401_1.0001.931/2.2_BUD	100401_1.0001.2031_BUD
100401_1.0001.931/2.4_BUD	100401_1.0001.2032_BUD
100401_1.0001.931/2.5_BUD	100401_1.0001.2033_BUD
100401_1.0001.931/3.1_BUD	100401_1.0001.2034_BUD
100401_1.0001.931/3.2_BUD	100401_1.0001.2035_BUD
100401_1.0001.934/1.1_BUD	100401_1.0001.2036_BUD
100401_1.0001.934/3.1_BUD	100401_1.0001.2037_BUD
100401_1.0001.935.1_BUD	100401_1.0001.2038_BUD
100401_1.0001.935.2_BUD	100401_1.0001.2039_BUD
100401_1.0001.935.4_BUD	100401_1.0001.2040_BUD
100401_1.0001.935.5_BUD	100401_1.0001.2041_BUD
100401_1.0001.936.1_BUD	100401_1.0001.2042_BUD
100401_1.0001.937.1_BUD	100401_1.0001.2043_BUD
100401_1.0001.937.2_BUD	100401_1.0001.2044_BUD
100401_1.0001.937.3_BUD	100401_1.0001.2045_BUD
100401_1.0001.937.4_BUD	100401_1.0001.2046_BUD
100401_1.0001.937.5_BUD	100401_1.0001.2047_BUD
100401_1.0001.938/1.1_BUD	100401_1.0001.2048_BUD
100401_1.0001.938/2.1_BUD	100401_1.0001.2049_BUD
100401_1.0001.938/2.2_BUD	100401_1.0001.2050_BUD
100401_1.0001.938/2.3_BUD	100401_1.0001.2051_BUD

100401_1.0001.938/2.4_BUD	100401_1.0001.2052_BUD
100401_1.0001.938/2.5_BUD	100401_1.0001.2053_BUD
100401_1.0001.938/2.6_BUD	100401_1.0001.2054_BUD
100401_1.0001.939.1_BUD	100401_1.0001.2055_BUD
100401_1.0001.939.2_BUD	100401_1.0001.2056_BUD
100401_1.0001.939.3_BUD	100401_1.0001.2057_BUD
100401_1.0001.940.1_BUD	100401_1.0001.2058_BUD
100401_1.0001.940.2_BUD	100401_1.0001.2059_BUD
100401_1.0001.940.3_BUD	100401_1.0001.2060_BUD
100401_1.0001.941/1.1_BUD	100401_1.0001.2061_BUD
100401_1.0001.941/1.2_BUD	100401_1.0001.2062_BUD
100401_1.0001.941/1.3_BUD	100401_1.0001.2063_BUD
100401_1.0001.942.1_BUD	100401_1.0001.2064_BUD
100401_1.0001.942.2_BUD	100401_1.0001.2065_BUD
100401_1.0001.942.6_BUD	100401_1.0001.2066_BUD
100401_1.0001.942.7_BUD	100401_1.0001.2067_BUD
100401_1.0001.942.8_BUD	100401_1.0001.2068_BUD
100401_1.0001.943.1_BUD	100401_1.0001.2069_BUD
100401_1.0001.943.2_BUD	100401_1.0001.2070_BUD
100401_1.0001.943.3_BUD	100401_1.0001.2071_BUD
100401_1.0001.943.4_BUD	100401_1.0001.2072_BUD
100401_1.0001.944.1_BUD	100401_1.0001.2073_BUD
100401_1.0001.944.2_BUD	100401_1.0001.2074_BUD
100401_1.0001.944.4_BUD	100401_1.0001.2075_BUD
100401_1.0001.945/2.5_BUD	100401_1.0001.2076_BUD
100401_1.0001.945/2.7_BUD	100401_1.0001.2077_BUD
100401_1.0001.945/2.8_BUD	100401_1.0001.2078_BUD
100401_1.0001.945/3.1_BUD	100401_1.0001.2079_BUD
100401_1.0001.945/3.2_BUD	100401_1.0001.2080_BUD
100401_1.0001.945/3.3_BUD	100401_1.0001.2081_BUD
100401_1.0001.946/1.1_BUD	100401_1.0001.2082_BUD
100401_1.0001.946/1.2_BUD	100401_1.0001.2083_BUD
100401_1.0001.946/1.3_BUD	100401_1.0001.2084_BUD
100401_1.0001.946/1.4_BUD	100401_1.0001.2085_BUD
100401_1.0001.946/1.5_BUD	100401_1.0001.2086_BUD
100401_1.0001.946/1.6_BUD	100401_1.0001.2087_BUD
100401_1.0001.946/1.7_BUD	100401_1.0001.2088_BUD
100401_1.0001.946/2.1_BUD	100401_1.0001.2089_BUD
100401_1.0001.946/2.2_BUD	100401_1.0001.2090_BUD
100401_1.0001.946/2.3_BUD	100401_1.0001.2091_BUD
100401_1.0001.950.1_BUD	100401_1.0001.2092_BUD
100401_1.0001.950.2_BUD	100401_1.0001.2093_BUD
100401_1.0001.950.3_BUD	100401_1.0001.2094_BUD
100401_1.0001.952.1_BUD	100401_1.0001.2095_BUD
100401_1.0001.952.2_BUD	100401_1.0001.2096_BUD
100401_1.0001.954.1_BUD	100401_1.0001.2097_BUD
100401_1.0001.954.2_BUD	100401_1.0001.2098_BUD
100401_1.0001.1024.1_BUD	100401_1.0001.2099_BUD
100401_1.0001.1024.2_BUD	100401_1.0001.2100_BUD
100401_1.0001.1024.3_BUD	100401_1.0001.2101_BUD
100401_1.0001.1024.4_BUD	100401_1.0001.2102_BUD
100401_1.0001.1024.5_BUD	100401_1.0001.2103_BUD
100401_1.0001.1025/1.1_BUD	100401_1.0001.2104_BUD
100401_1.0001.1025/1.2_BUD	100401_1.0001.2105_BUD

100401_1.0001.1037/1.1_BUD	100401_1.0001.2106_BUD
100401_1.0001.1037/1.2_BUD	100401_1.0001.2107_BUD
100401_1.0001.1037/1.3_BUD	100401_1.0001.2108_BUD
100401_1.0001.1037/3.1_BUD	100401_1.0001.2109_BUD
100401_1.0001.1038.1_BUD	100401_1.0001.2110_BUD
100401_1.0001.1038.2_BUD	100401_1.0001.2111_BUD
100401_1.0001.1038.3_BUD	100401_1.0001.2112_BUD
100401_1.0001.1038.4_BUD	100401_1.0001.2113_BUD
100401_1.0001.1039.1_BUD	100401_1.0001.2114_BUD
100401_1.0001.1039.2_BUD	100401_1.0001.2115_BUD
100401_1.0001.1039.3_BUD	100401_1.0001.2116_BUD
100401_1.0001.1040.1_BUD	100401_1.0001.2117_BUD
100401_1.0001.1040.2_BUD	100401_1.0001.2118_BUD
100401_1.0001.1041.1_BUD	100401_1.0001.2119_BUD
100401_1.0001.1041.3_BUD	100401_1.0001.2120_BUD
100401_1.0001.1041.5_BUD	100401_1.0001.2121_BUD
100401_1.0001.1041.6_BUD	100401_1.0001.2122_BUD
100401_1.0001.1041.7_BUD	100401_1.0001.2123_BUD
100401_1.0001.1043/1.4_BUD	100401_1.0001.2124_BUD
100401_1.0001.1045.1_BUD	100401_1.0001.2125_BUD
100401_1.0001.1045.2_BUD	100401_1.0001.2126_BUD
100401_1.0001.1045.3_BUD	100401_1.0001.2127_BUD
100401_1.0001.1051/2.1_BUD	100401_1.0001.2128_BUD
100401_1.0001.1056.1_BUD	100401_1.0001.2129_BUD
100401_1.0001.1056.2_BUD	100401_1.0001.2130_BUD
100401_1.0001.1056.3_BUD	100401_1.0001.2131_BUD
100401_1.0001.1056.4_BUD	100401_1.0001.2132_BUD
100401_1.0001.1056.5_BUD	100401_1.0001.2133_BUD
100401_1.0001.1056.6_BUD	100401_1.0001.2134_BUD
100401_1.0001.1057.1_BUD	100401_1.0001.2135_BUD
100401_1.0001.1057.2_BUD	100401_1.0001.2136_BUD
100401_1.0001.1057.3_BUD	100401_1.0001.2137_BUD
100401_1.0001.1057.4_BUD	100401_1.0001.2138_BUD
100401_1.0001.1057.5_BUD	100401_1.0001.2139_BUD
100401_1.0001.1057.6_BUD	100401_1.0001.2140_BUD
100401_1.0001.1057.7_BUD	100401_1.0001.2141_BUD
100401_1.0001.1057/2.1_BUD	100401_1.0001.2142_BUD
100401_1.0001.1058.1_BUD	100401_1.0001.2143_BUD
100401_1.0001.1058.2_BUD	100401_1.0001.2144_BUD
100401_1.0001.1058.3_BUD	100401_1.0001.2145_BUD
100401_1.0001.1060.1_BUD	100401_1.0001.2146_BUD
100401_1.0001.1060.2_BUD	100401_1.0001.2147_BUD
100401_1.0001.1060.3_BUD	100401_1.0001.2148_BUD
100401_1.0001.1060.4_BUD	100401_1.0001.2149_BUD
100401_1.0001.1060.5_BUD	100401_1.0001.2150_BUD
100401_1.0001.1060.6_BUD	100401_1.0001.2151_BUD
100401_1.0001.1060.7_BUD	100401_1.0001.2152_BUD
100401_1.0001.1060.8_BUD	100401_1.0001.2153_BUD
100401_1.0001.1060.9_BUD	100401_1.0001.2154_BUD
100401_1.0001.1060.10_BUD	100401_1.0001.2155_BUD
100401_1.0001.1060.11_BUD	100401_1.0001.2156_BUD
100401_1.0001.1060.12_BUD	100401_1.0001.2157_BUD
100401_1.0001.1060.13_BUD	100401_1.0001.2158_BUD
100401_1.0001.1060.14_BUD	100401_1.0001.2159_BUD

100401_1.0001.1060.15_BUD	100401_1.0001.2160_BUD
100401_1.0001.1096/3.1_BUD	100401_1.0001.2161_BUD
100401_1.0001.1096/3.2_BUD	100401_1.0001.2162_BUD
100401_1.0001.1096/3.3_BUD	100401_1.0001.2163_BUD
100401_1.0001.1136/2.1_BUD	100401_1.0001.2164_BUD
100401_1.0001.1136/2.3_BUD	100401_1.0001.2165_BUD
100401_1.0001.1136/2.4_BUD	100401_1.0001.2166_BUD
100401_1.0001.1138/1.1_BUD	100401_1.0001.2167_BUD
100401_1.0001.1138/2.1_BUD	100401_1.0001.2168_BUD
100401_1.0001.1138/2.2_BUD	100401_1.0001.2169_BUD
100401_1.0001.1138/2.3_BUD	100401_1.0001.2170_BUD
100401_1.0001.1138/2.4_BUD	100401_1.0001.2171_BUD
100401_1.0001.1138/2.5_BUD	100401_1.0001.2172_BUD
100401_1.0001.1139/1.7_BUD	100401_1.0001.2173_BUD
100401_1.0001.1139/2.1_BUD	100401_1.0001.2174_BUD
100401_1.0001.1140.1_BUD	100401_1.0001.2175_BUD
100401_1.0001.1140.2_BUD	100401_1.0001.2176_BUD
100401_1.0001.1140.3_BUD	100401_1.0001.2177_BUD
100401_1.0001.1140.4_BUD	100401_1.0001.2178_BUD
100401_1.0001.1144/3.1_BUD	100401_1.0001.2179_BUD
100401_1.0001.1144/4.1_BUD	100401_1.0001.2180_BUD
100401_1.0001.1144/4.2_BUD	100401_1.0001.2181_BUD
100401_1.0001.1144/5.1_BUD	100401_1.0001.2182_BUD
100401_1.0001.1146.1_BUD	100401_1.0001.2183_BUD
100401_1.0001.1146.2_BUD	100401_1.0001.2184_BUD
100401_1.0001.1146.3_BUD	100401_1.0001.2185_BUD
100401_1.0001.1151/1.1_BUD	100401_1.0001.2186_BUD
100401_1.0001.1151/1.2_BUD	100401_1.0001.2187_BUD
100401_1.0001.1151/1.3_BUD	100401_1.0001.2188_BUD
100401_1.0001.1151/1.4_BUD	100401_1.0001.2189_BUD
100401_1.0001.1151/1.5_BUD	100401_1.0001.2190_BUD
100401_1.0001.1151/1.6_BUD	100401_1.0001.2191_BUD
100401_1.0001.1153/3.1_BUD	100401_1.0001.2192_BUD
100401_1.0001.1171/4.1_BUD	100401_1.0001.2193_BUD
100401_1.0001.1171/4.2_BUD	100401_1.0001.2194_BUD
100401_1.0001.1171/4.3_BUD	100401_1.0001.2195_BUD
100401_1.0001.1171/6.1_BUD	100401_1.0001.2196_BUD
100401_1.0001.1171/6.2_BUD	100401_1.0001.2197_BUD
100401_1.0001.1171/6.3_BUD	100401_1.0001.2198_BUD
100401_1.0001.1171/6.5_BUD	100401_1.0001.2199_BUD
100401_1.0001.1171/6.6_BUD	100401_1.0001.2200_BUD
100401_1.0001.1171/6.7_BUD	100401_1.0001.2201_BUD
100401_1.0001.1185.1_BUD	100401_1.0001.2202_BUD
100401_1.0001.1185.2_BUD	100401_1.0001.2203_BUD
100401_1.0001.1185.3_BUD	100401_1.0001.2204_BUD
100401_1.0001.1185.4_BUD	100401_1.0001.2205_BUD
100401_1.0001.1185.5_BUD	100401_1.0001.2206_BUD
100401_1.0001.1185.6_BUD	100401_1.0001.2207_BUD
100401_1.0001.1186.1_BUD	100401_1.0001.2208_BUD
100401_1.0001.1186.2_BUD	100401_1.0001.2209_BUD
100401_1.0001.1190/2.1_BUD	100401_1.0001.2210_BUD
100401_1.0001.1236.1_BUD	100401_1.0001.2211_BUD
100401_1.0001.1236.2_BUD	100401_1.0001.2212_BUD
100401_1.0001.1237/8.1_BUD	100401_1.0001.2213_BUD

100401_1.0001.1240.1_BUD	100401_1.0001.2214_BUD
100401_1.0001.1240.2_BUD	100401_1.0001.2215_BUD
100401_1.0001.1240.3_BUD	100401_1.0001.2216_BUD
100401_1.0001.1241.1_BUD	100401_1.0001.2217_BUD
100401_1.0001.1244.1_BUD	100401_1.0001.2218_BUD
100401_1.0001.1244.2_BUD	100401_1.0001.2219_BUD
100401_1.0001.1245.1_BUD	100401_1.0001.2220_BUD
100401_1.0001.1245.2_BUD	100401_1.0001.2221_BUD
100401_1.0001.1245.3_BUD	100401_1.0001.2222_BUD
100401_1.0001.1245.4_BUD	100401_1.0001.2223_BUD
100401_1.0001.1245.5_BUD	100401_1.0001.2224_BUD
100401_1.0001.1246.1_BUD	100401_1.0001.2225_BUD
100401_1.0001.1246.2_BUD	100401_1.0001.2226_BUD
100401_1.0001.1246.3_BUD	100401_1.0001.2227_BUD
100401_1.0001.1246.4_BUD	100401_1.0001.2228_BUD
100401_1.0001.1249/1.1_BUD	100401_1.0001.2229_BUD
100401_1.0001.1249/1.2_BUD	100401_1.0001.2230_BUD
100401_1.0001.1249/1.3_BUD	100401_1.0001.2231_BUD
100401_1.0001.1253.1_BUD	100401_1.0001.2232_BUD
100401_1.0001.1253.2_BUD	100401_1.0001.2233_BUD
100401_1.0001.1253.3_BUD	100401_1.0001.2234_BUD
100401_1.0001.1255/2.1_BUD	100401_1.0001.2235_BUD
100401_1.0001.1255/3.1_BUD	100401_1.0001.2236_BUD
100401_1.0001.1255/4.1_BUD	100401_1.0001.2237_BUD
100401_1.0001.1255/5.1_BUD	100401_1.0001.2238_BUD
100401_1.0001.1255/6.1_BUD	100401_1.0001.2239_BUD
100401_1.0001.1255/7.1_BUD	100401_1.0001.2240_BUD
100401_1.0001.1255/7.2_BUD	100401_1.0001.2241_BUD
100401_1.0001.1256/2.1_BUD	100401_1.0001.2242_BUD
100401_1.0001.1256/3.1_BUD	100401_1.0001.2243_BUD
100401_1.0001.1256/4.2_BUD	100401_1.0001.2244_BUD
100401_1.0001.1257.1_BUD	100401_1.0001.2245_BUD
100401_1.0001.1257.2_BUD	100401_1.0001.2246_BUD
100401_1.0001.1257.3_BUD	100401_1.0001.2247_BUD
100401_1.0001.1258.1_BUD	100401_1.0001.2248_BUD
100401_1.0001.1258.2_BUD	100401_1.0001.2249_BUD
100401_1.0001.1258.4_BUD	100401_1.0001.2250_BUD
100401_1.0001.1258.7_BUD	100401_1.0001.2251_BUD
100401_1.0001.1262.1_BUD	100401_1.0001.2252_BUD
100401_1.0001.1262.2_BUD	100401_1.0001.2253_BUD
100401_1.0001.1263.1_BUD	100401_1.0001.2254_BUD
100401_1.0001.1263.2_BUD	100401_1.0001.2255_BUD
100401_1.0001.1264.1_BUD	100401_1.0001.2256_BUD
100401_1.0001.1264.2_BUD	100401_1.0001.2257_BUD
100401_1.0001.1264.3_BUD	100401_1.0001.2258_BUD
100401_1.0001.1265.1_BUD	100401_1.0001.2259_BUD
100401_1.0001.1265.2_BUD	100401_1.0001.2260_BUD
100401_1.0001.1267.1_BUD	100401_1.0001.2261_BUD
100401_1.0001.1267.2_BUD	100401_1.0001.2262_BUD
100401_1.0001.1268.1_BUD	100401_1.0001.2263_BUD
100401_1.0001.1268.2_BUD	100401_1.0001.2264_BUD
100401_1.0001.1269.1_BUD	100401_1.0001.2265_BUD
100401_1.0001.1269.2_BUD	100401_1.0001.2266_BUD
100401_1.0001.1270.1_BUD	100401_1.0001.2267_BUD

100401_1.0001.1271.1_BUD	100401_1.0001.2268_BUD
100401_1.0001.1271.2_BUD	100401_1.0001.2269_BUD
100401_1.0001.1272.1_BUD	100401_1.0001.2270_BUD
100401_1.0001.1272.2_BUD	100401_1.0001.2271_BUD
100401_1.0001.1273.1_BUD	100401_1.0001.2272_BUD
100401_1.0001.1273.2_BUD	100401_1.0001.2273_BUD
100401_1.0001.1274.1_BUD	100401_1.0001.2274_BUD
100401_1.0001.1274.2_BUD	100401_1.0001.2275_BUD
100401_1.0001.1274.3_BUD	100401_1.0001.2276_BUD
100401_1.0001.1275.1_BUD	100401_1.0001.2277_BUD
100401_1.0001.1275.2_BUD	100401_1.0001.2278_BUD
100401_1.0001.1279.1_BUD	100401_1.0001.2279_BUD
100401_1.0001.1280.1_BUD	100401_1.0001.2280_BUD
100401_1.0001.1280.2_BUD	100401_1.0001.2281_BUD
100401_1.0001.1281.1_BUD	100401_1.0001.2282_BUD
100401_1.0001.1281.2_BUD	100401_1.0001.2283_BUD
100401_1.0001.1281.3_BUD	100401_1.0001.2284_BUD
100401_1.0001.1282.1_BUD	100401_1.0001.2285_BUD
100401_1.0001.1282.2_BUD	100401_1.0001.2286_BUD
100401_1.0001.1283.1_BUD	100401_1.0001.2287_BUD
100401_1.0001.1284.1_BUD	100401_1.0001.2288_BUD
100401_1.0001.1284.2_BUD	100401_1.0001.2289_BUD
100401_1.0001.1284.3_BUD	100401_1.0001.2290_BUD
100401_1.0001.1286.1_BUD	100401_1.0001.2291_BUD
100401_1.0001.1286.2_BUD	100401_1.0001.2292_BUD
100401_1.0001.1286.3_BUD	100401_1.0001.2293_BUD
100401_1.0001.1287.1_BUD	100401_1.0001.2294_BUD
100401_1.0001.1287.2_BUD	100401_1.0001.2295_BUD
100401_1.0001.1288/3.1_BUD	100401_1.0001.2296_BUD
100401_1.0001.1288/3.2_BUD	100401_1.0001.2297_BUD
100401_1.0001.1288/3.3_BUD	100401_1.0001.2298_BUD
100401_1.0001.1288/3.4_BUD	100401_1.0001.2299_BUD
100401_1.0001.1289/1.1_BUD	100401_1.0001.2300_BUD
100401_1.0001.1289/1.4_BUD	100401_1.0001.2301_BUD
100401_1.0001.1289/1.5_BUD	100401_1.0001.2302_BUD
100401_1.0001.1289/1.6_BUD	100401_1.0001.2303_BUD
100401_1.0001.1292/1.1_BUD	100401_1.0001.2304_BUD
100401_1.0001.1292/4.1_BUD	100401_1.0001.2305_BUD
100401_1.0001.1292/6.1_BUD	100401_1.0001.2306_BUD
100401_1.0001.1292/11.1_BUD	100401_1.0001.2307_BUD
100401_1.0001.1292/11.2_BUD	100401_1.0001.2308_BUD
100401_1.0001.1292/11.3_BUD	100401_1.0001.2309_BUD
100401_1.0001.1292/12.1_BUD	100401_1.0001.2310_BUD
100401_1.0001.1292/14.1_BUD	100401_1.0001.2311_BUD
100401_1.0001.1292/15.1_BUD	100401_1.0001.2312_BUD
100401_1.0001.1292/16.3_BUD	100401_1.0001.2313_BUD
100401_1.0001.1292/20.1_BUD	100401_1.0001.2314_BUD
100401_1.0001.1292/22.1_BUD	100401_1.0001.2315_BUD
100401_1.0001.1292/26.1_BUD	100401_1.0001.2316_BUD
100401_1.0001.1292/27.1_BUD	100401_1.0001.2317_BUD
100401_1.0001.1292/28.1_BUD	100401_1.0001.2318_BUD
100401_1.0001.1292/28.2_BUD	100401_1.0001.2319_BUD
100401_1.0001.1292/28.3_BUD	100401_1.0001.2320_BUD
100401_1.0001.1292/31.1_BUD	100401_1.0001.2321_BUD

100401_1.0001.1292/31.2_BUD	100401_1.0001.2322_BUD
100401_1.0001.1292/31.3_BUD	100401_1.0001.2323_BUD
100401_1.0001.1292/31.4_BUD	100401_1.0001.2324_BUD
100401_1.0001.1292/31.5_BUD	100401_1.0001.2325_BUD
100401_1.0001.1292/31.7_BUD	100401_1.0001.2326_BUD
100401_1.0001.1293/7.1_BUD	100401_1.0001.2327_BUD
100401_1.0001.1293/8.1_BUD	100401_1.0001.2328_BUD
100401_1.0001.1293/11.1_BUD	100401_1.0001.2329_BUD
100401_1.0001.1293/12.1_BUD	100401_1.0001.2330_BUD
100401_1.0001.1293/19.1_BUD	100401_1.0001.2331_BUD
100401_1.0001.1293/21.1_BUD	100401_1.0001.2332_BUD
100401_1.0001.1293/42.1_BUD	100401_1.0001.2333_BUD
100401_1.0001.1293/44.1_BUD	100401_1.0001.2334_BUD
100401_1.0001.1293/45.1_BUD	100401_1.0001.2335_BUD
100401_1.0001.1293/47.1_BUD	100401_1.0001.2336_BUD
100401_1.0001.1293/48.1_BUD	100401_1.0001.2337_BUD
100401_1.0001.1293/49.1_BUD	100401_1.0001.2338_BUD
100401_1.0001.1293/51.1_BUD	100401_1.0001.2339_BUD
100401_1.0001.1293/52.1_BUD	100401_1.0001.2340_BUD
100401_1.0001.1293/53.1_BUD	100401_1.0001.2341_BUD
100401_1.0001.1293/54.1_BUD	100401_1.0001.2342_BUD
100401_1.0001.1293/55.1_BUD	100401_1.0001.2343_BUD
100401_1.0001.1293/56.1_BUD	100401_1.0001.2344_BUD
100401_1.0001.1293/58.1_BUD	100401_1.0001.2345_BUD
100401_1.0001.1293/59.1_BUD	100401_1.0001.2346_BUD
100401_1.0001.1293/61.1_BUD	100401_1.0001.2347_BUD
100401_1.0001.1293/65.1_BUD	100401_1.0001.2348_BUD
100401_1.0001.1293/68.1_BUD	100401_1.0001.2349_BUD
100401_1.0001.1293/78.1_BUD	100401_1.0001.2350_BUD
100401_1.0001.1293/79.1_BUD	100401_1.0001.2351_BUD
100401_1.0001.1293/80.1_BUD	100401_1.0001.2352_BUD
100401_1.0001.1293/81.1_BUD	100401_1.0001.2353_BUD
100401_1.0001.1293/84.1_BUD	100401_1.0001.2354_BUD
100401_1.0001.1293/87.1_BUD	100401_1.0001.2355_BUD
100401_1.0001.1293/89.1_BUD	100401_1.0001.2356_BUD
100401_1.0001.1293/92.1_BUD	100401_1.0001.2357_BUD
100401_1.0001.1293/99.1_BUD	100401_1.0001.2358_BUD
100401_1.0001.1293/102.1_BUD	100401_1.0001.2359_BUD
100401_1.0001.1293/102.2_BUD	100401_1.0001.2360_BUD
100401_1.0001.1293/102.3_BUD	100401_1.0001.2361_BUD
100401_1.0001.1293/102.4_BUD	100401_1.0001.2362_BUD
100401_1.0001.1293/102.5_BUD	100401_1.0001.2363_BUD
100401_1.0001.1293/102.6_BUD	100401_1.0001.2364_BUD
100401_1.0001.1293/102.7_BUD	100401_1.0001.2365_BUD
100401_1.0001.1295.1_BUD	100401_1.0001.2366_BUD
100401_1.0001.1295.2_BUD	100401_1.0001.2367_BUD
100401_1.0001.1296/1.1_BUD	100401_1.0001.2368_BUD
100401_1.0001.1296/1.3_BUD	100401_1.0001.2369_BUD
100401_1.0001.1296/1.4_BUD	100401_1.0001.2370_BUD
100401_1.0001.1296/1.5_BUD	100401_1.0001.2371_BUD
100401_1.0001.1296/2.1_BUD	100401_1.0001.2372_BUD
100401_1.0001.1296/2.2_BUD	100401_1.0001.2373_BUD
100401_1.0001.1301/2.1_BUD	100401_1.0001.2374_BUD
100401_1.0001.1301/3.1_BUD	100401_1.0001.2375_BUD

100401_1.0001.1301/7.1_BUD	100401_1.0001.2376_BUD
100401_1.0001.1301/10.1_BUD	100401_1.0001.2377_BUD
100401_1.0001.1301/12.1_BUD	100401_1.0001.2378_BUD
100401_1.0001.1301/13.1_BUD	100401_1.0001.2379_BUD
100401_1.0001.1310/1.1_BUD	100401_1.0001.2380_BUD
100401_1.0001.1311/3.1_BUD	100401_1.0001.2381_BUD
100401_1.0001.1311/3.2_BUD	100401_1.0001.2382_BUD
100401_1.0001.1311/3.3_BUD	100401_1.0001.2383_BUD
100401_1.0001.1311/3.4_BUD	100401_1.0001.2384_BUD
100401_1.0001.1311/3.5_BUD	100401_1.0001.2385_BUD
100401_1.0001.1311/3.6_BUD	100401_1.0001.2386_BUD
100401_1.0001.1311/3.7_BUD	100401_1.0001.2387_BUD
100401_1.0001.1311/3.8_BUD	100401_1.0001.2388_BUD
100401_1.0001.1311/3.9_BUD	100401_1.0001.2389_BUD
100401_1.0001.1311/3.10_BUD	100401_1.0001.2390_BUD
100401_1.0001.1314.1_BUD	100401_1.0001.2391_BUD
100401_1.0001.1314.2_BUD	100401_1.0001.2392_BUD
100401_1.0001.1315.1_BUD	100401_1.0001.2393_BUD
100401_1.0001.1316.1_BUD	100401_1.0001.2394_BUD
100401_1.0001.1318.1_BUD	100401_1.0001.2395_BUD
100401_1.0001.1318.3_BUD	100401_1.0001.2396_BUD
100401_1.0001.1320.3_BUD	100401_1.0001.2397_BUD
100401_1.0001.1325.1_BUD	100401_1.0001.2398_BUD
100401_1.0001.1336/2.1_BUD	100401_1.0001.2399_BUD
100401_1.0001.1350.1_BUD	100401_1.0001.2400_BUD
100401_1.0001.1351/2.1_BUD	100401_1.0001.2401_BUD
100401_1.0001.1351/2.2_BUD	100401_1.0001.2402_BUD
100401_1.0001.1355.1_BUD	100401_1.0001.2403_BUD
100401_1.0001.1355.3_BUD	100401_1.0001.2404_BUD
100401_1.0001.1355.4_BUD	100401_1.0001.2405_BUD
100401_1.0001.1355.6_BUD	100401_1.0001.2406_BUD
100401_1.0001.1359.1_BUD	100401_1.0001.2407_BUD
100401_1.0001.1359.2_BUD	100401_1.0001.2408_BUD
100401_1.0001.1359.3_BUD	100401_1.0001.2409_BUD
100401_1.0001.1359.4_BUD	100401_1.0001.2410_BUD
100401_1.0001.1359.5_BUD	100401_1.0001.2411_BUD
100401_1.0001.1360.1_BUD	100401_1.0001.2412_BUD
100401_1.0001.1360.2_BUD	100401_1.0001.2413_BUD
100401_1.0001.1361.1_BUD	100401_1.0001.2414_BUD
100401_1.0001.1362.1_BUD	100401_1.0001.2415_BUD
100401_1.0001.1362.2_BUD	100401_1.0001.2416_BUD
100401_1.0001.1363.1_BUD	100401_1.0001.2417_BUD
100401_1.0001.1363.2_BUD	100401_1.0001.2418_BUD
100401_1.0001.1364.1_BUD	100401_1.0001.2419_BUD
100401_1.0001.1364.2_BUD	100401_1.0001.2420_BUD
100401_1.0001.1365.1_BUD	100401_1.0001.2421_BUD
100401_1.0001.1365.2_BUD	100401_1.0001.2422_BUD
100401_1.0001.1366.1_BUD	100401_1.0001.2423_BUD
100401_1.0001.1366.2_BUD	100401_1.0001.2424_BUD
100401_1.0001.1367.1_BUD	100401_1.0001.2425_BUD
100401_1.0001.1367.2_BUD	100401_1.0001.2426_BUD
100401_1.0001.1368/2.1_BUD	100401_1.0001.2427_BUD
100401_1.0001.1368/2.2_BUD	100401_1.0001.2428_BUD
100401_1.0001.1368/2.3_BUD	100401_1.0001.2429_BUD

100401_1.0001.1368/2.4_BUD	100401_1.0001.2430_BUD
100401_1.0001.1368/2.5_BUD	100401_1.0001.2431_BUD
100401_1.0001.1368/2.6_BUD	100401_1.0001.2432_BUD
100401_1.0001.1368/2.7_BUD	100401_1.0001.2433_BUD
100401_1.0001.1368/4.1_BUD	100401_1.0001.2434_BUD
100401_1.0001.1370.1_BUD	100401_1.0001.2435_BUD
100401_1.0001.1370.2_BUD	100401_1.0001.2436_BUD
100401_1.0001.1371.1_BUD	100401_1.0001.2437_BUD
100401_1.0001.1371.2_BUD	100401_1.0001.2438_BUD
100401_1.0001.1372.1_BUD	100401_1.0001.2439_BUD
100401_1.0001.1372.2_BUD	100401_1.0001.2440_BUD
100401_1.0001.1373.1_BUD	100401_1.0001.2441_BUD
100401_1.0001.1373.2_BUD	100401_1.0001.2442_BUD
100401_1.0001.1374.1_BUD	100401_1.0001.2443_BUD
100401_1.0001.1375.1_BUD	100401_1.0001.2444_BUD
100401_1.0001.1376.1_BUD	100401_1.0001.2445_BUD
100401_1.0001.1376.2_BUD	100401_1.0001.2446_BUD
100401_1.0001.1377.1_BUD	100401_1.0001.2447_BUD
100401_1.0001.1377.2_BUD	100401_1.0001.2448_BUD
100401_1.0001.1377.3_BUD	100401_1.0001.2449_BUD
100401_1.0001.1377.4_BUD	100401_1.0001.2450_BUD
100401_1.0001.1378.1_BUD	100401_1.0001.2451_BUD
100401_1.0001.1378.2_BUD	100401_1.0001.2452_BUD
100401_1.0001.1378.3_BUD	100401_1.0001.2453_BUD
100401_1.0001.1379/1.1_BUD	100401_1.0001.2454_BUD
100401_1.0001.1379/1.2_BUD	100401_1.0001.2455_BUD
100401_1.0001.1379/2.1_BUD	100401_1.0001.2456_BUD
100401_1.0001.1380.1_BUD	100401_1.0001.2457_BUD
100401_1.0001.1380.2_BUD	100401_1.0001.2458_BUD
100401_1.0001.1381.1_BUD	100401_1.0001.2459_BUD
100401_1.0001.1381.2_BUD	100401_1.0001.2460_BUD
100401_1.0001.1382.1_BUD	100401_1.0001.2461_BUD
100401_1.0001.1382.2_BUD	100401_1.0001.2462_BUD
100401_1.0001.1382.3_BUD	100401_1.0001.2463_BUD
100401_1.0001.1383.1_BUD	100401_1.0001.2464_BUD
100401_1.0001.1383.2_BUD	100401_1.0001.2465_BUD
100401_1.0001.1384.1_BUD	100401_1.0001.2466_BUD
100401_1.0001.1384.2_BUD	100401_1.0001.2467_BUD
100401_1.0001.1385.1_BUD	100401_1.0001.2468_BUD
100401_1.0001.1385.2_BUD	100401_1.0001.2469_BUD
100401_1.0001.1386.1_BUD	100401_1.0001.2470_BUD
100401_1.0001.1386.2_BUD	100401_1.0001.2471_BUD
100401_1.0001.1387.1_BUD	100401_1.0001.2472_BUD
100401_1.0001.1388.1_BUD	100401_1.0001.2473_BUD
100401_1.0001.1388.2_BUD	100401_1.0001.2474_BUD
100401_1.0001.1388.3_BUD	100401_1.0001.2475_BUD
100401_1.0001.1388.4_BUD	100401_1.0001.2476_BUD
100401_1.0001.1389.1_BUD	100401_1.0001.2477_BUD
100401_1.0001.1389.2_BUD	100401_1.0001.2478_BUD
100401_1.0001.1391.1_BUD	100401_1.0001.2479_BUD
100401_1.0001.1391.2_BUD	100401_1.0001.2480_BUD
100401_1.0001.1391.3_BUD	100401_1.0001.2481_BUD
100401_1.0001.1392.1_BUD	100401_1.0001.2482_BUD
100401_1.0001.1392.2_BUD	100401_1.0001.2483_BUD

100401_1.0001.1392.3_BUD	100401_1.0001.2484_BUD
100401_1.0001.1394.1_BUD	100401_1.0001.2485_BUD
100401_1.0001.1394.2_BUD	100401_1.0001.2486_BUD
100401_1.0001.1394.3_BUD	100401_1.0001.2487_BUD
100401_1.0001.1395.1_BUD	100401_1.0001.2488_BUD
100401_1.0001.1395.2_BUD	100401_1.0001.2489_BUD
100401_1.0001.1397.2_BUD	100401_1.0001.2490_BUD
100401_1.0001.1397/1.1_BUD	100401_1.0001.2491_BUD
100401_1.0001.1397/2.1_BUD	100401_1.0001.2492_BUD
100401_1.0001.1397/2.2_BUD	100401_1.0001.2493_BUD
100401_1.0001.1398.1_BUD	100401_1.0001.2494_BUD
100401_1.0001.1398.2_BUD	100401_1.0001.2495_BUD
100401_1.0001.1402.1_BUD	100401_1.0001.2496_BUD
100401_1.0001.1409/3.1_BUD	100401_1.0001.2497_BUD
100401_1.0001.1409/3.2_BUD	100401_1.0001.2498_BUD
100401_1.0001.1410.1_BUD	100401_1.0001.2499_BUD
100401_1.0001.1410.2_BUD	100401_1.0001.2500_BUD
100401_1.0001.1414/4.1_BUD	100401_1.0001.2501_BUD
100401_1.0001.1414/6.1_BUD	100401_1.0001.2502_BUD
100401_1.0001.1416/2.1_BUD	100401_1.0001.2503_BUD
100401_1.0001.1416/2.4_BUD	100401_1.0001.2504_BUD
100401_1.0001.1418.1_BUD	100401_1.0001.2505_BUD
100401_1.0001.1418.2_BUD	100401_1.0001.2506_BUD
100401_1.0001.1418.7_BUD	100401_1.0001.2507_BUD
100401_1.0001.1418.8_BUD	100401_1.0001.2508_BUD
100401_1.0001.1420/1.1_BUD	100401_1.0001.2509_BUD
100401_1.0001.1420/1.2_BUD	100401_1.0001.2510_BUD
100401_1.0001.1420/1.3_BUD	100401_1.0001.2511_BUD
100401_1.0001.1420/1.4_BUD	100401_1.0001.2512_BUD
100401_1.0001.1420/1.5_BUD	100401_1.0001.2513_BUD
100401_1.0001.1420/1.6_BUD	100401_1.0001.2514_BUD
100401_1.0001.1421/2.1_BUD	100401_1.0001.2515_BUD
100401_1.0001.1421/2.3_BUD	100401_1.0001.2516_BUD
100401_1.0001.1423.1_BUD	100401_1.0001.2517_BUD
100401_1.0001.1423.2_BUD	100401_1.0001.2518_BUD
100401_1.0001.1423.3_BUD	100401_1.0001.2519_BUD
100401_1.0001.1428.1_BUD	100401_1.0001.2520_BUD
100401_1.0001.1428.2_BUD	100401_1.0001.2521_BUD
100401_1.0001.1428.3_BUD	100401_1.0001.2522_BUD
100401_1.0001.1428.4_BUD	100401_1.0001.2523_BUD
100401_1.0001.1429.1_BUD	100401_1.0001.2524_BUD
100401_1.0001.1429.2_BUD	100401_1.0001.2525_BUD
100401_1.0001.1429.3_BUD	100401_1.0001.2526_BUD
100401_1.0001.1429.4_BUD	100401_1.0001.2527_BUD
100401_1.0001.1429.5_BUD	100401_1.0001.2528_BUD
100401_1.0001.1429.6_BUD	100401_1.0001.2529_BUD
100401_1.0001.1429.7_BUD	100401_1.0001.2530_BUD
100401_1.0001.1429.8_BUD	100401_1.0001.2531_BUD
100401_1.0001.1430/1.1_BUD	100401_1.0001.2532_BUD
100401_1.0001.1430/1.2_BUD	100401_1.0001.2533_BUD
100401_1.0001.1430/1.3_BUD	100401_1.0001.2534_BUD
100401_1.0001.1430/1.4_BUD	100401_1.0001.2535_BUD
100401_1.0001.1431.1_BUD	100401_1.0001.2536_BUD
100401_1.0001.1431.2_BUD	100401_1.0001.2537_BUD

100401_1.0001.1432/1.1_BUD	100401_1.0001.2538_BUD
100401_1.0001.1433/1.1_BUD	100401_1.0001.2539_BUD
100401_1.0001.1433/1.2_BUD	100401_1.0001.2540_BUD
100401_1.0001.1433/1.3_BUD	100401_1.0001.2541_BUD
100401_1.0001.1433/1.4_BUD	100401_1.0001.2542_BUD
100401_1.0001.1433/1.5_BUD	100401_1.0001.2543_BUD
100401_1.0001.1433/1.6_BUD	100401_1.0001.2544_BUD
100401_1.0001.1433/1.7_BUD	100401_1.0001.2545_BUD
100401_1.0001.1433/3.1_BUD	100401_1.0001.2546_BUD
100401_1.0001.1433/3.2_BUD	100401_1.0001.2547_BUD
100401_1.0001.1433/3.3_BUD	100401_1.0001.2548_BUD
100401_1.0001.1433/3.4_BUD	100401_1.0001.2549_BUD
100401_1.0001.1433/3.5_BUD	100401_1.0001.2550_BUD
100401_1.0001.1433/4.1_BUD	100401_1.0001.2551_BUD
100401_1.0001.1433/4.2_BUD	100401_1.0001.2552_BUD
100401_1.0001.1433/4.3_BUD	100401_1.0001.2553_BUD
100401_1.0001.1433/4.4_BUD	100401_1.0001.2554_BUD
100401_1.0001.1433/4.5_BUD	100401_1.0001.2555_BUD
100401_1.0001.1433/7.3_BUD	100401_1.0001.2556_BUD
100401_1.0001.1433/7.4_BUD	100401_1.0001.2557_BUD
100401_1.0001.1434.1_BUD	100401_1.0001.2558_BUD
100401_1.0001.1500/1.1_BUD	100401_1.0001.2559_BUD
100401_1.0001.1500/1.2_BUD	100401_1.0001.2560_BUD
100401_1.0001.1501.1_BUD	100401_1.0001.2561_BUD
100401_1.0001.1501.2_BUD	100401_1.0001.2562_BUD
100401_1.0001.1501.3_BUD	100401_1.0001.2563_BUD
100401_1.0001.1502.1_BUD	100401_1.0001.2564_BUD
100401_1.0001.1502.2_BUD	100401_1.0001.2565_BUD
100401_1.0001.1502.3_BUD	100401_1.0001.2566_BUD
100401_1.0001.1503.1_BUD	100401_1.0001.2567_BUD
100401_1.0001.1503.2_BUD	100401_1.0001.2568_BUD
100401_1.0001.1504.1_BUD	100401_1.0001.2569_BUD
100401_1.0001.1504.2_BUD	100401_1.0001.2570_BUD
100401_1.0001.1504.3_BUD	100401_1.0001.2571_BUD
100401_1.0001.1505.1_BUD	100401_1.0001.2572_BUD
100401_1.0001.1507.1_BUD	100401_1.0001.2573_BUD
100401_1.0001.1508.1_BUD	100401_1.0001.2574_BUD
100401_1.0001.1508.2_BUD	100401_1.0001.2575_BUD
100401_1.0001.1509.1_BUD	100401_1.0001.2576_BUD
100401_1.0001.1509.2_BUD	100401_1.0001.2577_BUD
100401_1.0001.1510.1_BUD	100401_1.0001.2578_BUD
100401_1.0001.1510.2_BUD	100401_1.0001.2579_BUD
100401_1.0001.1511.1_BUD	100401_1.0001.2580_BUD
100401_1.0001.1511.2_BUD	100401_1.0001.2581_BUD
100401_1.0001.1512.1_BUD	100401_1.0001.2582_BUD
100401_1.0001.1512.2_BUD	100401_1.0001.2583_BUD
100401_1.0001.1513.1_BUD	100401_1.0001.2584_BUD
100401_1.0001.1513.2_BUD	100401_1.0001.2585_BUD
100401_1.0001.1513.3_BUD	100401_1.0001.2586_BUD
100401_1.0001.1514.1_BUD	100401_1.0001.2587_BUD
100401_1.0001.1514.2_BUD	100401_1.0001.2588_BUD
100401_1.0001.1514.3_BUD	100401_1.0001.2589_BUD
100401_1.0001.1517.1_BUD	100401_1.0001.2590_BUD
100401_1.0001.1517.2_BUD	100401_1.0001.2591_BUD

100401_1.0001.1518/1.1_BUD	100401_1.0001.2592_BUD
100401_1.0001.1518/2.1_BUD	100401_1.0001.2593_BUD
100401_1.0001.1518/2.2_BUD	100401_1.0001.2594_BUD
100401_1.0001.1519.1_BUD	100401_1.0001.2595_BUD
100401_1.0001.1519.2_BUD	100401_1.0001.2596_BUD
100401_1.0001.1520.1_BUD	100401_1.0001.2597_BUD
100401_1.0001.1520.2_BUD	100401_1.0001.2598_BUD
100401_1.0001.1521.1_BUD	100401_1.0001.2599_BUD
100401_1.0001.1521.2_BUD	100401_1.0001.2600_BUD
100401_1.0001.1521.3_BUD	100401_1.0001.2601_BUD
100401_1.0001.1522.1_BUD	100401_1.0001.2602_BUD
100401_1.0001.1522.2_BUD	100401_1.0001.2603_BUD
100401_1.0001.1523.1_BUD	100401_1.0001.2604_BUD
100401_1.0001.1523.2_BUD	100401_1.0001.2605_BUD
100401_1.0001.1524.1_BUD	100401_1.0001.2606_BUD
100401_1.0001.1524.2_BUD	100401_1.0001.2607_BUD
100401_1.0001.1525.1_BUD	100401_1.0001.2608_BUD
100401_1.0001.1525.2_BUD	100401_1.0001.2609_BUD
100401_1.0001.1526.1_BUD	100401_1.0001.2610_BUD
100401_1.0001.1526.2_BUD	100401_1.0001.2611_BUD
100401_1.0001.1527.1_BUD	100401_1.0001.2612_BUD
100401_1.0001.1527.2_BUD	100401_1.0001.2613_BUD
100401_1.0001.1528.1_BUD	100401_1.0001.2614_BUD
100401_1.0001.1528.3_BUD	100401_1.0001.2615_BUD
100401_1.0001.1528.4_BUD	100401_1.0001.2616_BUD
100401_1.0001.1530.1_BUD	100401_1.0001.2617_BUD
100401_1.0001.1531.1_BUD	100401_1.0001.2618_BUD
100401_1.0001.1531.2_BUD	100401_1.0001.2619_BUD
100401_1.0001.1532.1_BUD	100401_1.0001.2620_BUD
100401_1.0001.1533.1_BUD	100401_1.0001.2621_BUD
100401_1.0001.1534.1_BUD	100401_1.0001.2622_BUD
100401_1.0001.1534.2_BUD	100401_1.0001.2623_BUD
100401_1.0001.1535.1_BUD	100401_1.0001.2624_BUD
100401_1.0001.1535.2_BUD	100401_1.0001.2625_BUD
100401_1.0001.1536.1_BUD	100401_1.0001.2626_BUD
100401_1.0001.1537.1_BUD	100401_1.0001.2627_BUD
100401_1.0001.1538.1_BUD	100401_1.0001.2628_BUD
100401_1.0001.1539.1_BUD	100401_1.0001.2629_BUD
100401_1.0001.1540.1_BUD	100401_1.0001.2630_BUD
100401_1.0001.1540.2_BUD	100401_1.0001.2631_BUD
100401_1.0001.1541.1_BUD	100401_1.0001.2632_BUD
100401_1.0001.1542.1_BUD	100401_1.0001.2633_BUD
100401_1.0001.1543.1_BUD	100401_1.0001.2634_BUD
100401_1.0001.1544.1_BUD	100401_1.0001.2635_BUD
100401_1.0001.1545.1_BUD	100401_1.0001.2636_BUD
100401_1.0001.1545.2_BUD	100401_1.0001.2637_BUD
100401_1.0001.1546.1_BUD	100401_1.0001.2638_BUD
100401_1.0001.1546.2_BUD	100401_1.0001.2639_BUD
100401_1.0001.1549.1_BUD	100401_1.0001.2640_BUD
100401_1.0001.1550.1_BUD	100401_1.0001.2641_BUD
100401_1.0001.1551.1_BUD	100401_1.0001.2642_BUD
100401_1.0001.1552.1_BUD	100401_1.0001.2643_BUD
100401_1.0001.1553.1_BUD	100401_1.0001.2644_BUD
100401_1.0001.1554.1_BUD	100401_1.0001.2645_BUD

100401_1.0001.1554.2_BUD	100401_1.0001.2646_BUD
100401_1.0001.1555.1_BUD	100401_1.0001.2647_BUD
100401_1.0001.1556.1_BUD	100401_1.0001.2648_BUD
100401_1.0001.1558.1_BUD	100401_1.0001.2649_BUD
100401_1.0001.1558.2_BUD	100401_1.0001.2650_BUD
100401_1.0001.1559.1_BUD	100401_1.0001.2651_BUD
100401_1.0001.1560.1_BUD	100401_1.0001.2652_BUD
100401_1.0001.1561.1_BUD	100401_1.0001.2653_BUD
100401_1.0001.1562.1_BUD	100401_1.0001.2654_BUD
100401_1.0001.1563.1_BUD	100401_1.0001.2655_BUD
100401_1.0001.1564.1_BUD	100401_1.0001.2656_BUD
100401_1.0001.1565.1_BUD	100401_1.0001.2657_BUD
100401_1.0001.1565.2_BUD	100401_1.0001.2658_BUD
100401_1.0001.1566.1_BUD	100401_1.0001.2659_BUD
100401_1.0001.1567.1_BUD	100401_1.0001.2660_BUD
100401_1.0001.1568.1_BUD	100401_1.0001.2661_BUD
100401_1.0001.1569.1_BUD	100401_1.0001.2662_BUD
100401_1.0001.1570.1_BUD	100401_1.0001.2663_BUD
100401_1.0001.1571.1_BUD	100401_1.0001.2664_BUD
100401_1.0001.1572.1_BUD	100401_1.0001.2665_BUD
100401_1.0001.1573.1_BUD	100401_1.0001.2666_BUD
100401_1.0001.1574.1_BUD	100401_1.0001.2667_BUD
100401_1.0001.1575.1_BUD	100401_1.0001.2668_BUD
100401_1.0001.1576.1_BUD	100401_1.0001.2669_BUD
100401_1.0001.1577.1_BUD	100401_1.0001.2670_BUD
100401_1.0001.1578.1_BUD	100401_1.0001.2671_BUD
100401_1.0001.1579.1_BUD	100401_1.0001.2672_BUD
100401_1.0001.1580.1_BUD	100401_1.0001.2673_BUD
100401_1.0001.1581.1_BUD	100401_1.0001.2674_BUD
100401_1.0001.1582.1_BUD	100401_1.0001.2675_BUD
100401_1.0001.1583.1_BUD	100401_1.0001.2676_BUD
100401_1.0001.1584.1_BUD	100401_1.0001.2677_BUD
100401_1.0001.1585.1_BUD	100401_1.0001.2678_BUD
100401_1.0001.1586.1_BUD	100401_1.0001.2679_BUD
100401_1.0001.1587.1_BUD	100401_1.0001.2680_BUD
100401_1.0001.1588.1_BUD	100401_1.0001.2681_BUD
100401_1.0001.1588.2_BUD	100401_1.0001.2682_BUD
100401_1.0001.1589.1_BUD	100401_1.0001.2683_BUD
100401_1.0001.1590.1_BUD	100401_1.0001.2684_BUD
100401_1.0001.1591.1_BUD	100401_1.0001.2685_BUD
100401_1.0001.1592.1_BUD	100401_1.0001.2686_BUD
100401_1.0001.1593.1_BUD	100401_1.0001.2687_BUD
100401_1.0001.1594.1_BUD	100401_1.0001.2688_BUD
100401_1.0001.1595.1_BUD	100401_1.0001.2689_BUD
100401_1.0001.1596.1_BUD	100401_1.0001.2690_BUD
100401_1.0001.1597.1_BUD	100401_1.0001.2691_BUD
100401_1.0001.1598.1_BUD	100401_1.0001.2692_BUD
100401_1.0001.1598.2_BUD	100401_1.0001.2693_BUD
100401_1.0001.1598.3_BUD	100401_1.0001.2694_BUD
100401_1.0001.1599.1_BUD	100401_1.0001.2695_BUD
100401_1.0001.1600.1_BUD	100401_1.0001.2696_BUD
100401_1.0001.1600.2_BUD	100401_1.0001.2697_BUD
100401_1.0001.1601.1_BUD	100401_1.0001.2698_BUD
100401_1.0001.1602.1_BUD	100401_1.0001.2699_BUD

100401_1.0001.1603.1_BUD	100401_1.0001.2700_BUD
100401_1.0001.1604.1_BUD	100401_1.0001.2701_BUD
100401_1.0001.1606.1_BUD	100401_1.0001.2702_BUD
100401_1.0001.1607.1_BUD	100401_1.0001.2703_BUD
100401_1.0001.1608.1_BUD	100401_1.0001.2704_BUD
100401_1.0001.1609.1_BUD	100401_1.0001.2705_BUD
100401_1.0001.1610.1_BUD	100401_1.0001.2706_BUD
100401_1.0001.1611.1_BUD	100401_1.0001.2707_BUD
100401_1.0001.1612.1_BUD	100401_1.0001.2708_BUD
100401_1.0001.1613.1_BUD	100401_1.0001.2709_BUD
100401_1.0001.1614.1_BUD	100401_1.0001.2710_BUD
100401_1.0001.1615.1_BUD	100401_1.0001.2711_BUD
100401_1.0001.1616.1_BUD	100401_1.0001.2712_BUD
100401_1.0001.1617.1_BUD	100401_1.0001.2713_BUD
100401_1.0001.1618.1_BUD	100401_1.0001.2714_BUD
100401_1.0001.1619.1_BUD	100401_1.0001.2715_BUD
100401_1.0001.1620.1_BUD	100401_1.0001.2716_BUD
100401_1.0001.1621.1_BUD	100401_1.0001.2717_BUD
100401_1.0001.1622.1_BUD	100401_1.0001.2718_BUD
100401_1.0001.1623.1_BUD	100401_1.0001.2719_BUD
100401_1.0001.1624.1_BUD	100401_1.0001.2720_BUD
100401_1.0001.1624.2_BUD	100401_1.0001.2721_BUD
100401_1.0001.1625.1_BUD	100401_1.0001.2722_BUD
100401_1.0001.1625.2_BUD	100401_1.0001.2723_BUD
100401_1.0001.1626.1_BUD	100401_1.0001.2724_BUD
100401_1.0001.1627.1_BUD	100401_1.0001.2725_BUD
100401_1.0001.1627.2_BUD	100401_1.0001.2726_BUD
100401_1.0001.1628.1_BUD	100401_1.0001.2727_BUD
100401_1.0001.1628.2_BUD	100401_1.0001.2728_BUD
100401_1.0001.1629.1_BUD	100401_1.0001.2729_BUD
100401_1.0001.1630.1_BUD	100401_1.0001.2730_BUD
100401_1.0001.1631.1_BUD	100401_1.0001.2731_BUD
100401_1.0001.1632.1_BUD	100401_1.0001.2732_BUD
100401_1.0001.1633.1_BUD	100401_1.0001.2733_BUD
100401_1.0001.1633.2_BUD	100401_1.0001.2734_BUD
100401_1.0001.1634.1_BUD	100401_1.0001.2735_BUD
100401_1.0001.1635.1_BUD	100401_1.0001.2736_BUD
100401_1.0001.1636.1_BUD	100401_1.0001.2737_BUD
100401_1.0001.1638.1_BUD	100401_1.0001.2738_BUD
100401_1.0001.1639.1_BUD	100401_1.0001.2739_BUD
100401_1.0001.1640.1_BUD	100401_1.0001.2740_BUD
100401_1.0001.1641.1_BUD	100401_1.0001.2741_BUD
100401_1.0001.1642.1_BUD	100401_1.0001.2742_BUD
100401_1.0001.1643.1_BUD	100401_1.0001.2743_BUD
100401_1.0001.1643.2_BUD	100401_1.0001.2744_BUD
100401_1.0001.1644.1_BUD	100401_1.0001.2745_BUD
100401_1.0001.1645.1_BUD	100401_1.0001.2746_BUD
100401_1.0001.1646.1_BUD	100401_1.0001.2747_BUD
100401_1.0001.1647.1_BUD	100401_1.0001.2748_BUD
100401_1.0001.1648.1_BUD	100401_1.0001.2749_BUD
100401_1.0001.1648.2_BUD	100401_1.0001.2750_BUD
100401_1.0001.1649.1_BUD	100401_1.0001.2751_BUD
100401_1.0001.1649.2_BUD	100401_1.0001.2752_BUD
100401_1.0001.1650.1_BUD	100401_1.0001.2753_BUD

100401_1.0001.1651.1_BUD	100401_1.0001.2754_BUD
100401_1.0001.1652.2_BUD	100401_1.0001.2755_BUD
100401_1.0001.1652.3_BUD	100401_1.0001.2756_BUD
100401_1.0001.1652.4_BUD	100401_1.0001.2757_BUD
100401_1.0001.1654.1_BUD	100401_1.0001.2758_BUD
100401_1.0001.1655.1_BUD	100401_1.0001.2759_BUD
100401_1.0001.1656.1_BUD	100401_1.0001.2760_BUD
100401_1.0001.1657.1_BUD	100401_1.0001.2761_BUD
100401_1.0001.1658.1_BUD	100401_1.0001.2762_BUD
100401_1.0001.1659.1_BUD	100401_1.0001.2763_BUD
100401_1.0001.1660.1_BUD	100401_1.0001.2764_BUD
100401_1.0001.1661.1_BUD	100401_1.0001.2765_BUD
100401_1.0001.1662.1_BUD	100401_1.0001.2766_BUD
100401_1.0001.1662.2_BUD	100401_1.0001.2767_BUD
100401_1.0001.1663.1_BUD	100401_1.0001.2768_BUD
100401_1.0001.1664.1_BUD	100401_1.0001.2769_BUD
100401_1.0001.1665.1_BUD	100401_1.0001.2770_BUD
100401_1.0001.1666.1_BUD	100401_1.0001.2771_BUD
100401_1.0001.1666.3_BUD	100401_1.0001.2772_BUD
100401_1.0001.1666.4_BUD	100401_1.0001.2773_BUD
100401_1.0001.1669.1_BUD	100401_1.0001.2774_BUD
100401_1.0001.1670.1_BUD	100401_1.0001.2775_BUD
100401_1.0001.1671.1_BUD	100401_1.0001.2776_BUD
100401_1.0001.1672.1_BUD	100401_1.0001.2777_BUD
100401_1.0001.1673.1_BUD	100401_1.0001.2778_BUD
100401_1.0001.1674.1_BUD	100401_1.0001.2779_BUD
100401_1.0001.1675/1.1_BUD	100401_1.0001.2780_BUD
100401_1.0001.1675/1.2_BUD	100401_1.0001.2781_BUD
100401_1.0001.1675/3.1_BUD	100401_1.0001.2782_BUD
100401_1.0001.1675/5.1_BUD	100401_1.0001.2783_BUD
100401_1.0001.1683/2.1_BUD	100401_1.0001.2784_BUD
100401_1.0001.1683/2.2_BUD	100401_1.0001.2785_BUD
100401_1.0001.1683/3.1_BUD	100401_1.0001.2786_BUD
100401_1.0001.1683/3.2_BUD	100401_1.0001.2787_BUD
100401_1.0001.1684/1.1_BUD	100401_1.0001.2788_BUD
100401_1.0001.1684/2.1_BUD	100401_1.0001.2789_BUD
100401_1.0001.1684/2.2_BUD	100401_1.0001.2790_BUD
100401_1.0001.1684/3.1_BUD	100401_1.0001.2791_BUD
100401_1.0001.1687/2.1_BUD	100401_1.0001.2792_BUD
100401_1.0001.1687/3.1_BUD	100401_1.0001.2793_BUD
100401_1.0001.1687/4.1_BUD	100401_1.0001.2794_BUD
100401_1.0001.1687/7.1_BUD	100401_1.0001.2795_BUD
100401_1.0001.1687/8.1_BUD	100401_1.0001.2796_BUD
100401_1.0001.1687/8.2_BUD	100401_1.0001.2797_BUD
100401_1.0001.1689/3.1_BUD	100401_1.0001.2798_BUD
100401_1.0001.1689/4.1_BUD	100401_1.0001.2799_BUD
100401_1.0001.1689/5.1_BUD	100401_1.0001.2800_BUD
100401_1.0001.1689/8.1_BUD	100401_1.0001.2801_BUD
100401_1.0001.1689/10.1_BUD	100401_1.0001.2802_BUD
100401_1.0001.1689/11.1_BUD	100401_1.0001.2803_BUD
100401_1.0001.1699.1_BUD	100401_1.0001.2804_BUD
100401_1.0001.1699.2_BUD	100401_1.0001.2805_BUD
100401_1.0001.1699.3_BUD	100401_1.0001.2806_BUD
100401_1.0001.1701.1_BUD	100401_1.0001.2807_BUD

100401_1.0001.1702.1_BUD	100401_1.0001.2808_BUD
100401_1.0001.1703.1_BUD	100401_1.0001.2809_BUD
100401_1.0001.1704.1_BUD	100401_1.0001.2810_BUD
100401_1.0001.1705.1_BUD	100401_1.0001.2811_BUD
100401_1.0001.1710/8.1_BUD	100401_1.0001.2812_BUD
100401_1.0001.1710/13.1_BUD	100401_1.0001.2813_BUD
100401_1.0001.1710/13.2_BUD	100401_1.0001.2814_BUD
100401_1.0001.1710/13.3_BUD	100401_1.0001.2815_BUD
100401_1.0001.1710/14.1_BUD	100401_1.0001.2816_BUD
100401_1.0001.1710/15.1_BUD	100401_1.0001.2817_BUD
100401_1.0001.1710/26.1_BUD	100401_1.0001.2818_BUD
100401_1.0001.1710/28.2_BUD	100401_1.0001.2819_BUD
100401_1.0001.1710/29.1_BUD	100401_1.0001.2820_BUD
100401_1.0001.1710/30.1_BUD	100401_1.0001.2821_BUD
100401_1.0001.1710/31.1_BUD	100401_1.0001.2822_BUD
100401_1.0001.1710/32.1_BUD	100401_1.0001.2823_BUD
100401_1.0001.1710/33.1_BUD	100401_1.0001.2824_BUD
100401_1.0001.1710/34.1_BUD	100401_1.0001.2825_BUD
100401_1.0001.1710/35.1_BUD	100401_1.0001.2826_BUD
100401_1.0001.1710/36.1_BUD	100401_1.0001.2827_BUD
100401_1.0001.1710/38.1_BUD	100401_1.0001.2828_BUD
100401_1.0001.1710/41.1_BUD	100401_1.0001.2829_BUD
100401_1.0001.1710/43.1_BUD	100401_1.0001.2830_BUD
100401_1.0001.1711.1_BUD	100401_1.0001.2831_BUD
100401_1.0001.1838.1_BUD	100401_1.0001.2832_BUD
100401_1.0001.1840.1_BUD	100401_1.0001.2833_BUD
100401_1.0001.1844/1.1_BUD	100401_1.0001.2834_BUD
100401_1.0001.1844/3.2_BUD	100401_1.0001.2835_BUD
100401_1.0001.1844/4.1_BUD	100401_1.0001.2836_BUD
100401_1.0001.1844/5.1_BUD	100401_1.0001.2837_BUD
100401_1.0001.1844/8.1_BUD	100401_1.0001.2838_BUD
100401_1.0001.1845/4.1_BUD	100401_1.0001.2839_BUD
100401_1.0001.1845/5.1_BUD	100401_1.0001.2840_BUD
100401_1.0001.1846/1.1_BUD	100401_1.0001.2841_BUD
100401_1.0001.1846/1.2_BUD	100401_1.0001.2842_BUD
100401_1.0001.1846/2.1_BUD	100401_1.0001.2843_BUD
100401_1.0001.1846/5.1_BUD	100401_1.0001.2844_BUD
100401_1.0001.1846/7.1_BUD	100401_1.0001.2845_BUD
100401_1.0001.1846/8.1_BUD	100401_1.0001.2846_BUD
100401_1.0001.1846/8.2_BUD	100401_1.0001.2847_BUD
100401_1.0001.1846/10.1_BUD	100401_1.0001.2848_BUD
100401_1.0001.1846/12.1_BUD	100401_1.0001.2849_BUD
100401_1.0001.1846/12.2_BUD	100401_1.0001.2850_BUD
100401_1.0001.1846/14.1_BUD	100401_1.0001.2851_BUD
100401_1.0001.1846/16.1_BUD	100401_1.0001.2852_BUD
100401_1.0001.1846/17.1_BUD	100401_1.0001.2853_BUD
100401_1.0001.1846/19.1_BUD	100401_1.0001.2854_BUD
100401_1.0001.1846/20.1_BUD	100401_1.0001.2855_BUD
100401_1.0001.1846/20.2_BUD	100401_1.0001.2856_BUD
100401_1.0001.1846/22.1_BUD	100401_1.0001.2857_BUD
100401_1.0001.1846/23.1_BUD	100401_1.0001.2858_BUD
100401_1.0001.1846/25.1_BUD	100401_1.0001.2859_BUD
100401_1.0001.1846/26.1_BUD	100401_1.0001.2860_BUD
100401_1.0001.1846/26.2_BUD	100401_1.0001.2861_BUD

100401_1.0001.1846/29.1_BUD	100401_1.0001.2862_BUD
100401_1.0001.1847/3.1_BUD	100401_1.0001.2863_BUD
100401_1.0001.1847/3.2_BUD	100401_1.0001.2864_BUD
100401_1.0001.1847/3.3_BUD	100401_1.0001.2865_BUD
100401_1.0001.1847/4.1_BUD	100401_1.0001.2866_BUD
100401_1.0001.1847/4.2_BUD	100401_1.0001.2867_BUD
100401_1.0001.1847/4.3_BUD	100401_1.0001.2868_BUD
100401_1.0001.1847/4.4_BUD	100401_1.0001.2869_BUD
100401_1.0001.1847/6.1_BUD	100401_1.0001.2870_BUD
100401_1.0001.1847/7.1_BUD	100401_1.0001.2871_BUD
100401_1.0001.1847/7.2_BUD	100401_1.0001.2872_BUD
100401_1.0001.1847/7.3_BUD	100401_1.0001.2873_BUD
100401_1.0001.1847/7.4_BUD	100401_1.0001.2874_BUD
100401_1.0001.1847/9.1_BUD	100401_1.0001.2875_BUD
100401_1.0001.1847/10.1_BUD	100401_1.0001.2876_BUD
100401_1.0001.1847/11.1_BUD	100401_1.0001.2877_BUD
100401_1.0001.1847/11.2_BUD	100401_1.0001.2878_BUD
100401_1.0001.1847/12.1_BUD	100401_1.0001.2879_BUD
100401_1.0001.1848.1_BUD	100401_1.0001.2880_BUD
100401_1.0001.1849/2.1_BUD	100401_1.0001.2881_BUD
100401_1.0001.1849/5.1_BUD	100401_1.0001.2882_BUD
100401_1.0001.1849/6.1_BUD	100401_1.0001.2883_BUD
100401_1.0001.1849/6.2_BUD	100401_1.0001.2884_BUD
100401_1.0001.1850/1.1_BUD	100401_1.0001.2885_BUD
100401_1.0001.1850/4.1_BUD	100401_1.0001.2886_BUD
100401_1.0001.1850/6.1_BUD	100401_1.0001.2887_BUD
100401_1.0001.1850/9.1_BUD	100401_1.0001.2888_BUD
100401_1.0001.1850/11.1_BUD	100401_1.0001.2889_BUD
100401_1.0001.1850/13.1_BUD	100401_1.0001.2890_BUD
100401_1.0001.1850/15.1_BUD	100401_1.0001.2891_BUD
100401_1.0001.1850/16.1_BUD	100401_1.0001.2892_BUD
100401_1.0001.1850/20.1_BUD	100401_1.0001.2893_BUD
100401_1.0001.1850/22.1_BUD	100401_1.0001.2894_BUD
100401_1.0001.1850/23.1_BUD	100401_1.0001.2895_BUD
100401_1.0001.1851/4.1_BUD	100401_1.0001.2896_BUD
100401_1.0001.1851/5.1_BUD	100401_1.0001.2897_BUD
100401_1.0001.1851/6.1_BUD	100401_1.0001.2898_BUD
100401_1.0001.1851/7.1_BUD	100401_1.0001.2899_BUD
100401_1.0001.1851/9.1_BUD	100401_1.0001.2900_BUD
100401_1.0001.1855.1_BUD	100401_1.0001.2901_BUD
100401_1.0001.1859/4.1_BUD	100401_1.0001.2902_BUD